Project: FOUNTAIN HILL ASSISTED LIVING

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
1	FIXED TEH BMP AT SE CORNER AND ALONG SOUTH SIDE	4-28-20	4-28-20	5-1-20
2	REMOVE EXTRA DIRT ALONG THE SOUTH BMP AND CURE	4-28-20	4-28-20	5-1-20

SWPPP Management Signature: Shawn Biazar Date: 5-1-20

Ver. 070813