

			General Info	rmation			
Project Name and Location		Legacy	NAA	Apts	A		
		Jan F	47 40	me Ali	anela	<u> </u>	
Site Contact Name & Agency		San F matt F legacy H	erreira Ispidalit	1	NPDES ID	No.	F18 E064B
Date of Inspection		16-9-18	S		Start/End Time	Start/End 70:55	
COA I	nspector Name		Cur	tis Cherne, Sto			
	be Present ase of Construction	Stab	ilizil				
Type o	f Inspection:						
· R	gular • During storm	event • Post-	storm event (>	0.25 inch) • 3	311 / Compla	int Re	sponse • Follow-Up
Tist			Weather Info	rmation			
	er at time of this inspection		Fog · Sno	owing • '	Windy	Ter	mperature: ~_50 F°
Has th	ere been a storm event sin nt: • < 1/4" • 1/4" to 3/4"	ce the site was Po	ermitted?	Yes · No Snow"			
			Inspect				
			~				
	BMP / Activity	Maintenance Required? (1)	Corrective Action Required? (2)	Location and	d Notes		
1.5	Post a Notice	· Yes · No	· Yes · No	NLA	1		
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft	· Yes · No	· Yes · No				
2.2.3	Sediment control along any perimeter	· Yes · No	· Yes · No				
2.2.3	Sediment control along any perimeter	· Yes · No	· Yes · No				
2.2.3	Sediment control along any perimeter	· Yes · No	· Yes · No				
2.2.3	Sediment control along any perimeter	· Yes · No	· Yes · No				
2.2.3	Sediment control along any perimeter	· Yes · No	· Yes · No				
2.2.3	Sediment control along any perimeter	· Yes · No	· Yes · No				
2.2.3	Sediment control along any perimeter	· Yes · No	· Yes · No				
2.2.4	Minimize sediment track-out	· Yes · No	· Yes · No				
2.2.5	Manage stockpiles	· Yes · No	· Yes · No				

Minimize Dust	· Yes · No	· Yes · No	
Protect Storm Drain Inlets	· Yes · No	· Yes · No	
Protect Storm Drain Inlets	· Yes · No	· Yes · No	
Minimize erosion of conveyance channels	· Yes · No	· Yes · No	N/A
Sediment Basins	· Yes · No	· Yes · No	
Stabilize exposed portions of the site.	· Yes · No	· Yes · No	
the site.	· Yes · No	· Yes · No	
Stabilize exposed portions of the site.	· Yes · No	• Yes • No	
Stabilize exposed portions of the site.	· Yes · No	· Yes · No	
Equipment and Vehicle Fueling	· Yes · No	· Yes · No	
Equipment and Vehicle Washing	· Yes · No	· Yes · No	
Building Material Storage	· Yes · No	· Yes · No	
Fuel, oil, hydraulic fluid, petroleum products and chemical storage	· Yes · No	· Yes · No	Stabilized
Construction and Domestic Wastes	· Yes · No	· Yes · No	
Washing Applicators used for paint, stucco, concrete, etc.	· Yes · No	· Yes · No	
Washing Applicators used for paint, stucco, concrete, etc.	·.Yes · No	· Yes · No	
Washing Applicators used for paint, stucco, concrete, etc.	· Yes · No	· Yes · No	
Dewatering	· Yes · No	· Yes · No	
Discharge to MS4?		· Yes · No	
Self-Inspection Reports		· Yes · No	Latest Report Date:
	Protect Storm Drain Inlets Protect Storm Drain Inlets Minimize erosion of conveyance channels Sediment Basins Stabilize exposed portions of the site. Equipment and Vehicle Fueling Equipment and Vehicle Washing Building Material Storage Fuel, oil, hydraulic fluid, petroleum products and chemical storage Construction and Domestic Wastes Washing Applicators used for paint, stucco, concrete, etc. Washing Applicators used for paint, stucco, concrete, etc. Dewatering Discharge to MS4?	Protect Storm Drain Inlets Protect No Protect No Protect Storm Drain Inlets Protect No Protect No Protect Storm Drain Inlets Protect No Protect Storm Drain Inlets Protect No Protect No Protect Storm Drain Inlets Protect No Protect No Protect Storm Drain Inlets Protect No Pr	Protect Storm Drain Inlets Protect No Pres

Notes: (City Inspector Use) For inspection items with numerous rows, addit (1) Maintenance is to be complete by the end of the next business day.

(2) Corrective Actions are to be complete within 7
--

Notes:		
NOTES:		
Table 1		
		11-9-10
City of Albuquerque Stormwater Inspector Signature and Date:	Cuttin 6 chr	74-1-6
City of Albuquerque Stormwater Inspector Signature and Date:	00000 - ()	_

Signature

Date

From:

Cherne, Curtis

Sent:

Wednesday, June 06, 2018 12:31 PM

To:

'Matt Ferreira'

Subject:

FW: Inlets-Thx-forgot to mention much sock

If the straw wattle was replaced with mulch sock/filter sock, water would drain through and ponding would be reduced/eliminated.

2 cents.

Curtis

From: Cherne, Curtis

Sent: Wednesday, June 06, 2018 12:28 PM

To: 'Matt Ferreira' **Subject:** RE: Inlets-Thx

Matt,

Thanks for sending the pic.

Definitely provides protection.

Straw wattles don't let water through. The inlet may be located such that the water will go over the top then through the cocoa mat. IF you experience a localized ponding/flooding issue, scoot the wattle to the side or similar so the water can get to the cocoa mat.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

From: Matt Ferreira [mailto:mferreira@legacy-hospitality.com]

Sent: Wednesday, June 06, 2018 8:55 AM

To: Cherne, Curtis **Subject:** Inlets

Here is the first one.

Sent from my T-Mobile 4G LTE device

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Wednesday, June 06, 2018 12:34 PM

To:

Cherne, Curtis

Subject:

RE: Inlets-Thx-forgot to mention much sock

We will adjust wattles after event I just don't not want any debree with in the drain and don't want you on my ass anymore.

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Wednesday, June 6, 2018 12:31 PM

To: Matt Ferreira < <u>mferreira@legacy-hospitality.com</u> > **Subject:** FW: Inlets-Thx-forgot to mention much sock

If the straw wattle was replaced with mulch sock/filter sock, water would drain through and ponding would be reduced/eliminated.

2 cents.

Curtis

From: Cherne, Curtis

Sent: Wednesday, June 06, 2018 12:28 PM

To: 'Matt Ferreira' **Subject:** RE: Inlets-Thx

Matt,

Thanks for sending the pic.

Definitely provides protection.

Straw wattles don't let water through. The inlet may be located such that the water will go over the top then through the cocoa mat. IF you experience a localized ponding/flooding issue, scoot the wattle to the side or similar so the water can get to the cocoa mat.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

From: Matt Ferreira [mailto:mferreira@legacy-hospitality.com]

Sent: Wednesday, June 06, 2018 8:55 AM

To: Cherne, Curtis **Subject:** Inlets

Here is the first one.



General Information						
Project Name and Location						
Site Contact Name & Agency	Matt Ferreira ESC File No. CIOE064B					
Date of Inspection	f Inspection 6-4-18 Start/End 7:06/2:35					
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Describe Present Phase of Construction	Constructing units					
Type of Inspection:						
Regular	m event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up					
	Weather Information					
Weather at time of this inspecti	•					
Has there been a storm events	nce the site was Permitted? Ses · No					
Amount: • < 1/4" • 1/4" to 3/	4) · > 3/4" · Snow"					
	Erosion & Sediment Control Inspection					
Entrance / Track-Out	1 - no dreck - out					
Sediment Controls / Silt Fence, Nu Met - 511 fur under grote a/ Sadhags Inlet Protection, Wattles, etc. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						
Congrephe of Sud in any floor drawing for the left distribution Reports 5-22-10 105t - Storm on inspection report - next to child butte Erosion Controls PONDS Housekeeping/Pollutant Controls application on inspection left drawing to a in the Chemical for the side of the control of the control of the side of the control of the side of the control of the side of the control of						
Debris/Pollutants/Sediment in MS4 NO Notes Matt has order a cocoa mats, the full me he would call me today with a status - the sent email C-5-18						
Is site being maintained in compliance with the Drainage Ordinance?" Yes No Signature Date						

From: Matt Ferreira <mferreira@legacy-hospitality.com>

Sent: Tuesday, June 05, 2018 2:27 PM

To: Cherne, Curtis
Subject: RE: no phone call

Attachments: 20180605_142502_resized.jpg

They were unloaded about 2 minutes ago. I will have the guys install first thing in the morning, they also came with the install kit.

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Tuesday, June 5, 2018 2:22 PM

To: Matt Ferreira < mferreira@legacy-hospitality.com >

Subject: no phone call

Matt,

I thought you were going to call yesterday with status of cocoa mat?

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



Matt Ferreira

Project Manager/Superintendent Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000 mferreira@legacy-hospitality.com https://ddei3-0-

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=www.Legacy%2dHospitality.com&umid=7C040EE 6DEA-E105-851D-530A591B7096&auth=f0ebcd052f61e7a39dc93191e8a01d02608499af-4c43bafa99169b1c7e16fe21d7764c5faf67e903

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

This message has been analyzed by Deep Discovery Email Inspector.

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Thursday, May 24, 2018 10:31 AM

To:

Cherne, Curtis

Subject:

Re: Legacy NAA Apartments Construction Site Inspection

Were on it...I'll give you a call next week.

Sent from my T-Mobile 4G LTE device

----- Original message------ **From:** Cherne, Curtis

Date: Thu, May 24, 2018 10:09 AM

To: Matt Ferreira:

Cc:

Subject:Legacy NAA Apartments Construction Site Inspection

Matt,

Good morning.

I was out at your project on Tuesday.

The following issues were observed:

1. The inlet protection at three (all?) inlets isn't working. Seems when they receive flow they pull away from the grate and do not provide the required protection. As the inlets in the pavement see traffic, a flat-type inlet protection would work the best. The cocoa-mats work really well. See pic "cocoa_mat_grate_throat.jpg" for grate part They get zip-tied to the grate so they stay in place. Inspections Plus does a great job at installing these.

For the inlet in the NW corner off in the dirt a cocoa mat - mulch sock combo would work well. See inlet_protection.jpg. Inspections plus installed this one also.

- 2. The berm in the northwest corner blew-out. Unless berms are sixed appropriately and well-compacted they don't work and most likely add additional sediment into the system when they fail. They also work better in conjunction with a pond, which slows down the velocity. Due to the size of the area that drains to the NW corner, a pond would help extend the life of the inlet protection.
- 3. A sediment BMP should be installed at the toe of the stockpile. It used to have one, or still does, it's just not at the toe of the berm anymore.
- 4. The paved surfaces have a lot of dirt and some debris. This will cause your inlet protection to plug. Please remove the dirt from paved areas with lots of dirt.
- 5. I know you keep your self-inspection reports on-site. I can look for the post-storm report next week when I come out.

If you have any questions, please let me know.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



	General Information					
Designation of the second seco						
Project Name	Legacy NAA gras					
and Location	Sa petro me Marich Matt Reversa ESCEIONO CLOSENGER					
	matt Receive					
Site Contact Name & Agency	ESC File No. CIGE 06 4D					
	Coacy Hospitality Start/End Start/End					
Date of Inspection	5-22-18 Startend 10:05/10-25					
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Describe Present Phase of Construction	All unite untical					
Type of Inspection:	\sim					
Regular	m event Post-storm event (> 0.5 inch) · 311 / Complaint Response · Follow-Up					
	Weather Information					
Weather at time of this inspecti	on? Temperature: ~/_0F° Rain · Sleet · Fog · Snowing · Windy					
Has there been a storm event si	nce the site was Permitted? (Yes · No					
Amount: • < 1/4" • 1/4" to 3	4" · > 34" · Snow"					
	Erosion & Sediment Control Inspection					
Entrance / Track-Out	- AD track-out					
Sediment Controls / Silt Fence,	West who evener 1/2 had prefection					
Inlet Protection, Wattles, etc.	12 didnot					
Un Cumpacted	here blew out					
Carge stockers	velople as Bay at toe					
12 Let profession	Su corner - Inettoni - not cowing latest					
Same for inlet	NW CUMA					
Inspection Reports duty p-let worth drain to the calet						
Erosion Controls draws of Swinder and Celvis						
Housekeeping/Pollutant Controls						
mayor use cucaa mat						
Debris/Pollutants/Sediment in MS4 Yes - 12 by NW Comes						
Is site being maintained in compliance with the Drainage Ordinance? Yes (No) Luth a Chr 5.17-18 Signature Date						

From:

Cherne, Curtis

Sent:

Thursday, May 24, 2018 10:09 AM

To:

'Matt Ferreira'

Subject:

Legacy NAA Apartments Construction Site Inspection

Attachments:

inlet_protection.jpg; cocoa_mat_grate_throat_.jpg; NW_Corner.jpg; NW_corner_inlet.jpg;

ummmmm.jpg; stockpile_no_Bmp.jpg; drains_to_NW_Pavement_inlet.jpg;

drains_to_SE_inlet_pavement.jpg

Matt.

Good morning.

I was out at your project on Tuesday.

The following issues were observed:

1. The inlet protection at three (all?) inlets isn't working. Seems when they receive flow they pull away from the grate and do not provide the required protection. As the inlets in the pavement see traffic, a flat-type inlet protection would work the best. The cocoa-mats work really well. See pic "cocoa_mat_grate_throat.jpg" for grate part They get zip-tied to the grate so they stay in place. Inspections Plus does a great job at installing these.

For the inlet in the NW corner off in the dirt a cocoa mat - mulch sock combo would work well. See inlet protection.jpg. Inspections plus installed this one also.

- 2. The berm in the northwest corner blew-out. Unless berms are sixed appropriately and well-compacted they don't work and most likely add additional sediment into the system when they fail. They also work better in conjunction with a pond, which slows down the velocity. Due to the size of the area that drains to the NW corner, a pond would help extend the life of the inlet protection.
- 3. A sediment BMP should be installed at the toe of the stockpile. It used to have one, or still does, it's just not at the toe of the berm anymore.
- 4. The paved surfaces have a lot of dirt and some debris. This will cause your inlet protection to plug. Please remove the dirt from paved areas with lots of dirt.
- 5. I know you keep your self-inspection reports on-site. I can look for the post-storm report next week when I come out.

If you have any questions, please let me know.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



	General Information					
Project Name	Legacy NAA Apts					
and Location	San Pedro & Go As matt Ferreira	land				
Site Contact Name & Agency	matt Ferreira	ESC File No.	C18E0640			
Date of Inspection 3-26-18 Start/End Time 1:50/2:35						
Inspector Name, COA Dept.	Inspector Name, COA Dept. Curtis Cherne, Stormwater Quality					
Describe Present Phase of Construction	east 1/2 of project comp	2ete				
Type of Inspection:	,					
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 3	311 / Complaint Resp	oonse • Follow-Up			
	Weather Information					
Weather at time of this inspect Clear Cloudy		Tem	perature: ~_GSF°			
Has there been a storm event s						
Amount: • < 1/4" • 1/4" to 3	3/4" · > 3/4" · Snow"					
	Erosion & Sediment Control Inspec	ction				
Entrance / Track-Out	- no trade rout					
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	, Require sections Book Mun	fland	Sucher Su B14			
what properties	west he has a hole on	he butter - pr	place			
	But at east endance					
Inspection Reports Frask	neur edge area					
- W						
Housekeeping/Pollutant Controls touth New South A coan						
a Esh-out peur souther edge - no washout facility						
paint - wash-our						
dry wall these subsite fine						
Notes Sediment in MS4 Notes Notes						
005-101						
+ 41K	falke to haft - told him has known to					
Is site being maintained in compliance with the Drainage Ordinance? Yes No Little Charles 3-26-18 Signature Date						

From:

Cherne, Curtis

Sent:

Monday, March 26, 2018 3:39 PM

To:

'Matt Ferreira'

Subject:

Legacy NAA Apartments Construciton Site Inspection

Attachments:

west_inlet.jpg; NW_inlet.jpg; staging_area_inlet.jpg; sediment_BMP.jpg; sedimetn_BMP_trash.jpg; sedimetn_BMP_trash2.jpg; paint_trash.jpg

Matt.

As discussed I am sending a list of the issues observed at the site today:

- 1. Two catch basin in the west area of the site have a hole/tear in the inlet protection in the bottom. Please repair.
- 2. The inlet in the NW corner of the staging area has no inlet protection. Please provide.
- 3. Provide a sediment BMP along the southern edge of the site where the grade is higher than the grade south of the fence. If the grade at the fence-line will drain into the site a sediment BMP is not required. This seemed to be the case at the east end of the half under construction.
- 4. There was trash along the southern fence and on the north side near the drive entrance.
- 5. Provide a sediment BMP on the north side near the drive entrance in the ramp area.
- 6. Paint on ground in southern area of project. Please remove. Pic also shows more trash.
- 7. Prevent trash from being on ground where it could leave your site. This may require localized trash containers. The only trash container I saw was the roll-off in the middle of the site. Way too far for a sub to walk.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



	General Information					
Project Name and Location Cegacy NAA Apartments Oakland and Sun Pedro Site Contact Name & Agency Math Ferreura ESC File No. CIBEDAY						
	Oakland and Sun Redop					
Site Contact Name & Agency	Mart Ferreura ESC File No. C18F064B					
Date of Inspection	4-4-18 Start/End Time 10:40					
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Describe Present Phase of Construction	M units vetrida a/ phyword oheathing					
Type of Inspection:						
Regular	m event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up					
	Weather Information					
Weather at time of this inspecti	•					
Has there been a storm event si Amount: -1/4" 1/4" 10 3	nce the site was Permitted? • (es) • No 4" • > 34" • Snow"					
	Erosion & Sediment Control Inspection					
Entrance / Track-Out						
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.						
Inspection Reports 45+ 3-24-18						
Erosion Controls On S Housekeeping/Pollutant Controls O						
Debris/Pollutants/Sediment in MS4 Notes fixed overything - CXUAR NESSIG 15 of wath m 51 Wh wh						
700k for UEC						
Is site being maintained in compliance with the Drainage Ordinance? (Yes) No Signature Date						

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Monday, March 26, 2018 3:40 PM

To:

Cherne, Curtis

Subject:

Re: Legacy NAA Apartments Construciton Site Inspection

Thanks Curtis...we will be on it tomorrow...see you next week.

Sent from my T-Mobile 4G LTE device

----- Original message-----From: Cherne, Curtis

Date: Mon, Mar 26, 2018 3:38 PM

To: Matt Ferreira:

Subject:Legacy NAA Apartments Construction Site Inspection

Matt,

As discussed I am sending a list of the issues observed at the site today:

- 1. Two catch basin in the west area of the site have a hole/tear in the inlet protection in the bottom. Please repair.
- ✓2. The inlet in the NW corner of the staging area has no inlet protection. Please provide.
 - 3. Provide a sediment BMP along the southern edge of the site where the grade is higher than the grade south of the fence. If the grade at the fence-line will drain into the site a sediment BMP is not required. This seemed to be the case at the east end of the half under construction.
 - 4. There was trash along the southern fence and on the north side near the drive entrance.
 - 5. Provide a sediment BMP on the north side near the drive entrance in the ramp area.
 - 6. Paint on ground in southern area of project. Please remove. Pic also shows more trash.
 - 7. Prevent trash from being on ground where it could leave your site. This may require localized trash containers. The only trash container I saw was the roll-off in the middle of the site. Way too far for a sub to walk.

Thanks.

Curtis Cherne, PE, QCIS **Principal Engineer** Stormwater Quality COA 505-924-3420



Matt Ferreira

Project Manager/Superintendent

Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000

mferreira@legacy-hospitality.com

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=www.Legacy%2dHospitality.com&umid=8D659E 6857-9D05-AA01-0D6AB16C3CBE&auth=f0ebcd052f61e7a39dc93191e8a01d02608499af-276eeac4aab2462c7ad3f072250cb311b1510bed

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From:

Cherne, Curtis

Sent:

Wednesday, March 07, 2018 3:44 PM

To:

'Matt Ferreira'

Subject:

Legacy NAA Apartments Construction Site inpection follow-up

Matt,

Good afternoon.

I know that Totten went through all the issues with you today so I won't repeat them.

It may help to put wash-out facilities (e.g lined pit, Outpak) closer to the work areas so the workers will use them.

I somehow sent the previous e-mail before I was finished. Sorry about that.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



General Information					
Project Name and Location	LEGACY NAA APTS				
Site Contact Name & Agency	RASSAM ESC File No. C187064B				
Date of Inspection	3-6/8 Start/End 1.45 3:00				
Inspector Name, COA Dept.	Stanice "Totten" Elliott, Stormwater Quality				
Describe Present Phase of Construction	CONSTRUCTING MULTIPLE BLDGS				
Type of Inspection: (\(\superset{\text{P}}\) Regular \(\superset{\text{D}}\) During stor	m event Post-storm event (> 0.5 inch) 311 / Complaint Response Follow-Up				
Trogum a During Stor					
Weather at time of this inspecti	Weather Information				
lear Cloudy E					
Has there been a storm event si					
Amount: $\square < \frac{1}{4}$ " to $\frac{3}{4}$ "					
	Erosion & Sediment Control Inspection				
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc. SEDIMENT IN GUTTER ON OAKAND INLET PROTECTION COULD USE SEDIMENT REMOVAC					
Inspection Reports ATEST 3-1-18 Erosion Controls					
Housekeeping/Pollutant Controls MULTIPLE LOCATIONS OF INASHOUT TRASH THROUGHOUT BUILDINGS ON SOUTH END, TRASH GETTING UNDER FENCE AND CENTING SITE WASHOUT FACILITY AND TRASH DUMPSTER PRESERVIT Debris/Pollutants/Sediment in MS4 Notes					
Is site being maintained in compliance with the Drainage Ordinance? Yes No Signature 3-16-18 Date					

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Wednesday, March 07, 2018 3:45 PM

To:

Cherne, Curtis

Subject:

Re: Legacy NAA Apartments Construction Site inpection follow-up

I will follow up with a email once complete.

Sent from my T-Mobile 4G LTE device

----- Original message----- From: Cherne, Curtis

Date: Wed, Mar 7, 2018 3:43 PM

To: Matt Ferreira:

Cc:

Subject:Legacy NAA Apartments Construction Site inpection follow-up

Matt,

Good afternoon.

I know that Totten went through all the issues with you today so I won't repeat them.

It may help to put wash-out facilities (e.g lined pit, Outpak) closer to the work areas so the workers will use them.

I somehow sent the previous e-mail before I was finished. Sorry about that.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



Matt Ferreira

Project Manager/Superintendent

Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000

mferreira@legacy-hospitality.com

https://ddei3-0-

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=www.Legacy%2dHospitality.com&umid=C6FD71I 66DA-4F05-8A7A-46A13BC00425&auth=f0ebcd052f61e7a39dc93191e8a01d02608499af-33b195152aee816a5697a8673fff1862662dcc88

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

This message has been analyzed by Deep Discovery Email Inspector.



		Information				
Project Name	Legacy NAA Sportments					
Project Name and Location	Callland east at San Pedro Matt Ferreira 5005000 (1050/40)					
Site Contact Name & Agency	matt Ferr.	CIFL	ESC File No.	C18E0640		
Date of Inspection	11-29-7 Start/End 71:20 /1:20					
Inspector Name, COA Dept.						
Describe Present Phase of Construction						
Type of Inspection:						
• Regular • During stor	m event • Post-storm event	ent (> 0.5 inch) • 3	11 / Complaint Resp	onse Follow-Up		
	Weather	r Information		·		
Weather at time of this inspecti Clear · Cloudy · I	i on? Rain • Sleet • Fog	· Snowing ·	Windy	perature: ~SfF°		
Has there been a storm event si		Yes · No				
Amount: • < 1/4" • 1/4" to 3	4" > 3/4"	• Snow"				
Erosion & Sediment Control Inspection						
Entrance / Track-Out						
Erosion Controls Housekeeping/Pollutant Controls SL						
Debris/Pollutants/Sediment in Notes place was	MS4 NO Affle at bese a	f curt p	, C,			
Is site being maintained in compliance	ce with the Drainage Ordinance	. 110	int & chr	11-20-17 Date		

From:

Cherne, Curtis

Sent:

Tuesday, November 28, 2017 2:44 PM

To:

'Matt Ferreira'

Subject:

Legacy NAA Apartments Construction Site Inspection-PASS

Matt,

I went by the above referenced project this morning for a follow-up inspection. Looked good.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



	General Information				
Project Name and Location Cesacy NAA Apertmets Oakine east of San Pero					
nott Ferrura					
Site Contact Name & Agency	(escry blospublit	ESC File No.	C18E064/3		
Date of Inspection	of Inspection 10-21-77 Start/End Time 1/2/5/12:15				
Inspector Name, COA Dept.	Curtis Cherne, S	Stormwater Quality			
Describe Present Phase of Construction	most unite crupical				
Type of Inspection: Regular • During stor	rm event • Post-storm event (> 0.5 inch) •	311 / Complaint Resp	ponse • Follow-Up		
	Weather Information				
Weather at time of this inspection • Cloudy • I		Ten Windy	nperature: ~F°		
Has there been a storm event si					
Amount: • < 1/4" • 1/4" to 3	4'' · > 3/4'' · Snow	***			
	Erosion & Sediment Control Insp		minin drock a		
Entrance Track-Out Free	July I was standing of	ack-out jad			
Sediment Controls / Silt Fence,					
Inlet Protection, Wattles, etc.	Lowest Oxit into Holly-	no drack	up pare		
Si Cland 1~	they country on the	an both si			
Silt Ince Happe	is 17 the bruse new west	- 00,0			
east exit int	oaklas	- tack -n	& enty shut		
Remove adend in oakland both sile prijes frestry - in prosen					
Erosion Controls 1 Housekeeping/Pollutant Controls Lydralic fluit besk Carp					
Notes Notes					
Sucinet 13m/ on Staging Cat					
Is site being maintained in compliance with the Drainage Ordinance?* Yes • No					

October 20, 2017

Faizel Kassam, Vandy Investments, Inc.: fkassam@legacy-Hospitality.com

Copy: Matt Ferreira, Legacy Hospitality, Inc.: mferreira@legacy-hospitality.com

Site: Legacy NAA Apartments: Alameda and San Pedro

Re: Drainage Ordinance (14-5-2-1) Violations for Erosion and Sediment Control

Dear Mr. Kassam,

The following violations were observed at today's inspection.

- 1. Three exit locations from the site without stabilized construction entrances (track-out pads).
- 2. Sediment in San Pedro Blvd and Oakland Ave.
- 3. Silt fence not buried.

Photos are shown below:

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



No track-out pad onto San Pedro Blvd. Sediment in street.




No track-out pad onto Oakland Ave. Sediment in street.

PO Box 1293

Albuquerque

New Mexico 87103



Additional entrance onto Oakland Ave. without a track-out pad. Sediment in street.




Silt fence not buried.

PO Box 1293

Albuquerque

New Mexico 87103



Sediment in Oakland Ave.



Required Mitigation:

3/2 grand grand

1. Install stabilized construction entrances (track-out pads) at all locations where vehicles are leaving the site per the approved Erosion and Sediment Control plan details. Currently workers are exiting the site in three locations. The laydown yard/parking lot west of the buildings is part of the site.

2. Remove sediment from San Pedro Blvd and Oakland Ave. along the frontage

of the project.

3. Maintain or reinstall silt fence per the approved Erosion and Sediment Control plan details.

BMD for det piles

If violations are not mitigated within 30 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you would like to schedule a follow-up inspection at a day and time of your convenience, prior to 30 days from the date of this letter please let me know.

If you have any questions, you can contact me at 924-3420.

Albuquerque

PO Box 1293

New Mexico 87103

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

From:

Cherne, Curtis

Sent:

Monday, October 23, 2017 1:27 PM

То:

'Matt Ferreira'

Subject:

RE: Legacy NAA Apartments Violation Letter

Matt,

Thanks for getting back with me.

- 3. Sweep- glad to hear you are sweeping twice/day. I stopped using that term and changed it to "remove'. Too many people were sweeping sediment into the gutter and leaving it there.
- 4. As can be seen from the pic. Grade is above curb/sidewalk. So you can lower grade to a couple inches below adjoining grade or properly install silt fence.

You didn't mention the exit onto San Pedro.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

From: Matt Ferreira [mailto:mferreira@legacy-hospitality.com]

Sent: Friday, October 20, 2017 3:47 PM **To:** Cherne, Curtis; Faizel Kassam

Subject: Re: Legacy NAA Apartments Violation Letter

Curtis good afternoon...sorry didn't see you on site..

- 1. The East entry off Oakland will be paved Friday
- 2. The West Oakland entry will be installed Monday by inspections plus.
- 3.we sweep twice a day..i will have to look into the sediment on Oakland.
- 4. The silt fence ours more of dust control now as our curb, gutter, fence and grade work see on place to eliminate any water to leave the site...

Thanks Have a good weekend. Matt

Sent from my T-Mobile 4G LTE device

----- Original message------ From: Cherne, Curtis

Date: Fri, Oct 20, 2017 3:35 PM

To: Faizel Kassam; Cc: Matt Ferreira;

Subject:Legacy NAA Apartments Violation Letter

Faizel,

See letter.

Curtis Cherne, PE, QCIS

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Friday, May 19, 2017 6:45 PM

To:

Cherne, Curtis; Faizel Kassam

Subject:

Re: Legacy NAA Apartments Violation Letter

Shit forgot the wattles, will get them in tomorrow. Thanks

Sent from my T-Mobile 4G LTE device

----- Original message-----

From: Cherne, Curtis

Date: Fri, May 19, 2017 3:47 PM

To: Faizel Kassam; Cc: Matt Ferreira;

Subject:Legacy NAA Apartments Violation Letter

Faizel,

Please see letter.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



Matt Ferreira

Project Manager/Superintendent Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000 mferreira@legacy-hospitality.com www.Legacy-Hospitality.com

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Monday, May 22, 2017 11:13 AM Cherne, Curtis; Faizel Kassam

To: Subject:

RE: Legacy NAA Apartments Violation Letter

Curtis, I have the wattles installed by EOD. The other listed items are a daily/bi-daily upkeep.

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Friday, May 19, 2017 3:47 PM

To: Faizel Kassam < fkassam@legacy-hospitality.com Cc: Matt Ferreira mferreira@legacy-hospitality.com Subject: Legacy NAA Apartments Violation Letter

Faizel,

Please see letter.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



Matt Ferreira Project Manager/Superintendent Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000 mferreira@legacy-hospitality.com www.Legacy-Hospitality.com

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Monday, May 22, 2017 11:20 AM

To:

Cherne, Curtis

Subject:

RE: Legacy NAA Apartments Violation Letter

Will do

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Monday, May 22, 2017 11:16 AM

To: Matt Ferreira < mferreira@legacy-hospitality.com > Subject: RE: Legacy NAA Apartments Violation Letter

Matt, Got it.

Please don't forget the inlet protection on Oakland.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

From: Matt Ferreira [mailto:mferreira@legacy-hospitality.com]

Sent: Monday, May 22, 2017 11:13 AM **To:** Cherne, Curtis; Faizel Kassam

Subject: RE: Legacy NAA Apartments Violation Letter

Curtis, I have the wattles installed by EOD. The other listed items are a daily/bi-daily upkeep.

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Friday, May 19, 2017 3:47 PM

To: Faizel Kassam < fkassam@legacy-hospitality.com cc: Matt Ferreira < mferreira@legacy-hospitality.com Subject: Legacy NAA Apartments Violation Letter

Faizel,

Please see letter.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



A LANDON						
	General Information					
Project Name	Calched east of Son Police Matt Ferrance Contact Phone #/					
and Location	Oaklind east of Son Podru					
Site Contact Name & Agency Legacy Hospitolity Contact Phone #/ E-mail						
Date of Inspection 6-19-17 Start/End Time 10:50 //:15						
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Qualified Compliance Inspector of Stormwate	er- Stormwater Onc				
Describe Present Phase of Construction	10 units vertical hast	perbin of Oaklard Pore				
Type of Inspection:						
Regular	m event • Post-storm event (> 0.5 inch) • 3	11 / Complaint Response Follow-Up				
	Weather Information	0.0				
Weather at time of this inspecti	ion? Rain · Sleet · Fog · Snowing · V	Temperature: ~F° Windy				
Has there been a storm event si	ince the site was Permitted? · Yes · No					
Amount: • < 1/4" • 1/4" to 3/	4" · > 3/4" · Snow"					
Erosion & Sediment Control Inspection						
 Entrance / Track-Out _ 	Je- no truck out					
Sediment Controls / Silt Fence, Check Dams, Waddles, etc.						
Erosion Controls / Mulch, Seed,						
Housekeeping/Pollutant Controls Olc						
• Debris/Pollutants/Sediment in MS4						
· Notes_ 516 contrac	Notes 5,5 contract parker off-sik (form)					
p. b. formed	nuntuan a calet	, 4-19-12				
Is site being maintained in complian	nce with the Drainage Ordinance? "Yes" No Sig	Cut + chu 6-19-73 gnature Date				

ECS File: C/UE06413



	General Information			
			<i>A</i> 1	
Project Name and Location	Markane Sparing Lesacy Non Morting			
and Location	Oakland east at sur preds			
Site Contact Name & Agency	not Ferrario	Contact Phone #/ E-mail	Sep Lu	
Date of Inspection	5-19-17 Start/End 7:40 2:50			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	Installing Utilities on Dakland, Construction 18 cdg			
Type of Inspection:		,		
Regular	rm event • Post-storm event (> 0.5 inch) • 3	311 / Complaint Resp	onse Follow-Up	
	Weather Information			
Weather at time, of this inspection? Temperature: ~_65 F°				
·		Windy		
Has there been a storm event s				
Amount: $\cdot < \frac{1}{4}$ " ($\frac{1}{4}$ " to $\frac{3}{4}$	½" • > ¾" • Snow"			
	Erosion & Sediment Control Inspec	ction		
Entrance / Track-Out	DISA + Inspen	1		
• Entrance / Track-Out DISA + Inspen • Sediment Controls / Silt Fence, Check Dams, Waddles, etc.				
Erosion Controls / Mulch, Seed,				
 Housekeeping/Pollutant C 	Controls didn't cospil			
 Debris/Pollutants/Sedime 	nt in MS4			
• Notes				
Is site being maintained in complian	nce with the Drainage Ordinance?* Yes $\frac{1}{S}$	Cut C	5- A-17 Date	

May 19, 2017

Faizel Kassam, Vandy Investments, Inc.: fkassam@legacy-Hospitality.com

Legacy NAA Apartments: Alameda and San Pedro

Copy: Matt Ferreira, Legacy Hospitality, Inc.: mferreira@legacy-hospitality.com

Re: Drainage Ordinance (14-5-2-1) Violations for Erosion and Sediment Control

Dear Mr. Kassam,

On May 9th, you were informed of the following required mitigation:

- 1. A sediment BMP (e.g. filter sock or wattle) should be placed at the west end of Oakland/east edge of San Pedro. Please extend 50 feet south of Oakland on the east side of San Pedro.
- 2. The inlet protection on Oakland Ave. requires maintenance
- 3. The track-out pad requires maintenance. Please remove sediment from Oakland St. uphill from inlet mentioned in #2.

At today's inspection, the sediment BMP had not been installed at the west end of Oakland Ave.

PO Box 1293

Photos are shown below:

Albuquerque

New Mexico 87103

www.cabq.gov



Sediment BMP not installed.







PO Box 1293

Albuquerque

New Mexico 87103





Dirt drainage area uphill from San Pedro Ave.

Due to time constraints, issues #2 and #3 as stated above were not checken



PO Box 1293

Inlet protection on Oakland requires maintenance.

Albuquerque

New Mexico 87103



Track-out pad requires maintenance.



Sediment in Oakland Ave.

PO Box 1293

Albuquerque

Required mitigation:

1. A sediment BMP (e.g. filter sock or wattle) shall be placed at the west end of Oakland/east edge of San Pedro. Extend BMP 50 feet south of Oakland on the east side of San Pedro.

New Mexico 87103 2. Issues #2 and #3 (inlet protection, track-out pad, sediment in Oakland Ave.) were not checked during this inspection, but shall be mitigated.

www.cabq.gov

If violations are not mitigated within 30 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you would like to schedule a follow-up inspection at a day and time of your convenience, prior to 30 days from the date of this letter, please let me know.

If you have any questions, you can contact me at 924-3420.

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Tuesday, May 09, 2017 3:50 PM

To:

Cherne, Curtis

Subject:

RE: Markana Apts inspection

We are on top of it, thanks.. should be wrapped up by end of week...

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Tuesday, May 9, 2017 3:28 PM

To: Matt Ferreira < mferreira@legacy-hospitality.com >

Subject: Markana Apts inspection

Matt.

Good afternoon.

The following issues were observed at today's inspection.

- 1. A sediment BMP (e.g. filter sock or wattle) should be placed at the west end of Oakland/east edge of San Pedro. Please extend 50 feet south of Oakland on the east side of San Pedro.
- 2. A sediment BMP should be placed at the south edge of Oakland. Lay it between the construction fences.
- 3. The inlet protection on Oakland requires maintenance.
- 4. The track-out pad requires maintenance. Track-out was minor. Please remove sediment from Oakland St. uphill from inlet mentioned in #3.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



Matt Ferreira

Project Manager/Superintendent

Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000

mferreira@legacy-hospitality.com www.Legacy-Hospitality.com

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From:

Cherne, Curtis

Sent:

Friday, May 19, 2017 3:47 PM

To:

Faizel Kassam

Cc:

mferreira@legacy-hospitality.com

Subject: Attachments:

Legacy NAA Apartments Violation Letter Legacy_NAA_Apartments_Violation2.pdf

Faizel,

Please see letter.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: C19506413



N FI MARIE			
	General Information		
Project Name and Location	Ligary NAN A	almats	
Site Contact Name & Agency	Most Ferania Shan	Contact Phone #/ E-mail	
Date of Inspection	3-14-17	Start/End 7:45/0:01	
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One		
Describe Present Phase of Construction	I vot going ventral, ustalling Utilities		
Type of Inspection:	3		
Regular	rm event • Post-storm event (> 0.5 inch) • 3	11 / Complaint Response Follow-Up	
	Weather Information		
Weather at time of this inspect		Temperature: ~ 6 6 F° Windy	
Has there been a storm event s	\		
Amount: • < 1/4" • 1/4" to 3			
	Erosion & Sediment Control Inspec	ction	
■ Entrance / Track-Out	UK melone no de	rech-ut	
 Sediment Controls / Silt I Check Dams, Waddles 		Alarota	
Erosion Controls / Mulch	, Seed,		
 Housekeeping/Pollutant C 	Controls		
■ Debris/Pollutants/Sedime	nt in MS4		
· Notes Cleans	Suffer in ockland		
Is site being maintained in complian	nce with the Drainage Ordinance ? (Y) s • No S	Centra che 3-14-7 ignature Date	

ECS File: <u>C18/20648</u>



	General Informatio	n
Project Name and Location	(egacy NAA AD	commut
Site Contact Name & Agency	not Ferreira Lesacy Hospitally	Contact Phone #/ Fee E-mail
Date of Inspection	5-9-17	Start/End /0!05/11:00
Inspector Name, COA Dept.	Curtis Che	rne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov	
Inspector Qualifications	Qualified Compliance Inspector of Sto	rmwater- Stormwater One
Describe Present Phase of Construction	Installing Utilities on Oc	gelad, Constructing building,
Type of Inspection: Regular • During store	Post-storm event (> 0.5 inch) Weather Informatio	
	ion? Rain · Sleet · Fog · Snowing ince the site was Permitted? · Yes	-
	$\frac{1}{4}$ • Snow _	
	Erosion & Sediment Control	Inspection
 Entrance / Track-Out 	track-out pa & reluming	Daklas who dre
 Sediment Controls / Silt F Check Dams, Waddles 	etc.	South sil of other
• Erosion Controls / Mulch.	Seed, - no Sodiand Ball	t projection west end
 Housekeeping/Pollutant C 	Controls - Met prukeha	aud maintener on Oakler
- traduou	nt in MS4 - Stident In Sol	nut / guther worth side of Oaklash
* Notes	1 mass	
Is site being maintained in complian	nce with the Drainage Ordinance ? Yes N	Signature Ch 5-9-17 Date

From:

Cherne, Curtis

Sent: To: Tuesday, May 09, 2017 3:28 PM mferreira@legacy-hospitality.com

Subject:

Markana Apts inspection

Attachments:

Oakland_west_end.jpg; Oakland_west_end2.jpg; Oakland_south-side.jpg;

inlet_maintenance.jpg

Matt,

Good afternoon.

The following issues were observed at today's inspection.

- 1. A sediment BMP (e.g. filter sock or wattle) should be placed at the west end of Oakland/east edge of San Pedro. Please extend 50 feet south of Oakland on the east side of San Pedro.
- 2. A sediment BMP should be placed at the south edge of Oakland. Lay it between the construction fences.
- 3. The inlet protection on Oakland requires maintenance.
- 4. The track-out pad requires maintenance. Track-out was minor. Please remove sediment from Oakland St. uphill from inlet mentioned in #3.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

March 3, 2017

Faizel Kassam, Vandy Investments, Inc.: fkassam@legacy-Hospitality.com

Legacy NAA Apartments: Alameda and San Pedro

Copy: Matt Ferreira, Legacy Hospitality, Inc.: mferreira@legacy-hospitality.com

Re: Drainage Ordinance (14-5-2-1) Violations for Erosion and Sediment Control

Dear Mr. Kassam,

On February 23rd, you were informed of the following required mitigation:

- 1. The Track-out pad/stabilized construction entrance was in poor condition and was required to be replaced.
- 2. Remove sediment from the gutter along the north side of Oakland Ave.

At today's inspection, the track-out pad/stabilized construction entrance was in poor condition and the sediment was still present in Oakland Ave.


Photos are shown below:

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Track-out pad/stabilized construction entrance in poor condition.






PO Box 1293

Sediment in gutter Oakland Ave.

Albuquerque

New Mexico 87103

www.cabq.gov



Sediment in gutter Oakland Ave.

Additional noncompliance issues were observed at the site;

- 1. A disturbed area along Alameda Blvd requires a sediment BMP.
- 2. The silt fence requires maintenance at the Northwest corner of the site.



PO Box 1293

Disturbed area requires a sediment BMP.

Albuquerque

New Mexico 87103

www.cabq.gov



Silt fence requires maintenance at Northwest corner.



Required mitigation:

- 1. Install a stabilized construction entrance per the approved Erosion and Sediment Control Plan.
- 2. Remove sediment from the gutter along the north side of Oakland Ave from this site's entrance to the east side of the drive pad shown in the photo below.



PO Box 1293

Albuquerque

New Mexico 87103

- 3. Install a sediment BMP south of the disturbed area along Alameda Blvd.
- 4. Perform maintenance on the silt fence at the northwest corner at the outfall.

If violations are not mitigated within 30 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you would like to schedule a follow-up inspection at a day and time of your convenience, prior to 30 days from the date of this letter please let me know.

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

www.cabq.gov

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Friday, March 03, 2017 2:59 PM Cherne, Curtis; Faizel Kassam

To: Cc:

Stephen Pendergraft

Subject:

RE: Legacy NAA Apartmetns construciotn Site inspection and Violation letter

Curtis, we just re-fluffed the drive this week, and re-swept all Oakland, but still not up to par by your comments, I will be on it first this Monday, next time you are on site please stop in the trailer, I much rather walk the site with you first hand. Thanks again, have a good weekend. - Matt

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Friday, March 3, 2017 2:37 PM

To: Faizel Kassam < fkassam@legacy-hospitality.com Cc: Matt Ferreira mferreira@legacy-hospitality.com

Subject: Legacy NAA Apartmetns construciotn Site inspection and Violation letter

Faizel,

Please see attached letter.

Most folks like to schedule the follow-up inspection at a date/time of their convenience.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



Matt Ferreira

Project Manager/Superintendent Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000 mferreira@legacy-hospitality.com www.Legacy-Hospitality.com

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

ECS File: C 18 E064B



	General Information
Project Name	Legacy NAA Apt
and Location	Caller A prist of Sin Parker
	Contact Phone #/ Contact Phone Phone #/ Contact Phone Phone #/ Contact Phone Phone Phone Phone Phone Phone Phone Phone Phone
Site Contact Name & Agency	Contact Phone #/
Date of Inspection	3-3-17 Start/End Time 10:20 / 1024
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	installing utilities pouring foundation
Type of Inspection:	(X) failif of the all the all the
Regular	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Pollow-Up
	Weather Information
Weather at time of this inspect	ion? Temperature: ~_50F°
	Rain · Sleet · Fog · Snowing · Windy
	ince the site was Permitted? · Yes · No
Amount: • < 1/4" • 1/4" to 3	
	Erosion & Sediment Control Inspection
■ Entrance / Track-Out	Frack-vet pak not possable property cut needs mainten Sence, etc. Solimer in guther worth 5th - Street Seed, from evolume to east 5-1 is at
 Sediment Controls / Silt F 	ience.
Check Dams, Waddles	etc. Iddin't in gutter worth 54 - Street
Erosion Controls / Mulch,	seed from evalue to east 5-1 is at
entruie.	east of m AL to towing endman
 Housekeeping/Pollutant C 	Controls Controls
 Debris/Pollutants/Sedimer 	nt in MS4 along Alane de - filh Soll
" Notes Sitt for which 18	n outfall for the site
Is site being maintained in complian	nce with the Drainage Ordinance? Yes No Signature 3.3-17 Date

ECS File: CIOE064B



N E				
	General Informat	ion		
Project Name and Location	Legacy NAA 1	pb		
Site Contact Name & Agency	mast Ferreira	Contact Pho E-mail	one #/	mforeira@ Cegacy.husphlish 10/2:30
Date of Inspection	2-14-17	Start/End Time	2:	10/2:36
Inspector Name, COA Dept.	Curtis Cl	nerne, Stormwater Qu		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		_	
Inspector Qualifications	Qualified Compliance Inspector of S	tormwater- Stormwate	r One	
Describe Present Phase of Construction	1 pod pound, gradin	e part		
Type of Inspection:	, , , , , , , , , , , , , , , , , , , ,			
• During stor	rm event • Post-storm event (> 0.5 ind	ch) (311) Complain	t Resp	onse • Follow-Up
1 34 6	Weather Informat	tion		
Weather at time of this inspect			Tem	perature: ~ 4 F°
	Rain · Sleet · Fog · Snowing			
Has there been a storm event s Amount: • < 1/4" • /4" to		• No		
Amount.	Erosion & Sediment Contr			
	CALCULATION OF THE PROPERTY OF	to the - Parkett in the Parket	1	
Entrance / Track-Out	pard new entrance.	- modern or	rack	-at - Suein
 Sediment Controls / Silt F Check Dams, Waddles 	,			
Erosion Controls / Mulch	, Seed,			
 Housekeeping/Pollutant C 	Controls			
Debris/Pollutants/Sedime	nt in MS4			
· Notes Sit Supu	Know what he's	durns.		
				1
Is site being maintained in complian	nce with the Drainage Ordinance?" Yes	No) Curt (C	<u>Date</u>

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Friday, February 24, 2017 8:49 AM

To:

Cherne, Curtis

Subject:

RE: Legacy NAA Apartments follo-up inspection

Thanks for the follow up Curtis, I will send you pic once completed.-Matt

From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Thursday, February 23, 2017 4:20 PM

To: Matt Ferreira < mferreira@legacy-hospitality.com > Cc: Faizel Kassam < fkassam@legacy-hospitality.com > Subject: Legacy NAA Apartments follo-up inspection

Matt,

Good afternoon.

I visited the site today for a follow-up inspection since last week the track-out pad was in poor condition and needed to be replaced.

During today's inspection, it had not been replaced.

Got to talk to Shane and he said you've ordered the rock and are waiting on it. Let me know if you need more than one week. It helps that you have some subs parking on Oakland Ave. I asked that he/you send a pic when it is installed.

We also discussed removing the sediment from the gutter along the north side of Oakland. Don't know if it was swept over there or blown over there. Either way there is too much.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



Matt Ferreira
Project Manager/Superintendent
Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000 mferreira@legacy-hospitality.com

mferreira@legacy-hospitality.com www.Legacy-Hospitality.com

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

racking No: NMR12 B223

ECS File: CIBEOGYB



	General Information		
Project Name	Legacy NAA Apt	·S	
and Location	legacy NAN Apt. Oakland east of San	Podr	
Site Contact Name & Agency	Mott Ferreira	Contact Phone #/ E-mail	Sep Lule
Date of Inspection	2-23-17	Start/End 7;6	15:/1000
Inspector Name, COA Dept.	Curtis Cherne, St	ormwater Quality	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormwate	er- Stormwater One	
Describe Present Phase of Construction	onsile utilities		
Type of Inspection:			
• Regular • During sto	rm event • Post-storm event (> 0.5 inch) • 3	11 / Complaint Resp	onse • Follow-Up
	Weather Information		
Weather at time of this inspect			perature: ~ 50 F°
	Rain · Sleet · Fog · Snowing ·	Windy	
Has there been a storm events Amount: • < 1/4" • 1/4" to	ince the site was Permitted? • Yes • No 4" • > 34" • Snow"		
	Erosion & Sediment Control Inspec	ction	
* Entrance / Track-Out	Jeeds replacement - sheet.	Swept to	suth on with
 Sediment Controls / Silt I Check Dams, Waddles 	•		
 Erosion Controls / Mulch 	, Seed, hatering while I h	as There	
Housekeeping/Pollutant C	Controls		
 Debris/Pollutants/Sedime 	/1		
· Notes 501h to	- wait forever as to Fu	it on Ros	ek. Jord
him it const	- wait forever as to Fu	A pic who	- conglite
Is site being maintained in complian	nce with the Drainage Ordinance?" Yes " No	ignature	Date

From:

Matt Ferreira <mferreira@legacy-hospitality.com>

Sent:

Tuesday, February 14, 2017 2:28 PM

To:

Cherne, Curtis

Subject:

Legacy NAA Apartments

Cell Phone (505) 415-4568



Matt Ferreira Project Manager/Superintendent Legacy Hospitality, Inc.

6501 Eagle Rock NE Suite B-5 Albuquerque, NM 87113 (505)243-6000 mferreira@legacy-hospitality.com www.Legacy-Hospitality.com

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mail are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From:

Cherne, Curtis

Sent:

Thursday, February 23, 2017 4:20 PM

To: Cc:

'mferreira@legacy-hospitality.com' 'fkassam@legacy-hospitality.com'

Subject:

Legacy NAA Apartments follo-up inspection

Attachments:

entrance.jpg; sediment_oakland.jpg; sediment_oakland2.jpg

Matt,

Good afternoon.

I visited the site today for a follow-up inspection since last week the track-out pad was in poor condition and needed to be replaced.

During today's inspection, it had not been replaced.

Got to talk to Shane and he said you've ordered the rock and are waiting on it. Let me know if you need more than one week. It helps that you have some subs parking on Oakland Ave. I asked that he/you send a pic when it is installed.

We also discussed removing the sediment from the gutter along the north side of Oakland. Don't know if it was swept over there or blown over there. Either way there is too much.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

C/ 8 E 0 6 4 B ECS File: BEE 001



	General Information		
Project Name and Location	Legacy NAA Apo	adout site to	se of Toyota
and Location	Legacy NAA Apartmel site essent Toyoda Oakland east of SAn Ardin Faizel Kussan Contact Phone #/ Skassan @		
Site Contact Name & Agency	Faizel Kussan Vandy Investments, Inc	E-mail	fkassune Cegacy-Hispita
Date of Inspection	12-5-16	Start/End //Time	1:15
Inspector Name, COA Dept.	Curtis Chern	e, Stormwater Quality	1
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One		
Describe Present Phase of Construction	grading		
Type of Inspection:	J		
 Regular During sto 	rm event • Post-storm event (> 0.5 inch)	• 311 / Complaint Resp	oonse Follow-Up
	Weather Information		
Weather at time of this inspect	ion?	Ten	nperature: ~ 50 F°
	Rain · Sleet · Fog · Snowing	• Windy	
/	ince the site was Permitted? · Yes · N	lo	
Amount: $(< \frac{1}{4})$ • $\frac{1}{4}$ " to			
	Erosion & Sediment Control In	spection	
• Entrance / Track-Out	fixed entrance, will	rus mantum	Som - no track-i
 Sediment Controls / Silt I Check Dams, Waddles 	s, etc. <u>6</u> K	- ` 1	
 Erosion Controls / Mulch 	, Seed, Ad luging STH	mo15t	
 Housekeeping/Pollutant 0 	Controls OL	···	
 Debris/Pollutants/Sedime 	nt in MS4		
* Notes			
Is site being maintained in complia	nce with the Drainage Ordinance? • (Yes) • No	Cuto C Cs Signature	12-5-11 Date

ECS File: CIE EUL 48



	General Information
Project Name	Legacy NAA Spartnuts
and Location	nalular rast 1 san Rebo
Site Contact Name & Agency	Contact Phone #/ Legacy- Ituspitahk
Date of Inspection	11-21-16 Start/End 7:45/0/0188
Inspector Name, COA Dept.	17-21-16 Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	groding
Type of Inspection:	0.1
• Regular • During stor	
	Weather Information
Weather at time of this inspect	ion? Temperature: ~_45F°
	Rain · Sleet · Fog · Snowing · Windy
Has there been a storm event s Amount: '4" to 3	ince the site was Permitted? · No · Snow"
	Erosion & Sediment Control Inspection
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 	. \ 11
 Erosion Controls / Mulch 	, Seed, \sim 6
Housekeeping/Pollutant C	Controls OL
 Debris/Pollutants/Sedime 	nt in MS4
· Notes Franklins	doing touthwork
(1) Jacobin	
Is site being maintained in complian	nce with the Drainage Ordinance? Yes No Gut a Clu 11-31-16 Signature Date

From:

Cherne, Curtis

Sent:

Tuesday, November 22, 2016 10:30 AM 'fkassam@legacy-hospitality.com'

To: Cc:

'Grant Morrison'

Subject:

Legacy NAA APrtments SWPPP inspection

Attachments:

track-out_pad.jpg

Faizel,

Good morning.

I was out at Legacy NAA apartments yesterday.

The track-out pad should extend all the way to the asphalt as the dirt in the gap will create track-out. The track-out was minor.

I forgot to check for the fabric underneath the rock when I was out there. If there isn't any, please put some down. It will extend the life of the track-out pad.

Thanks, Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."