

From: [Sims, Timothy E.](#)
To: Pm@paarugroup.com
Cc: [Cherne, Curtis](#); [Sims, Timothy E.](#)
Subject: Mark 35 Development - 9300 Holly Ave. NE - SWPPP Inspection 02.07.19
Date: Friday, February 8, 2019 10:35:52 AM
Attachments: [ConcreteWashoutLeak.jpg](#)
[ConstructionDebris.jpg](#)
[ConstructionTrash.jpg](#)
[DumpsterCover.jpg](#)
[TrackoutPad.jpg](#)
[West_SecondaryTrackout.jpg](#)
[West_sediment_in_Street.jpg](#)
[02.07.19InspectionR-S.PDF](#)
[ConcreteWashout2.jpg](#)

Good morning Xenia:

I conducted an inspection on Thursday, 02.07.19; and noted some issues that will need to be completed within approximately seven (7) days.

1. Concrete washout is leaking, please provide/ ensure this spill is cleaned and prevented in the future.
2. Construction debris and associated trash will require cleaning. Also please provide a cover for the dumpster.
3. Please tidy up the initial track out pad, rocks are a little too close to the travel lane. Is the entrance required?
4. To the west of this project the main construction traffic enters the site, please provide a sediment BMP or sweep this entrance.

I have also attached a copy of the inspection report. Please ensure these outstanding issues are mitigated within the standard seven days.

Regards,



Timothy Sims

Stormwater Inspector
stormwater quality

o 505.803.6155

e tsims@cabq.gov

cabq.gov/planning

