



	General Information		
Project Name	FAIR FIELD S	SUITES	
and Location	4875 PAN AN	1ERICAL	
Site Contact Name & Agency	KELL MOORE	ESC File No.	F17E006B
Date of Inspection	12-20-17	Start/End / .'	50/200
Inspector Name, COA Dept.	Stanice "Totten" Ellio	tt, Stormwater Qua	dity
Describe Present Phase of Construction	COMPLETE 5Jab,	lized	
Type of Inspection: Regular During store	m event	11 / Complaint Resp	oonse 🗆 Follow-Up
	Weather Information		Myna Pens
Weather at time of this inspecti	on?	Tem	perature: ~55 F°
		Windy	
Has there been a storm event si Box 1293 Amount: □ < ¼" ↓ to ¾	nce the site was Permitted? $\sqrt{\text{Yes}}$ $\square \text{No}$ $\square \text{Snow}$ \square		
	Erosion & Sediment Control Inspec	tion	
Entrance / Track-Out			
Sediment Controls / Silt Fence,			,
Inlet Protection, Wattles, etc.			
4 87103			
	BI		
w.cabq.gov	- KANO		
Erosion Controls Housekeeping/Pollutant Control	ols		
Debris/Pollutants/Sediment in I	ASA		
Notes	713-4		
a. 1			
	•	1 4 00 =	
Is site being maintained in compliance	e with the Drainage Ordinance ? Yes No	1 Ulioti	12 -20-17

From:

Cherne, Curtis

Sent:

Wednesday, August 16, 2017 3:09 PM

To:

Verhage, Kathleen M.

Cc:

Chavez, Patrick (pchavez@amafca.org); Daggett, Kevin; ken@wrighthospitality.com

Subject:

RE: Construction debris at Vineyard Water Quality feature

Kathy/Patrick,

I just got back from the site.

I meat with Ken, Site Supervisor, and explained to him why I was there. The material in the channel is Styrofoam. It is being blown into the channel from the hotel project.

The Styrofoam is installed on top of the plywood, then "rasped" or roughened up so it will hold the stucco and it is also "rasped" as the framing isn't necessarily flush, so they work it so there is a flush surface. The small particles are from this process.

Ken called the subcontractor foreman (Dominic) who arrived on the jobsite in about 15 minutes. I explained to him that we want only water entering the river.

I told the foreman, Dominic, that the Styrofoam pieces are to be removed from the ground (they vacuum it) and I expect a 95% removal rate. We also agreed that they would vacuum at the end of each day. I also relayed this info to the Site Supervisor, Ken.

As far as the Vineyard channel goes, I told them that it is an AMFCA facility so I cannot direct any work in the channel. Patrick, please let Ken know (and please copy me) on what AMAFCA would like for them to do as far as mitigation.

They are also to send me pictures once this initial batch of material is removed from the ground at the site.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

From: Verhage, Kathleen M.

Sent: Wednesday, August 16, 2017 1:16 PM

To: Cherne, Curtis

Cc: Chavez, Patrick (<u>pchavez@amafca.org</u>); Daggett, Kevin **Subject:** Construction debris at Vineyard Water Quality feature

Curtis-

Is this hotel construction site on your list? Or should I ask one of our IDDE inspectors to check it out?

Thanks, Kathy



	General Info	rmation		
Project Name and Location	FAIRFIELD	501	TES	
Site Contact Name & Agency	KEN MOORE		ESC File No.	F175006B
Date of Inspection	8-29-17		Start/End 7:2	93 /9:55
Inspector Name, COA Dept.	Cur	tis Cherne, St	ormwater Quality	
Describe Present Phase of Construction	PREPPILIG T	0 570	icco Bu	DG.
Type of Inspection:				
· Regular · During stor	m event • Post-storm event (>	0.5 inch) • 3	11 / Complaint Resp	oonse Follow-Up
	Weather Info	rmation		
Weather at time of this inspecti	on? Rain · Sleet · Fog · Sno	wing •	Tem Windy	perature: ~_ 7 0_F°
Has there been a storm event si		Yes · No		
Amount: • $< \frac{1}{4}$ " to $\frac{3}{4}$ "	4" > 3/4"	Snow"		
	Erosion & Sediment C	ontrol Inspec	tion	
Entrance / Track-Out	H			
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.				
Erosion Controls PAVET Housekeeping/Pollutant Contro	DEPARING AR	EA END, BON	IC. POLLUTANT	W.SIDE @ INLET
Debris/Pollutants/Sediment in Notes	MS4_ N 0			
Is site being maintained in compliance	e with the Drainage Ordinance ? Yo	9 1 10 1	Cut & Ch	8-29-7 Date

From:

Cherne, Curtis

Sent:

Tuesday, August 29, 2017 2:54 PM

To:

ken@wrighthospitality.com

Subject:

Farifiled Suites Construction Site Inspection

Attachments:

cement_pollution.jpg; cement_pollution2.jpg; cement_pollution3.jpg

Ken,

Good afternoon.

I couldn't find you when we finished the inspection.

There were a couple new wash-outs on the out-lot with the trailer. Please remove.

The wash-out behind the building was old, but still needs to be removed.

Dominic's crew got busy picking up trash and said he would clean-up the wash-out behind the building.

The wash-out bin had recent additions to it, which is good to see.

Thanks, Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

[&]quot;Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



	General Information	
Project Name and Location	Furfield Sull 4875 Pan	
Site Contact Name & Agency	Kn nove	ESC File No. FN Bob63
Date of Inspection	8-16-17	Start/End /:SS/2:40
Inspector Name, COA Dept.	Curtis Cher	ne, Stormwater Quality
Describe Present Phase of Construction	installing form Ext	6/15
Type of Inspection: Regular During stor	m event • Post-storm event (> 0.5 inch)	311/Complaint Response · Follow-Up
	Weather Information	
Weather at time of this inspection Clear · Cloudy · H	on? Rain · Sleet · Fog · Snowing	Temperature: ~F° • Windy
Has there been a storm event si	nce the site was Permitted? · Yes · I	No
Amount: • < 1/4" • 1/4" to 3	4" · > 3/4" · Snow	"
	Erosion & Sediment Control I	nspection
Entrance / Track-Out		
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	of may	or down w/ buchet
Erosion Controls Housekeeping/Pollutant Control Styro four blog Bourd guer Debris/Pollutants/Sediment in Notes	on blog outsile of	a bldg var Sandlig Bboal word panel out into
Is site being maintained in compliance	ee with the Drainage Ordinance?" Yes " No	Signature Date

09/16/2017 D9:02

Shows and bows



Spoke to Pan move. He calked as he is having Phoding problems and the inlit protection is raising his west.

His His parent section is 6", I tolk
him to seat his site so it is 6"
below the grate and he can remove
the inlet production
Cut. Mr



	General Information
Project Name and Location	Fairfield Surfer 4275 Pan America Fray NE
Site Contact Name & Agency	The work orouge ESC File No. FITE 0060
Date of Inspection	8-7-17 Start/End 0:55 / 9:35
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Describe Present Phase of Construction	512 weather in
Type of Inspection:	£ .
Regular	
	Weather Information
	Rain · Sleet · Fog · Snowing · Windy
Has there been a storm event s	ince the site was Permitted? · Yes · No 4" · > ¾" · Snow"
Amount: • < 1/4" • 1/4" to	4" · > 3/4" · Snow"
	Erosion & Sediment Control Inspection
Entrance / Track-Out(XC
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	how to seinstall new inter problem
draing gruh	in du to Ston 6 lockoge 1
1/1 00 11/2010	a fall freeze / tempers
Erosion Controls PML Housekeeping/Pollutant Control	
Debris/Pollutants/Sediment in	MS4
Notes pails tra	iler up 3" and now dist pile
will will	5, 1+ free along whin South bry
Is site being maintained in complian	ce with the Drainage Ordinance? Yes No Signature Date

From:

Cherne, Curtis

Sent:

Monday, August 07, 2017 2:33 PM

To:

'ken@wrighthospitality.com'

Subject: Attachments:

Construction site and drainge inspection

NW_inlet.jpg

Ken,

Thanks for taking the time to speak with me at the site today.

In addition to the items we spoke about, the inlet in the NW corner could use a different BMP. Rather than covering it, I think more of a double-stacked filter sock and leave the grate uncovered would work. You should dig it out a bit first.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: PNEOOGB



	General Information	
Project Name and Location	Farfist I Suites 4875 Pan Anrica Ken Moore	. Fray NE
Site Contact Name & Agency	The word Group	E-mail /20 AV
Date of Inspection	4-19-17	Start/End /0:15//0:25
Inspector Name, COA Dept.	Curtis Cherne,	Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov	
Inspector Qualifications	Qualified Compliance Inspector of Stormwa	ater- Stormwater One
Describe Present Phase of Construction	Construction walls	
Type of Inspection: Regular • During store	rm event • Post-storm event (> 0.5 inch) • Weather Information	311 / Complaint Response • Follow-Up
•	Rain · Sleet · Fog · Snowing · ince the site was Permitted? · Yes · No	
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 	A 10	
 Erosion Controls / Mulch 	, Seed, <u>walls</u>	
 Housekeeping/Pollutant C 	Controls <u>Ol</u>	
Debris/Pollutants/Sedime	nt in MS4	
• Notes		
Is site being maintained in complian	nce with the Drainage Ordinance ?" (res) " No	Signature Date

ECS File: FITE0063



	General Information		
Project Name and Location	Fairfill Studios 485 Pan Ameria Fr	ny NE	
Site Contact Name & Agency	1/2015 Pan Ameria Fray NE 1/201 Moore Contact Phone #/ Ken@ wright ho sprtetly E-mail Com Com Com		
Date of Inspection	3-6-17	Start/End /130/2106	
Inspector Name, COA Dept.	Curtis Cherne, St	ormwater Quality	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormwate	er- Stormwater One	
Describe Present Phase of Construction Type of Inspection:	foundation powed		
• Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 3	11 / Complaint Response Follow-Up	
	Weather Information		
Has there been a storm exent si	Rain · Sleet · Fog · Snowing ince the site was Permitted? · Yes · No	Temperature: ~60_F°	
Amount: • < 1/4" • (4") to 3/	4" -> 3/4"	42	
	Erosion & Sediment Control Inspec	tion	
 Entrance / Track-Out 	0k		
 Sediment Controls / Silt F Check Dams, Waddles 		protection at su vale	
 Erosion Controls / Mulch, 	Seed, walls		
 Housekeeping/Pollutant C 	Controls ok		
 Debris/Pollutants/Sediment 	nt in MS4		
Notes			
		1	
Is site being maintained in complian	ice with the Drainage Ordinance? [16] - No	Cute 6 clar 3-6-17 gnature Date	

ECS File: FNE006P



	Gene	ral Information			
Project Name and Location	Fairfult				
Site Contact Name & Agency	Deepush		Contact Pho E-mail	one #/	
Date of Inspection	2-21-17		Start/End Time	101.	50/11:05
Inspector Name, COA Dept.		Curtis Cherne, St	ormwater Qı		
Inspector Phone / E-mail	505-924-3420/ccherne@	cabq.gov			
Inspector Qualifications	Qualified Compliance I	Inspector of Stormwate	er- Stormwate	r One	
Describe Present Phase of Construction	Placing steel	for fundad	ber s		
Type of Inspection:					3
Regular	rm event • Post-storm	event (> 0.5 inch) • 3	11 / Complain	nt Respon	ise Follow-Up
	Weat	her Information			
Weather at time of this inspect	ion? Rain · Sleet · Fog	- Snowing -	Windy	Tempe	rature: ~ 60 F
Has there been a storm event s Amount: • < 1/4" • 1/4" to 3					
	Erosion & Sed	iment Control Inspec	tion		
■ Entrance / Track-Out _	0K				
 Sediment Controls / Silt F Check Dams, Waddles 	' 1,				
Erosion Controls / Mulch					
Housekeeping/Pollutant C	Controls Ok - A	NO ECNT	pollum o	-40	ach out
■ Debris/Pollutants/Sedime	nt in MS4	1			
• Notes 012	it see wa	short m 3	sile		
			9		
Is site being maintained in compliar	ice with the Drainage Ordinar		enature	chi	2-21-7 Date
		nce ? Yes No	Cut 6	ch	2-21-1 Date

ECS File: F17 B0068



	General Information
Project Name and Location	Farfiel Soules 4075 Pan America Fruy NA
Site Contact Name & Agency	Deepesh Dream Catcher ABR North Contact Phone #/ Syncup. HI Hotels
Date of Inspection	2-6-17 Start/End /0'00//0:/5
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	retaining wall bust
Type of Inspection:	
Regular	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up
	Weather Information
Weather at time of this inspect	
	Rain · Sleet · Fog · Snowing · Windy
Has there been a storm event s Amount: • < 1/4" • 1/4" to 3	ince the site was Permitted? · Yes · No '4" · > 3/4" · Snow"
	Erosion & Sediment Control Inspection
Entrance / Track-Out	ok
 Sediment Controls / Silt F Check Dams, Waddles 	s, etc.
Erosion Controls / Mulch	, Seed, NU a a little frasky - av brash receptable
Housekeeping/Pollutant C	Controls 1 come portupe - didn't when it drying
Debris/Pollutants/Sedime	nt in MS4 <u>~U</u>
• Notes	
Is site being maintained in complian	nce with the Drainage Ordinance? Yes $\underbrace{\text{No}}_{Signature}$ $\underbrace{\text{Lut }^c}_{Date}$ $\underbrace{\text{Lut }^c}_{Date}$

From:

Cherne, Curtis

Sent:

Monday, February 06, 2017 4:08 PM

To:

deepesh@suncapitalhotels.com

Cc: Subject: 'Grant Morrison'

Attachments:

Fairfield Suites Follow-up inspection cement_pollution.jpg; trash.jpg

Deepesh,

Good afternoon.

I went out to your site for a follow-up in hopes of closing the previous violation(s).

I saw that an acceptable concrete wash-out pit was installed, that's good.

However, someone failed to use it. I figure since you are making progress, I will not issue another fine as stated in the previous letter, but will give you this one. I scheduled a follow-up for ten days from now. That gives you plenty of time to clean-up the latest cement pollution and talk to concrete subs.

In addition, the site is getting a little trashy in the northeast corner.

If you would like to schedule a day/time for the follow-up inspection please let me know. Most folks find it beneficial as there should be no surprises.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: F17 E00617



	General Information
Project Name and Location	Fairfield Suites 4275 Par Anview Fow, No
Site Contact Name & Agency	Deeped Contact Phone #/ Sur capill hiles
Date of Inspection	1-17-17 (Start/End 7:06/9:18
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	
Type of Inspection:	
Regular	rm event Post-storm event (> 0.5 inch) • 311 / Complaint Response Follow-Up
	Weather Information
Weather at time of this inspect	ion? Temperature: ~F°
	Rain Sleet Fog Snowing Windy
	ince the site was Permitted? Yes · No 'Yes · No 'Snow"
Amount: • < 1/4" (• 1/4" to 3	
	Erosion & Sediment Control Inspection
■ Entrance / Track-Out _	use trackout po 2
 Sediment Controls / Silt F Check Dams, Waddles 	CKUM.
Erosion Controls / Mulch.	5HII has, concret wash out, 158hin - was
 Housekeeping/Pollutant C 	Controls Lass The 30 days - refree u dy 11
Debris/Pollutants/Sedime	nt in MS4
Notes Check	checking for draining and Try - not
ESC, com	t tall
Is site being maintained in complian	nce with the Drainage Ordinance? * Aps/ No Signature 1-17-17 Date

City of Albuquerque Planning Department One Stop Shop-Development and Building Services Drainage Control Ordinance Violation Invoice Date 12-22-16

Permit Number: 2016 000 005 Category Code: 971

Project: Fairfield Suites account string: 110 441011 4961000

Property Legal Description/Address: Lot A1C1A3A Blk 0000 Cryer Property

Property Owner: Dreamcatcher ABQ North, LLC

Property Contact/Invoice sent to: Deepesh Kholwadwala @

deepesh@suncapitalhotels.com

Description of Violation: Drainage onto adjacent property not per approved drainage

plan.

Fine:

Date(s) of Violation: 12-22-16

\$500/day \$500.00

Number of days:

Total due: \$500.00

Total due is to be paid within 30 days of receipt of this invoice. After 30 days if payment is not made, a municipal lien may be placed on the property and non-payment will result in delay of future approvals related to the project.

The fine can be paid at any City of Albuquerque Treasury location. The most convenient may be at Plaza del Sol, 600 2nd St. NW. Provide a copy of the receipt to Stormwater Quality, Suite 400 600 2nd St. NW, or e-mail to ccherne@cabq.gov.

Rev. February 2016

ECS File: F17E0068



	General Information
Project Name and Location	Fairfull Suites 4975 Pan America Fruy NE
Site Contact Name & Agency	General Information Fairfield Suites 4975 Pan Anesca Fruy NE Despein Oreacath ABR with M Start/End 1126 / 1146
Date of Inspection	1-23-7 Start/End 11:30 /11:45
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	Constructing reterring wall
Type of Inspection:	
Regular	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up
	Weather Information
Weather at time of this inspect	Temperature: ~ 45 F° Rain · Sleet · Fog · Snowing · Windy
Has there been a storm event s Amount: • < 1/4" • 1/4" (0.3)	
	Erosion & Sediment Control Inspection
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 	
Erosion Controls / Mulch	, Seed,
Housekeeping/Pollutant (Controls no-washiout
Debris/Pollutants/Sedime	nt in MS4
Notes	
Is site being maintained in complian	nce with the Drainage Ordinance? Yes No Signature Date

City of Albuquerque Planning Department One Stop Shop-Development and Building Services Drainage Control Ordinance Violation Invoice Date 1-24-17

Permit Number:

2017 000 006

Category Code: 971

Project: Fairfield Suites

account string: 110 441011 4961000

Property Legal Description/Address: Lot A1C1A3A Blk 0000 Cryer Property

Property Owner: Dreamcatcher ABQ North, LLC

Property Contact/Invoice sent to: Deepesh Kholwadwala @

deepesh@suncapitalhotels.com

Description of Violation: Cement Pollution

Date(s) of Violation: 1-23-17

Fine:

\$500/day

\$500.00

Number of days:

1

Total due:

\$500.00

Total due is to be paid within 30 days of receipt of this invoice. After 30 days if payment is not made, a municipal lien may be placed on the property and non-payment will result in delay of future approvals related to the project.

The fine can be paid at any City of Albuquerque Treasury location. The most convenient may be at Plaza del Sol, 600 2nd St. NW. Provide a copy of the receipt to Stormwater Quality, Suite 400 600 2nd St. NW, or e-mail to ccherne@cabq.gov.

Rev. February 2016

January 24, 2017

Deepesh Kholwadwala, Dreamcatcher ABQ North, LLC: deepesh@suncapitalhoteis.com Fairfield Suites: 4875 Pan American Frwy NE

Re: Drainage Control Ordinance (14-5-2-1) and NPDES CGP Violations for Cement Pollution and Erosion and Sediment Control- Fairfield Suites

Dear Mr. Kholwadwala,

On December 22nd, the City issued a Violation Letter (Order) to remove the cement pollution and provide an acceptable concrete/mortar/stucco wash-out receptacle.

You were also notified that "In addition, if the violations are not mitigated within 30 days or are found again after 30 days, the property owner is subject to a fine up to \$500/day per the City's Drainage Control Ordinance."

At yesterday's inspection:

1. Numerous instances of cement pollution were observed on the site and an acceptable concrete/mortar/stucco receptacle was not on-site.


See photos below:

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Cement pollution.



Cement pollution.

PO Box 1293

Albuquerque


New Mexico 87103

www.cabq.gov



Cement pollution.

In addition, the sediment BMP (silt fence) had a gap along the southern boundary and sediment has entered the site to the south.



Gap in silt fence and sediment on adjacent property.

PO Box 1293

Required Mitigation:

- 1. Remove the cement pollution and provide an acceptable concrete/mortar/stucco wash-out receptacle.
 - 2. Provide a sediment BMP(s) to prevent sediment from migrating offsite.

Albuquerque

For the Cement Pollution:

Per the previous Violation letter, the City is assessing a fine of \$500. This fine is for one day. Additional days may be added if the violations are not mitigated upon a follow-up inspection in ten days or violations are observed in future inspections.

New Mexico 87103

For the sediment BMP:

www.cabq.gov

The violations are to be mitigated within 30 days or the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

C: Grant@inspectionsplusinc.com

December 22, 2016

Deepesh Kholwadwala, Dreamcatcher ABQ North, LLC: deepesh@suncapitalhotels.com Fairfield Suites: 4875 Pan American Frwy NE

Re: Drainage Control Ordinance (14-5-2-1) and NPDES CGP Violations for Erosion and Sediment Control- Fairfield Suites

Dear Mr. Kholwadwala,

On November 21st, the City issued a Violation Letter (Order) to provide a temporary drainage solution to prevent flows from entering the PNM substation

You were also notified that "In addition, if the violations are not mitigated within 30 days or are found again after 30 days, the property owner is subject to a fine up to \$500/day per the City's Drainage Control Ordinance."

At today's inspection:

- 1. Drainage was observed leaving your site and entering the PNM substation. The photos were taken at 12:00 PM and it was still raining.
- 2. Numerous instances of cement pollution were observed and an acceptable concrete wash-out was not onsite.

PO Box 1293

3. Dirt was piled-up against the silt fence higher than halfway.

See photos below:

Albuquerque


NM 87103

www.cabq.gov



Drainage leaving site.





PO Box 1293

Albuquerque

NM 87103

www.cabq.gov



Cement Pollution





Dirt piled-up against silt fence.

Required Mitigation:

PO Box 1293

- 1. Provide a temporary drainage solution that prevents drainage from entering the PNM substation.
- 2. Remove the cement pollution and provide an acceptable concrete/mortar/stucco wash-out receptacle.
- Albuquerque

3. Remove soil from the silt fence so it is below halfway up the silt fence.

For the Drainage entering the PNM substation:

NM 87103

Per the previous Violation letter, the City is assessing a fine of \$500. This fine is for one day. Additional days may be added if the violations are not mitigated upon a follow-up inspection in ten days or violations are observed in future inspections.

www.cabq.gov

For the cement pollution and silt fence:

The violations are to be mitigated within 30 days or the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

C: Grant@inspectionsplusinc.com

From: Deepesh Kholwadwala <deepesh@suncapitalhotels.com>

Sent: Monday, November 21, 2016 2:06 PM

To: Cherne, Curtis

Cc: Carrillo, Abiel X.; 'Moye, Laurie'
Subject: RE: Fiarfiled Suites Violation Letter

Curtis -

Thank you for the note. We're working to get a retaining wall permitted. Work will start as soon as permit is in hand. We hit a short delay with Century Link but that resolved last Friday. Meanwhile, I forwarded this notice to our engineer and supervisor to make comments and take action while we wait for the permit.

Deepesh

From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Monday, November 21, 2016 1:53 PM

To: deepesh@suncapitalhotels.com

Cc: Carrillo, Abiel X. <acarrillo@cabq.gov>; 'Moye, Laurie' <Laurie.Moye@pnm.com>

Subject: Fiarfiled Suites Violation Letter

Deepesh,

Good afternoon.

The drainage problem at Fairfield Suites was not mitigated. Please see attached letter.

Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

City of Albuquerque Planning Department

City of Albuquerque Treasury
Date:1/26/2017 Office:ANNEX
Stat ID:WS000008 Cashier:TRSRMS
Batch: 7759 Trans #:33
Permit: 2016000005
Receipt Num 00399921
Payment Total:#500.00
0910 Drainase Non Complai

VISA Tendered :

\$500.00 \$500.00

City of Albuquerque Planning Department One Stop Shop-Development and Building Services Drainage Control Ordinance Violation Invoice Date 12-22-16

Permit Number:

2016 000 005

Category Code: 971

Project: Fairfield Suites

account string: 110 441011 4961000

Property Legal Description/Address: Lot A1C1A3A Blk 0000 Cryer Property

Property Owner: Dreamcatcher ABQ North, LLC

Property Contact/Invoice sent to: Deepesh Kholwadwala @

deepesh@suncapitalhotels.com

Description of Violation: Drainage onto adjacent property not per approved drainage

plan.

Date(s) of Violation: 12-22-16

Fine:

\$500/day

\$500.00

Number of days:

1

Total due:

\$500.00

Total due is to be paid within 30 days of receipt of this invoice. After 30 days if payment is not made, a municipal lien may be placed on the property and non-payment will result in delay of future approvals related to the project.

The fine can be paid at any City of Albuquerque Treasury location. The most convenient may be at Plaza del Sol, 600 2nd St. NW. Provide a copy of the receipt to Stormwater Quality, Suite 400 600 2nd St. NW, or e-mail to ccherne@cabq.gov.

Rev. February 2016

From:

Cherne, Curtis

Sent:

Tuesday, January 24, 2017 2:04 PM

To:

deepesh@suncapitalhotels.com

Cc:

Biazar, Shahab; 'Grant Morrison'; Sandoval, Darlene M.

Subject:

Fairfiled Suites Violation Letter and Fine Invoice

Attachments:

Fairfield_Suites_Violation_Fine2.pdf; Fairfield_Suites_Violation_Letter_Fine2.pdf

Deepesh,

Please see attached for most recent violation(s) and fine.

This is the second fine the City has sent you.

You are past due on the first fine. A hold has been placed on your project to not allow any inspections or permits to be processed. The hold will be removed when the fine is paid.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

[&]quot;Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

From:

Cherne, Curtis

Sent:

Thursday, December 22, 2016 2:56 PM deepesh@suncapitalhotels.com

To:

Cc:

'Grant Morrison'

Subject:

Violation(s) and fine Fairfield Suites

Attachments:

F17D006B_Violation_Fine_letter.pdf; F17D006B_Fine_Invoice.pdf

Deepesh,

The violation letter and fine invoice are attached.

Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

From:

Cherne, Curtis

Sent:

Monday, January 23, 2017 9:06 AM

To:

Sandoval, Darlene M.

Subject:

Stop inpsections and all permitting on 4875 Pan American Frwy NE

Darlene,

Good morning.

The property owner at 4875 Pan American Frwy is past due on paying his Drainage Ordinance Fine.

In KIVA, I used to put a Hard Hold on the project. This is what I wish to do at above referenced project, but it is not that obvious in POSSE.

I think I put a "stop" on the retaining wall permit, but in "Event" screen, there is no selection for "inspections", so I picked "Findings".

IS this where your employees would look to not schedule an inspection?

I guess I'll put in another one for no new permits. Thanks.

Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: F17 E0668



NI NI		
	General Information	
Project Name	Fairfield Suites	
and Location	4875 Pan America 1	Fruz NE
Site Contact Name & Agency	Despert Kho hradwala Dream Cutch ABO well, LC	Contact Phone #/ E-mail Contact Phone #/ Contact Phone #/
Date of Inspection	12-22-16	Start/End P.Su /9:46
Inspector Name, COA Dept.	Curtis Cherne, Sto	ormwater Quality Cefural at now
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov	to check Ben
Inspector Qualifications	Qualified Compliance Inspector of Stormwate	
Describe Present Phase of Construction	construction for for wall	Soulecer shu closer into
Type of Inspection:		2
Regular During store	m event • Post-storm event (> 0.5 inch) • 31	11 / Complaint Response Follow-Up
	Weather Information	
Weather at time of this inspect • Clear • Cloudy	on? Jain · Sleet · Fog · Snowing · V	Temperature: ~F° Windy
Has there been a storm event s	ince the site was Permitted? · Yes · No	
Amount: • < \frac{1}{4}" • \frac{1}{4}" to \frac{3}{2}	4" · > 34" · Snow"	
	Erosion & Sediment Control Inspect	tion
 Entrance / Track-Out 	track out got ness mass	
 Sediment Controls / Silt F Check Dams, Waddles 		other souther ess
Erosion Controls / Mulch.		nut p. pillutin
 Housekeeping/Pollutant C 	7,0.750 002	5:11
• Debris/Pollutants/Sedime	nt in MS4	1 / 1
Notes Title	Culosul drainer issut.	come beet not not
Chausa	Curende	1
Is site being maintained in complian	ice with the Drainage Ordinance? Yes Sig	enature Date

November 21, 2016

Deepesh Kholwadwala, Dreamcatcher ABQ North, LLC: deepesh@suncapitolhoters.com Fairfield Suites: 4875 Pan American Frwy NE

Re: Drainage Control Ordinance Violation

Dear Mr. Kholwadwala,

On November 10th, 2016, you were informed of the following issue:

1. The inlet that drains Bubba's, Cheddar's and this site has been removed. The grades along the channel will divert flows in the PNM substation. Please contact your engineer to provide a temporary drainage solution until proposed inlets are installed and proper drainage is restored.

A site visit was performed this morning. The temporary drainage solution was not provided and drainage left the site and drained into the PNM substation. In addition, there is considerable erosion where the water comes off the parking lot.

Photos are shown below:

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Arroyo draining into PNM substation. Area is also eroding.



Location where drainage leaves the parking lot.

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Portion of drainage basin draining to PNM substation.



The above listed violation is to be mitigated within 30 days or the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov

copy: Hydrology, Laurie Moye-PMM

ECS File: F17 E06GB



	General Information
Project Name and Location	Fairfield Surtes 4075 Pan America Fray NE
Site Contact Name & Agency	Dream catehor ADO with, UC Contact Phone #/ Sunceptal Habit.
Date of Inspection	11-21-16 Start/End P:18/8.35
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	graded
Type of Inspection:	0.1
Regular	rm event Post-storm event (> 0.5 lech) · 311 / Complaint Response · Follow-Up
	Weather Information
Weather at time of this inspect	ion? Temperature: ~F°
· Clear Choudy · I	Rain · Sleet · Fog · Snowing · Windy
	ince the site was Permitted? · Yes · No
Amount: • < 1/4" • 1/4" to 3	½" · > ¾" · Snow"
	Erosion & Sediment Control Inspection
 Entrance / Track-Out 	olc
 Sediment Controls / Silt F Check Dams, Waddles 	, etc.
Erosion Controls / Mulch.	, seed, Ared erosin combal SE, comme for make draining of of babba'l -, and not provide Solution
 Housekeeping/Pollutant C 	
 Debris/Pollutants/Sedime 	nt in MS4
· Notes write	Vialatin letter
Is site being maintained in complian	nce with the Drainage Ordinance?" Yes "(N) Late the M-11-11 Signature Date

From:

David Soule <david@riograndeengineering.com>

Sent:

Thursday, November 10, 2016 7:27 AM

To:

Cherne, Curtis; deepesh@suncapitalhotels.com

Cc:

Biazar, Shahab

Subject:

RE: Fairfield Suites SWPPP inspection

Thank you i will provide direction as to how we keep the flow on our site. It will involve a berm i anticipate

From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Wednesday, November 09, 2016 2:13 PM

To: deepesh@suncapitalhotels.com

Cc: David Soule (david@riograndeengineering.com); Biazar, Shahab

Subject: Fairfield Suites SWPPP inspection

Deepesh,

Good afternoon.

I stopped by the Fairfield Suites site today at 4875 Pan American for a SWPPP inspection.

The mulch sock along the west side and stabilized entrance looked good.

The silt fence was being installed along the southern boundary while I was there. The silt fence will be a good sediment BMP, but it should be installed prior to earth disturbance activities.

The inlet that drains Bubba's, Cheddar's and this site has been removed. The grades along the channel will divert flows into the PNM substation if there is a source of water (rain/contractor/other).

Please contact your engineer to provide a temporary drainage solution until proposed inlets are installed and proper drainage is restored. I will propose that the southern boundary is bermed-up to direct flows into the AMAFCA channel and a sediment BMP acceptable to AMAFCA is in the channel.

Let me know if you need contact info for AMAFCA.

Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: FITEOULIS



440	
	General Information
Project Name and Location	Hotel behind Chidden's Fairfield Suiley
	4875 Pan American Formy NE
Site Contact Name & Agency	Despet Cholusduala Contact Phone # Scan Capital Dream Catcher 180 runs hotels. con
Date of Inspection	11-9-14 Start/End Time 12:34/2,45
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	grated, serous abet,
Type of Inspection:	
Regular • During storm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up	
	Weather Information
Weather at time of this inspection? • Clear • Cloudy • Rain • Sleet • Fog • Snowing • Windy Temperature: ~ 65 F°	
Has there been a storm event since the site was Permitted? · Yes · No	
Amount: • < ½" • ½" • ¾" • > ½" • Snow"	
Erosion & Sediment Control Inspection	
Entrance / Track-Out	
Sediment Controls / Silt Fence, Check Dams, Waddles, etc. 21 und drain to Mr. 5.15stets	
Erosion Controls / Mulch, Seed,	
Housekeeping/Pollutant Controls O L	
Debris/Pollutants/Sediment in MS4	
· Notes ask Bank when what is:	
Fulni ul Guzman Saul Davil Searche saut A Man 1	
12 2 1 -9-16	
Is site being maintained in compliance with the Drainage Ordinance? No Signature Date	
inly	

From:

Cherne, Curtis

Sent:

Wednesday, November 09, 2016 2:13 PM

To:

deepesh@suncapitalhotels.com

Cc:

David Soule (david@riograndeengineering.com); Biazar, Shahab

Subject:

Fairfield Suites SWPPP inspection

Attachments:

grades west bndry.jpg; existing_inlet_location.jpg; existing_inlet.jpg

Deepesh,

Good afternoon.

I stopped by the Fairfield Suites site today at 4875 Pan American for a SWPPP inspection.

The mulch sock along the west side and stabilized entrance looked good.

The silt fence was being installed along the southern boundary while I was there. The silt fence will be a good sediment BMP, but it should be installed prior to earth disturbance activities.

The inlet that drains Bubba's, Cheddar's and this site has been removed. The grades along the channel will divert flows into the PNM substation if there is a source of water (rain/contractor/other).

Please contact your engineer to provide a temporary drainage solution until proposed inlets are installed and proper drainage is restored. I will propose that the southern boundary is bermed-up to direct flows into the AMAFCA channel and a sediment BMP acceptable to AMAFCA is in the channel.

Let me know if you need contact info for AMAFCA.

Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."