## **Development & Commercial Stormwater Construction Site Inspection Report**

General Information						
Project Name	TRU by Hilton Hotel					
Owners/Operators Name	Veecon LLC / Hanuman	Corporation				
<b>Date of Inspection</b>	08/28/19	Start Time	3:10 PM			
Inspector's Name(s)	Marcos Valadez					
Inspector's Title(s)	Inspector					
<b>Inspector's Contact Information</b>	marcos@inspectionsplusi	nc.com				
Inspector's Qualifications	Training and work experier SWPPP.	nce – see inspector qu	nalification page in section 2 of the			
Type of Inspection: Regular During storm ev	vent Post-storm eve	nt				
	Weather Info	rmation				
Has there been a storm event since the last inspection? Yes If yes, provide: Storm Start Date: 08/27/19   Approximate Amount of Precipitation (in): 0.20" on site rain gauge  Weather at time of this inspection?    Clear						
8. Is there a spill kit on site?	<ul><li>7. Has the "Chemical On Site" form been filled out?</li><li>8. Is there a spill kit on site? Yes Where is it located? In the construction trailer</li></ul>					
	9. Have they done any training for the supervisors or others? Yes 10. Was the inspector able to train any one on this visit? No Who did you speak with?					
10. was the inspector able to	train any one on this visit?	no <b>wno aia you sp</b>	eak with:			
Are the SWPPP and inspections available on site?	Yes The SWPPP b	book and inspections	are located at The construction trailer.			
	Notes	<b>S</b>				
Send inspections to Sam Patel - Taurus5468@gmail.com     3.						

Ver 092314

	Final Stabilization/Termination Checklist.							
1.	Are all soil-disturbing activities complete?	No						
2.	Have all inactive areas of the site not covered by pavement or structure achieved a density of 70% coverage?	No						
3.	Date of Final Stabilization.							
	If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.							
Date	Date Construction Stopped Date Construction Resumed							
Mea the S	Site.							

Construction Phasing		
Activity	Current Status	Activity Started / Completed
Installed BMPs	Silt Fence, Stabilized Const Entrance, Portable Toilet, Roll off	Started:
		Completed: 04/10/19
Site Clearing and Grading	In progress.	Started: 04/10/19
		Completed:
Installing Utilities	Continue In progress	Started: 05/07/19
		Completed:
Building Structure	Vertical construction in progress.	Started: 07/16/19
		Completed:
Paving and Walks		Started:
		Completed:
Final Grading/ Stabilize Site		Started:
		Completed:
Other	Retaining wall in progress	Started: 07/02/19

## **Site-specific BMPs**

• The corrective actions initiated and date completed are in the Corrective Action Log.

	List of BMPs Installed	BMP Installed?	BMP Maintenance Required?	Notes
1	Portable Toilet	Yes	No	
2	Roll off	Yes	No	
3	Silt Fence	Yes	No	
4	Stabilized Construction	Yes	No	
	Entrance			
5	Concrete Washout	Yes	No	
6	Mulch Socks	Yes	No	
7				
8				
9				
10				

Ver 092314 2

1	Are the BMPs shown on	Yes	
	the map?		
2	Were there changes to the SWPPP?	No	
3	Has the SWPPP been updated?	No	
4	Were the changes to the SWPPP implemented within 7 days?		

	New BMPs needed	Notes
1		
2		
3		
4		
5		

## **Overall Site Issues**

 $\label{list of corrective actions will be supplied with this inspection.}$ 

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
1	Are all slopes and disturbed areas not actively being worked properly stabilized?			Entire site is being worked
2	Are natural resource areas (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?	Yes	No	
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	Yes	No	
4	Are discharge points and receiving waters free of any sediment deposits?	Yes	No	
5	Are storm drain inlets properly protected?			Protect the inlets when they are active
6	Is the construction exit preventing sediment from being tracked into the street?	Yes	No	
7	Is trash/litter from work areas collected and placed in dumpsters?	Yes	No	
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	Yes	No	

Ver 092314 3

	BMP/activity	Implemen	nted?	Maintenance Required?	Corrective Action Needed and Notes.
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	No		No No	
10	Are materials that are potential storm water contaminants stored inside or under cover?	Yes	,	No	
11	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	No			
12	Has the Site map been updated to reflect current conditions?	Yes	<b>,</b>	No	The Inspectors map has been updated.
13	Is the NOI posted	Yes	<b>,</b>	No	NOI Posting Location: In the construction trailer
14	Were previous corrections made within 7 days of last inspection or before the next storm event?				
15	(Other)				
Wal	k through the facility and look for	r signs of no	ollution	including paint	, solvents, chemicals, solid waste, oil, and fuel.
1	· · · · · · · · · · · · · · · · · · ·	No		moral paragraph	, 552 ( 212.5) 212.112.113.113.113.113.113.113.113.113.
2		No			
		CERT	'IFICA'	TION STATEM	IENT
	supervision in accordance with a sy the information submitted. Based of directly responsible for gathering the	ystem desigr on my inquir he informati . I am aware	ned to as y of the on, the e that the	ssure that qualifice person or person information sub- ere are significar	were prepared under my direction or ed personnel properly gathered and evaluated as who manage the system, or those persons nitted is, to the best of my knowledge and at penalties for submitting false information, ons."
	Print name: Marcos Valadez				Title: Inspector
		Many	3'		
	Signature:	/ "		-	<b>Date:</b> <u>08/28/19</u>
	SWPPP Management Signature:				Date:

Ver 092314 4

Date: 08/28/19

Project: TPILby

## TRU by Hilton Hotel Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
1	Ensure there is a spill kit	04/10/19		06/04/19
2	Install a rain gauge	04/10/19		07/02/19
3	Install mulch socks per ECP	04/10/19		05/07/19
4	No new issues at the time of this inspection	05/07/19		05/07/19
5	Re-install the mulch sock at the NW side of the site That was removed by TLC Company	05/21/19		06/04/19
6	No new issues at the time of this inspection	06/04/19		06/04/19
7	No new issues at the time of this inspection	06/18/19		06/18/19
8	The site looked good at the time of this inspection.	07/02/19		07/02/19
9	The trash bin needs to be emptied	07/16/19		08/14/19
10	Repair the silt fence at the SW corner. Need to make sure the silt fence at the SW corner of the site is toed in (bottom of fence is buried 6") and adjust the mulch sock.	07/31/19		08/14/19
11	No new issues at the time of this inspection	08/14/19		08/14/19
12	The site looked good at the time of this inspection.	08/28/19		08/28/19

SWPPP Management Signature: Date:

Ver. 070813