Development & Commercial Stormwater Construction Site Inspection Report

General Information					
Project Name TRU by Hilton Hotel					
Owners/Operators Name	Veecon LLC / Hanuman Corporation				
Date of Inspection	12/04/2019	Start Time	12:30pm		
Inspector's Name(s)	Cassandra Durkin				
Inspector's Title(s)	Environmental Complianc	e Manager			
Inspector's Contact Information	cassandra@inspectionsp	lus.com			
Inspector's Qualifications	CPESC, CESSWI– see ins	pector qualification	page in section 2 of the SWPPP.		
Type of Inspection: ⊠ Regular □ During storm e	vent Post-storm eve	ent			
	Weather Info	ormation			
Has there been a storm event since If yes, provide: Storm Start Date: 11/26/19 - 11/30/1 Weather at time of this inspection Clear Cloudy Rain Other:	9 Approximate Amount	of Precipitation (in):	1.25"		
Have any discharges occurred since the last inspection? No If yes, describe: What did the water look like at the time of the discharge? Clear Partly turbid Very turbid Are there any discharges at the time of inspection? No If yes, describe: What did the water look like at the time of the discharge? Clear Partly turbid Very turbid					
 Is a rain gage installed on site? Yes Where is it located? Hanging on the security fence at the entrance of the site. Has the Rain Event page been filled out? Yes Are there MSDS sheets on site? Yes Where are they located? In the construction trailer Has the SWPPP been signed on the certification page? Yes What companies have signed? Veecon LLC Have the delegation letters been signed? Yes What companies have signed? Veecon LLC Has a delegation of authority been filled out for who is signing the inspection reports? Yes Who is signing the inspection reports? Ken Moore Has the "Chemical On Site" form been filled out? Is there a spill kit on site? Yes Where is it located? In the construction trailer Have they done any training for the supervisors or others? Yes Was the inspector able to train any one on this visit? No Who did you speak with? Missed Ken Moore 					
Are the SWPPP and	Yes The SWPPP	book and inspection	s are located at The construction trailer.		
inspections available on site?			and the construction date.		
	, 				
1. Send inspections to Sam Patel -	Note	S			
 Send inspections to Sam Patel - 2. 	1 aurus 5400 (Wgman.com				
3.					

	Final Stabilization/Termination Checklist.						
1.	Are all soil-disturbing activities complete?	No					
2.	Have all inactive areas of the site not covered by pavement or structure achieved a density of 70% coverage?	No					
3.	Date of Final Stabilization.						
	If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.						
Date	e Construction Stopped	Date Construction	n Resumed				
Mea the S	Site.						

Construction Phasing		
Activity	Current Status	Activity Started / Completed
Installed BMPs	Silt Fence, Stabilized Const Entrance, Portable Toilet, Roll off	Started:
		Completed: 04/10/19
Site Clearing and Grading	In progress.	Started: 04/10/19
		Completed:
Installing Utilities	Continue to be installed	Started: 05/07/19
		Completed:
Building Structure	Vertical construction in progress.	Started: 07/16/19
		Completed:
Paving and Walks		Started:
		Completed:
Final Grading/ Stabilize Site		Started:
		Completed:
Other	Retaining wall in progress	Started: 07/02/19

Site-specific BMPs

• The corrective actions initiated and date completed are in the Corrective Action Log.

	List of BMPs Installed	BMP Installed?	BMP Maintenance Required?	Notes
1	Portable Toilet	Yes	No	
2	Roll off	Yes	No	
3	Silt Fence	Yes	Yes	Repair damaged areas of fence
4	Stabilized Construction	Yes	Yes	Add rock and fluff entrance
	Entrance			
5	Concrete Washout	Yes	No	
6	Mulch Socks	Yes	No	
7				
8				
9				
10				

1	Are the BMPs shown on	Yes	
	the map?		
2	Were there changes to	No	
	the SWPPP?		
3	Has the SWPPP been	No	
	updated?		
4	Were the changes to the	Yes	
	SWPPP implemented		
	within 7 days?		

	New BMPs needed	Notes
1		
2		
3		
4		
5		

Overall Site Issues

A list of corrective actions will be supplied with this inspection.

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
1	Are all slopes and disturbed areas not actively being worked properly stabilized?			Entire site is being worked
2	Are natural resource areas (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?	Yes	No	
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	Yes	Yes	Silt fence needs repair in damaged areas
4	Are discharge points and receiving waters free of any sediment deposits?	Yes	No	
5	Are storm drain inlets properly protected?			Protect the inlets when they are active
6	Is the construction exit preventing sediment from being tracked into the street?	Yes	Yes	Add rock and fluff entrance
7	Is trash/litter from work areas collected and placed in dumpsters?	Yes	No	
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	Yes	No	

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	No	No	
10	Are materials that are potential storm water contaminants stored inside or under cover?	Yes	No	
11	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	No		
12	Has the Site map been updated to reflect current conditions?	Yes	No	The Inspectors and SWPPP book map has been updated.
13	Is the NOI posted	Yes	No	NOI Posting Location: In the construction trailer
14	Were previous corrections made within 7 days of last inspection or before the next storm event?	Yes	No	
15	(Other)			

Wal	Walk through the facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.					
1	Are there any signs of	No				
	hazardous materials					
	being exposed to storm					
	water runoff?					
2	Have there been any	No				
	reportable quantities					
	releases of hazardous					
	materials?					

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name: Cassandra Durkin	Title: CPESC, CESSWI
Signature:	Date: 12/04/2019
SWPPP Management Signature:	Date:

Date: 12/04/2019

Project: TRU by Hilton Hotel

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
1	Ensure there is a spill kit	04/10/19		06/04/19
2	Install a rain gauge	04/10/19		07/02/19
3	Install mulch socks per ECP	04/10/19		05/07/19
4	No new issues at the time of this inspection	05/07/19		05/07/19
5	Re-install the mulch sock at the NW side of the site That was removed by TLC Company	05/21/19		06/04/19
6	No new issues at the time of this inspection	06/04/19		06/04/19
7	No new issues at the time of this inspection	06/18/19		06/18/19
8	The site looked good at the time of this inspection.	07/02/19		07/02/19
9	The trash bin needs to be emptied	07/16/19		08/14/19
10	Repair the silt fence at the SW corner. Need to make sure the silt fence at the SW corner of the site is toed in (bottom of fence is buried 6") and adjust the mulch sock.	07/31/19		08/14/19
11	No new issues at the time of this inspection	08/14/19		08/14/19
12	The site looked good at the time of this inspection.	08/28/19		08/28/19
13	No new issues at the time of this inspection	09/11/19		09/11/19
14	No new issues at the time of this inspection	09/25/19		09/25/19
15	The Trash bins need to be emptied	10/09/19		11/20/19
16	Empty the concrete washout	10/23/19		11/06/19
17	All sediment on Restaurant Ln. Needs to be swept	11/06/19		11/20/19
18	Install silt fence at the Southwest corner of the site to prevent runoff down the street	11/20/19		12/04/19
19	No Corrective Actions at this time, only maintenance			

Ver. 070813

Date: 12/04/2019

Project: TRU by Hilton Hotel

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
SWPPP Man	agement Signature:		Date:	

Ver. 070813