CITY OF ALBUQUERQUE



October 29, 2015

Jay Newell, P.E. Sterling Design Associates, LLC 2009 W. Littleton Blvd. Suite 300 Littleton, CO 80120

RE: Starbucks
4301 San Mateo Blvd. NE
Request Permanent C.O. – Not Accepted
Engineers Stamp Date 2/9/15 (G17D006C)
Certification Dated 10/23/15

Dear Mr. Newell,

Based upon the information provided in your submittal received 10/26/15, this plan cannot be accepted for release of Certificate of Occupancy by Hydrology until the following comments are addressed.

PO Box 1293

Albuquerque

NM 87103

www.cabq.gov

The concrete sidewalk culvert does not have the steel plate top.

- The 2' wide concrete pan from the concrete sidewalk culvert following thru behind the north parking area is missing.
- The 6" curb opening on the west end of the building is missing.
- Justify this course of action or follow the plan which was approved.

If you have any questions, please contact me at 924-3695 or Totten Elliott at 924-3982.

1)+7

Sincerely,

Rita Harmon, P.E.

Senior Engineer, Hydrology

Planning Department

TE/RH C: File