

# CITY OF ALBUQUERQUE



November 4, 2015

Kevin Patton  
Pulte Homes  
7601 Jefferson St NE  
Albuquerque, NM 87109  
[Kevin.Patton@PulteGroup.com](mailto:Kevin.Patton@PulteGroup.com)

Fred Salls  
Salls Brothers Construction  
7301 Reading Ave SE  
Albuquerque, NM 87105  
[fsalls@sallsbrothers.com](mailto:fsalls@sallsbrothers.com)

**Re: Drainage Control Ordinance and NPDES CGP Violations for Erosion and Sediment Control**

**Pulte eNOI - NMR12AR29**

**Salls eNOI - NMR12B878**

Dear Mr. Patton and Mr Salls,

On May 27<sup>th</sup>, 2015, Pulte was notified of missing a section of the BMP at the east end of the project in the Mirehaven Arroyo and that a large amount of sediment had left the construction site. This was mitigated within seven days.

On October 22<sup>nd</sup>, 2015 Pulte was notified of erosion in the Mirehaven Arroyo and that a large amount of sediment was leaving the site at the east end of the project. BMPs in the arroyo were inadequate. This is the same location as the notification on May 27<sup>th</sup>, 2015. In addition to the e-mail Pulte was contacted by phone to discuss possible mitigation efforts.

On October 30<sup>th</sup>, 2015 Pulte and Salls Brothers were notified of the required mitigation and provided a few more days to develop a mitigation plan with a schedule for completion. There has been no response.

The violations to be mitigated are erosion in the construction site and sediment leaving the construction site at the east end of the project.

The above listed violations are to be mitigated within seven days or your non-compliance will be reported to the New Mexico Environment Department, Surface Water Quality Bureau to aid in the determination if this issue is to be forwarded to the EPA.

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality  
Planning Dept.

C: [tim@superiorstormwater.com](mailto:tim@superiorstormwater.com)