

## City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	nformation				
ESC File No.	K09EC	)48C	Project Name:		Sonic 98th and Bluewater			
NPDES Id. No.	NMR10	NMR1005XZ LO			9701 Bluewater Rd NW			
11/2	11/22/2023		Owner		Contractor			
Operator		B&B Merritt Real Estate Group			MIRA Enterprises Inc.			
Contact na	me & title	Ken Merritt			Mike Batteas			
e-mail		kmerritt@merrittgroup.net			mike@miraenterprises.net			
Contact Phone #		480-748-0314			254-632-8060			
COA Inspector		Chancellor English			Start/End Time:	: 11:45am		
	Construction Phase:				g, utilities			
Type of Ir	Type of Inspection:		Regular Storm Event Post Storm		Event >0.25" 311/Complaint Follow Up			
Weath	er at time of i	nspection?	Clea	ır	Temper	ature: ~	55	
	date of last s					11/20/2023		
Item								
			Deficienc	cy/ Correctiv	e Action			
Number								
1	Ground disturbing activities occurred before installation of stormwater controls was complete in							
	violation of CGP Parts 2.1.3 and 2.2.3. Silt fence was partially installed, but missing from the low side of							
	the property where stormwater discharges could occur. A stabilized construction entrance was not							
	installed. Required mitigation: You must complete installation of stormwater controls by the time phase of construction activities has begun per CGP Part 2.1.3. You must also install sediment controls							
							nt controls	
	along any perimeter areas that are downslope from any exposed soil or other disturbed areas per					eas per CGP		
	Part 2.2.3.							
2	There was no posting of permit coverage in violation of CGP Part 1.5. Required mitigation: You must							
2								
	post a sign or other notice of your permit coverage per CGP Part 1.5. The notic							
	visible from th	the public road that is nearest to the active part of the construction site, and it must use a						
	font large enough to be readily viewed from a public right-of-way.							
3	The SWPPP and self-inspection reports were unavailable at the time of inspection in violation of CGP							
5	Parts 4.7.3 and 7.3. Required mitigation: You must keep a copy of all inspection reports and the current							
		-	-			-		
			easily accessible loc	-		made immediate	ely avallable	
	at the time of	an on-site ins	spection per CGP Pa	arts 4.7.3 and	7.3.			
4	Track-out on the road from the missing stabilized construction entrance in violation of CGP Part 2.2.4.							
	Required mitigation: You must minimize sediment track-out and use appropriate stabilization							
	techniques or track-out controls to ensure that sediment removal prior to vehicle exit per CGP Part							
	2.2.4. Where sediment has been tracked-out of your site, remove the deposited sediment by the end of the same business day in which the track-out occurs.							
	the same busi	ness day in w	nich the track-out o	occurs.				
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect			Latest rep		N/A		

Notes:						
Began construction without complete BMP installation.						