## CITY OF ALBUQUERQUE



August 13, 2020

Mike Salvador Buffalo Design Architects 10899 Montgomery Blvd NE, Ste A Address Albuquerque, NM 87111

Re: First Nations Community Healthsource-Vision Clinic 505 Madeira Drive SE Traffic Circulation Layout Architect's Stamp 08-10-2020 (L18-D085)

Dear Mr. Salvador,

Based upon the information provided in your submittal received 08-10-2020, the above referenced plan cannot be approved for Building Permit until the following comments are addressed:

PO Box 1293

You are have 3 motocycle stall requirements but are providing only one stall (4ft x 8ft). Can you explain how you will be able to fit 2 other motorcycles on this one stall?

Albuquerque

2. You are now providing a new 22 ft drivepad with sidewalk behind curb and gutter. How will you provide an ADA 4 ft wide (2%) pathway across entrance? Please provide an explanation and/or detail substantiating this criteria. Please address this issue or call me to further discuss.

NM 87103

- 3. Detail A4 for ADA ramp states 36"minimum width but the minimum width should be 48", please clarify this issue.
- 4. The re-submittal fee will still need to be addressed for this last submittal.

www.cabq.gov

If you have any questions, please contact me at (505) 924-3630.

Sincerely,

Nilo Salgado-Fernandez, P.E. Senior Engineer, Planning Dept. Development Review Services

C: CO Clerk, File