## CITY OF ALBUQUERQUE

Planning Department Alan Varela, Director



Mayor Timothy M. Keller

May 19, 2023

Jesse Macias M3 Design 2008 N 7<sup>TH</sup> Ave Phoenix, AZ 85007

Re: Take 5 Car Wash

10415 Central Ave. NE Traffic Circulation Layout

Engineer's Stamp 05-18-23 (L21-D059B)

Dear Mr. Macias,

The TCL submittal received 05-17-2023 is approved for Building Permit by Transportation. A copy of the stamped and signed plan will be needed for each of the building permit plans. Please keep the original to be used for certification of the site for final C.O. for Transportation.

PO Box 1293

Albuquerque

When the site construction is completed and an inspection for Certificate of Occupancy (C.O.) is requested, use the original City stamped approved TCL for certification. Redline any minor changes and adjustments that were made in the field. A NM registered architect or engineer must stamp, sign, and date the certification TCL along with indicating that the development was built in "substantial compliance" with the TCL. Submit this certification, the TCL, and a completed <u>Drainage and Transportation Information Sheet</u> to the <u>PLNDRS@cabq.gov</u> for log in and evaluation by Transportation.

NM 87103

Once verification of certification is completed and approved, notification will be made to Building Safety to issue Final C.O. To confirm that a final C.O. has been issued, call Building Safety at 924-3690.

www.cabq.gov


15


Sincerely,

Ernest Armijo, P.E. Principal Engineer, Planning Dept.

**Development Review Services** 

C: CO Clerk, File







## **ELEVATION**

### SIGN NOTES: 1. METAL POST TO BE GALVANIZED. ALL BOLTS, NUTS, WASHERS AND SCREWS

- MUST BE RUSTPROOF. 2. CONCRETE FOR FOOTING SHALL BE PORTLAND CEMENT AND HAVE A MINIMUM
- COMPRESSIVE STRENGTH OF 3,000 P.S.I. 3. SIGNS WILL BE FABRICATED BY USING REFLECTING COATING IN THE SYMBOL, MESSAGE AND BORDER APPLIED TO A SHEET ALUMINUM BACKING (.080) IN
- THICKNESS. 4. MESSAGE LETTERING SHALL BE UPPER CASE (WHITE)(SERIES B) 2" HIGH IN ACCORDANCE WITH MANUAL ON UNIFORM TRAFFIC CONTROL DEVICES.
- 5. THE SYMBOL IS COMPOSED OF TWO ELEMENTS, A WHITE WHEELCHAIR FIGURE (WHICH SHOULD ALWAYS FACE RIGHT) ON A SQUARE BACKGROUND,
- INTERNATIONAL BLUE IN COLOR (FED. STD. 595a, COLOR #15180). 6. SIGN POST SHALL BE MIN. 2'-0" CLEAR FROM BACK OF CURB.

## SIGN DETAILS






1. CROSSWALK ALONG AN ACCESSIBLE ROUTE SHALL MAINTAIN A SLOPE OF 2% MAX. IN ALL


# TYPICAL CROSSWALK N.T.S.


Einest Ormijo 5/19/2023

TRAFFIC CIRCULATION


LAYOUT APPROVED











ATEF A. HANNA, PE #27436

TAKE 5 CAR WASH


**NEW MEXICO** CENTRAL & **UBANKS** 

10415 CENTRAL AVE NE, ALBUQUERQUE,

SITE DETAILS

SHEET NUMBER:

C - 8.1



# AND FACILITIES .

# SAFETY WARNINGS & EQUIPMENT INSPECTION


- Owners and installers please note these safety warnings and make use of this checklist on a regular basis.
- Follow installation instructions when erecting equipment
- Ground surfaces around equipment should be restored as needed. Concrete footings should never be exposed. Surface depth should comply with ASTM and CPSC specifications.
- Check for and repair damage caused by wear or vandalism, a major factor in injury causing situations.
- All protruding bolts should be covered or cut off and finished smooth. Sharp edges on pipes should be capped or removed. Check for bent, broken, or severely worn pipe, and replace.
- All equipment should be free of rust and repainted whenever necessary to deter rusting
- We provide our customers with layout sheets and installation instructions. Please keep on file the specifications sheet that contains the listing of every part used.
- Never add components not intended for use with this product.
- Regular maintenance is necessary in this and all park and recreational equipment to insure the safety of the user
- Note: Proper maintenance of equipment requires regular tightening of all bolts, nuts, and setscrews.
- Note: Regular checking of all parts, castings, etc. should be made. If a part is broken or worn, it should be replaced immediately.
- Check to be sure all fittings are tight and that bars and pipes do not move.
- Replace all worn S-hooks. S-hooks must be completely closed. Failure to close S-hooks can result in serious injury to the user. NEVER reuse S-hooks.
- Test for free movement of swing hanger and other moving attached parts.
- Check for worn chains and replace them.


8/14/2017

A soft resilient surface should be placed under all swings extending at least twice the height of the top rail both front and back.

2/4


FIGURE 7.4.115 Bicycle Parking Stall Layout Options







TRAFFIC CIRCULATION
LAYOUT APPROVED

Emest Amijo 5/19/2023










ATEF A. HANNA, PE #27436

CIVIL ENGINEERING
EVELOPMENT ENGINEERS
45 GUNN HIGHWAY
TAMPA, FL 33626

LAND DEV 8345 TA



TAKE 5
CAR
WASH

OF NEW MEXICO CENTRAL & UBANKS

10415 CENTRAL AVE NE, ALBUQUERQUE, NM

SHEET NAME:

SITE DETAILS

SHEET NUMBER:

C-8.2