

City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	formation				
ESC File No. M15E				Veterans Integration Center				
NPDES Id. No.			D5M1 Location:			2701 Mulberry St SE		
1/28/2025		Owner			Contractor			
Operator		NM Veteran Integration Centers			Hart Construction			
Contact name & title		Jerry Becker						
e-mail		jerry@steamaticnm.com						
Contact Phone #		505-991-4708						
COA Inspector		Chancellor English			Start/End Time:	315p	om	
	ction Phase:				addition		1	
	nspection:	Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weathe	er at time of ii	nspection? Clear			Temperature: ~ 57			
Estimated	date of last s	orm 0.25" or greater			11/7/2024			
Item			Defisions					
Number	Deficiency/ Corrective Action							
1	Posting - The permit coverage posting was missing from the site in violation of CGP Part 1.5. Required							
	mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly accessible							
	location in close proximity to the construction site per CGP Part 1.5. The notice must be located so it is							
	visible from the public road that is nearest to the active part of the construction site.							
	SWPPP - The SWPPP and self-inspection reports were unavailable at the time of the inspection in violation of CGP Parts 4.7.3 and 7.3. Required mitigation: You must keep a current copy of your							
	SWPPP and all inspection reports at the site or at an easily accessible location so that it can be made							
	available at the time of an on-site inspection per CGP Parts 4.7.3 and 7.3.							
3								
5	BMPs - The perimeter silt fence needs maintenance around the south and west sides of the property in							
	violation of CGP Part 2.1.4. Required mitigation: Ensure all stormwater controls are maintained and							
	remain in effective operating condition during permit coverage per CGP Part 2.1.4.							
2.1	Discharge off site?	(Y/N)	no	Γ				
4	•	ion Reports		Latest rei	port Date:	N/A		
— —								
Natari								
Notes:								
The general contractor has changed from Jaynes Corporation to Hart Construction. Hart Construction								
will need to include their NOI in the SWPPP.								
				ptied befor	e it can be us	ed again		
The concrete washout pit is full and needs to be emptied before it can be used again.								

Chancellor English