





Work Location

Remove 5 existing bollards

Remove 30 existing bollards
and replace with Corten
guardrail, see attached.

Coal Pl SE

Pine St SE

Remove 35 existing bollards and replace with Approx. 175 LF of corten guardrail

