
| ADMINISTRATIVE AMENDMENT | |
|--------------------------|------------|
| FILE #: | PROJECT #: |
| | |
| | |
| | |
| | |
| APPROVED BY | DATE |



C40-45(2)

CHORD CHORD BEARING TANGENT

157.43 S39°54'19"W

42.31 S77°46'23"W

81.40 N63°31'48"W

92.70 N62°40'20"W

122.41

79.30

16.05

105.86

120.02

29.84

40.94

46.70

) 1

8999174 PLAT MAP FOR

RADIUS

647.96

380.00

380.00

NUMBER

C1 C2

С3

C4 C5 C6

C7

63

ARC

241.94

157.82

32.09

209.85

239.48

46.96

81.56

92.94

RIVERWALK MARKETPLACE

State of New Maarca 1 25 Frinty of Bornellio 1 25 is a stationart was filed for record on

BERNALILLO COUNTY, NEW MEXICO OCTOBER, 1989

10/171000 sing the standard

CURVE DATA

643.69 21°32'07" 240.52 S21°04'19"E

643.69 2°51'22" 32.08 S11°43'56"E 643.69 18°40'45" 208.92 S22°30'00"E 1437.84 09°32'35" 239.21 S37°41'56"W

DELTA

13°57'20"

12°17'49"

14°00'46"

30.00 89°41'27"

| Additiona | 1 R/W |
|------------|-------|
| cated with | the |
| This Plat. | |

* 7

\$

47

LOT 3

°.

¥.

16

1

ۍ م

0

PLAZA DEL NORTE

Filed: April 2, 1982 (C19-115)

Lot 1

QUESTA

SUBDIVISION/ Filed: 3/8/50

DEL RIO

(01-16) Lot 2

T N T T

-Easement for Right-of-Way Filed: October 29, 1973 (Misc. Bk. 338, Pgs. 574-577)

(, °°,

Agreement for Abandonment of Channel Filed: May 13, 1985 (Misc. Bk. 351A, Pgs. 444-454) THAN TH

`°`*)

TANGENT DATA

| 1BER | BEARING | DISTANCE |
|------|--------------|----------|
| [] | S45°51°29"E | 29.05 |
| [2 | S32°38'56"W | 200.02 |
| 13 | S57°21'16"E | 256.14 |
| [4 | S32°55'39"W | 243.72 |
| 5 | N57°22'54"W | 235.07 |
| 6 | S16°03'17"W | 85.92 |
| 7 | N81°08'35"W | 79.47 |
| 8 | S45°51'29"E | 81.03 |
| 9 | \$45°51'29"E | 65.97 |
| 10 | S45°51'29"E | 15.06 |
| 11 | N57°16'53"E | 46.35 |
| 12 | N18°53'44"W | 38.42 |
| 13 | S32°55'39"W | 161.62 |
| [14 | N57°22'54"W | 120.16 |

NMSHC Brass Tablet stamped "NM448-N12"

N.M. State Plane Coordinates (Central Zone) X= 381,108.54 Y= 1.528,910.94 Ground-to-Grid Factor = 0.99967595 $\Delta \propto = -00^{\circ}13^{\circ}46^{\circ}$ Elev. = 5023.411

LEGEND

● Found 1-1/2" Pipe

¢.

S

04

ر°`


*رج*ي.


- Found 5/8" Rebar with yellow plastic survey cap stamped "HUGG LS 5823"
- ◎ Found 3/8" Rebar
- ▲ Found 5/8" Rebar
- Found 3/4" Rebar
- Set 5/8" Rebar with 1-1/4" yellow plastic survey cap stamped "WEAVER LS 6544"
- ⊙ Set P.K. Nail with 1-1/2" aluminum survey washer stamped "WEAVER RLS 6544"
- Found 5/8" Rebar with yellow plastic cap stamped "PE & LS 2455"
- Found Highway R/W T-Rail 488+05.20


SHEET 2 OF 2 SHEETS



JOB ND. 88306.09







| NO. | DATE | DESCRIPTION |
|-----|------|-------------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |



620 24TH STREET OGDEN, UT 84401 BP-ARCHITECTS.NET P **801.394.3033** F 801.394.9064

GENERAL DEMOLITION NOTES:

A. Field verify existing conditions.

- B. Provide miscellaneous demolition required for new construction, whether specifically defined, or not.
- C. Reference engineering sheets for additional demolition requirements. D. Provide temporary bracing and shoring as required for removal of existing walls.
- E. Reference demolition reflected ceiling plans for ceiling demolition requirements not shown on this sheet.
- F. Where a wall is removed, cut back gypsum board to adjoining wall and ceiling surfaces and patch as required for smooth and even finish.
- G. Protect existing materials and finishes to remain from damage.
- H. All noted materials are new, unless noted otherwise.


KEYED NOTES:

- 02.01 Remove existing mop sink/laundry sink, complete. Waste line must be removed to below concrete floor slab and capped - re: plumbing.
- 02.02 Remove portion of existing aluminum storefront system as shown.
- 02.03 Remove existing LVP/vinyl flooring system in this room, complete, including wall base 02.04 Remove existing wood/metal framed partition, complete, including wall base, etc. Protect adjacent materials and finishes from damage.
- 02.05 Remove existing metal door and hollow metal frame, complete.
- 02.06 Remove existing service counter millwork, complete. 02.07 Remove existing salon chairs including sinks and plaumbing. Waste line must be removed to below
- concrete floor slab and capped re: plumbing. 02.08 Remove existing wall mount lavatory and faucet, complete - re: plumbing. Waste line must be
- removed to below concrete floor slab and capped re: plumbing. 02.09 Remove existing floor mount water closet, complete - re: plumbing. Waste line must be removed to
- below concrete floor slab and capped re: plumbing. 02.13 Saw cut and remove existing concrete floor slab as required for new plumbing/electrical work -
- coordinate with plumbing/electrical drawings.
- 02.16 Remove existing clothes washer/dryer and associated mechanical and plumbing systems, complete. 02.17 Remove existing wall mount fire extinguisher.
- 02.18 Remove existing wood door and frame, complete 02.19 Remove all existing restrooms accessories in this room (i.e. grab bars, mirrors, toilet paper
- dispensers, paper towl dispensers, etc.).
- 02.21 Remove existing salon millwork system, complete 02.22 Remove existing floor drain, complete. Waste line must be removed to below concrete floor slab and
- capped re: plumbing.
- 02.23 Remove existing wall shelving system 02.25 Remove existing wood/metal framed partial height partition, complete, including wall base, etc.
- Protect adjacent materials and finishes from damage.
- 02.38 Remove existing electric drinking fountains
- 02.40 Remove existing broadloom carpeting and rubber wall base to location of new demising wall. 02.42 Remove existing electrical panel board - re: electrical

DEMOLITION LEGEND:

| | : Building element to be demolished. | | |
|------------------------------|---|-----|------------|
| | : Existing building element to remain (protect from damage). | | |
| | 1ST LEVEL DEMOLITION FLOOR PLAN | NOF | хтн |
| E OF NEW METICO | 1' = 1'-0", 1/4" = 1'-0" 06.02.21 PERMIT SET Project Number: 2118 | | \bigcirc |
| NO. 6200 and the 06.02.21 | | | |
| STERED ARCHITE | AFCU - ALBUQUERQUE BRANCH 3400 HIGHWAY 528 ALBUQUERQUE, NM | 1. | 1 |







620 24TH STREET OGDEN, UT 84401 BP-ARCHITECTS.NET P **801.394.3033** F 801.394.9064

GENERAL DEMOLITION NOTES:

- A. Field verify existing conditions.
- B. Provide miscellaneous demolition required for new construction, whether specifically defined, or not.
- C. Reference engineering sheets for additional demolition requirements. D. Provide temporary bracing and shoring as required for removal of existing walls.
- E. Reference demolition reflected ceiling plans for ceiling demolition requirements not shown on this sheet.
- F. Where a wall is removed, cut back gypsum board to adjoining wall and ceiling surfaces and patch as required for smooth and even finish.
- G. Protect existing materials and finishes to remain from damage. H. All noted materials are new, unless noted otherwise.

KEYED NOTES:

- Remove portion of existing aluminum storefront system as shown.
 Remove existing metal door and hollow metal frame, complete.
 Existing EIFS system protect from damage
 Existing light fixture to remain protect from damage
 Existing awning system to remain protect from damage
 Existing aluminum storefront system to remain protect from damage

1ST LEVEL F.F. ±0"

DEMOLITION ELEVATIONS


FNEW


ott Pantone Architects. Drawings, written materials and design concepts shall not be used or reproduced in whole or part in any form or format without prior written consent.

1/4" = 1'-0", 1' = 1'-0" 06.02.21 **PERMIT SET** Project Number: 2118

NORTH

D2.1





| NO. | DATE | DESCRIPTION |
|-----|------|-------------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

KEYED NOTES:

| 01.02 03.01 | Line of soffit above shown dashed - Patch and repair existing concrete f |
|----------------|--|
| 03.02 03.03 | room. Install leveling compound as Patch and repair existing concrete f Patch and repair existing concrete f |
| 06.03 06.04 | Millwork - re: millwork details and ir Millwork above shown dashed - re: |
| 06.05 06.14 | Provide 1/2" plywood or metal back Provide solid blocking in the wall to |
| 06.15 08.02 | Owner provided upper cabinet Install new hollow metal door and fr and repair existing EIFS system as r |
| 08.03 08.04 | Interior glazing partition system furn Install new aluminum storefront jam |
| 09.05 | Install new glass seals, etc. as requi Infill existing wood framed exterior p location of demolished storefront/ho of wall to match existing. Skim coal sheathing and exterior EIFS system |
| 09.06 | existing storefront opening to match Contractor to provide Soelberg wall interior elevations for color and joint A1.31. Field verify and cut any ope |
| 09.13 09.15 | shall be cut tio the size of the electr Patch and repair existing gypsum b Patch and repair existing gypsum b room. Skim coat wall to provide sm |
| | |



620 24TH STREET OGDEN, UT 84401 **BP-ARCHITECTS.NET** ₽ 801.394.3033 F 801.394.9064

GENERAL PARTITION NOTES:

FRAMED WALL PARTITIONS

- Partition type indications are independent of applied finishes. See the finish sheets and interior elevations 1. for wall finishes including tile coursing and layout and/or the designations on the plans for additional information regarding applied finishes.
- Where partition type designation on floor plans is interrupted by door opening, glazed partitions, etc., 2. construction above interruption (and where applicable below) is to be the same as that designated for the partition in which the interruption occurred.
- The minimum requirements for construction of each partition type as expressed by the indicated reference are incorporated by reference and are applicable to the work of this project. However, additional and/or more restrictive requirements may be indicated by the specifications and drawings. Such requirements also apply and shall govern such requirements including but are not limited to:
- Use 5/8" thick gypsum board throughout, unless noted otherwise. а.
- Use 16" o.c. max. stud spacing, unless noted otherwise in these documents. The spacing stated by the referenced approval or test report is the max. spacing if allowed in these documents. Use studs of gauge indicated on the drawings or in the specifications. The gauge stated by the referenced approval or test report is the minimum gauge tested. 20 ga (30 mils) is the minimum allowed in these documents.
- 4. Use studs of depth indicated by this set of documents. The depth stated by the referenced approval or test report is the minimum depth allowed in these documents.
- All dimensions are center of stud or rough opening unless noted otherwise. Face of finished wall will be noted as FOW. At all interior walls, the studs, insulation, and gypsum board are to extend to the deck above, unless noted
- otherwise. Wall types not noted are assumed to match adjacent rooms. See sheets for finishes. Notify architect of 7.
- any discrepancies. All metal stud partitions are considered acoustic partitions and are to receive a type 1 sound attenuation
- blanket. Thickness shall match stud depth unless noted otherwise. Provide control joints in metal framed walls at approximately 30 feet on center. Locate at corner above
- doors or inside corner of pilasters or other inconspicuous locations where possible. Consult with architect prior to commencing framing.
- 10. At wall openings for penetration of pipes, ducts, devices, etc. gypsum board is to be cut to match the shape and dimension of the penetrating object and the gap between the object and the wall is to be sealed with acoustical or fire sealant on all sides with a 3/4" joint at all sides maximum. The opening for ducts or large penetrations shall be framed with a header. Add an angled corner brace if the gap exceeds 3" from framing to the opening.
- Contractor to provide blocking/backing for all wall mounted equipment. See floor plans and interior 11. elevations for cabinets, grab bars, etc. Install blocking as detailed or as required to mount such devices. All wood blocking is to be fire retardant treated. Install as per detail 01/A1.2.
 - 12. Where there is limited water exposure: install one layer of 5/8" type X water resistant gypsum board per ASTM C1396 (where gypsum board occurs) of basic partition at the following locations: Within 2 feet horizontally and 4 feet vertically of janitors sinks.
 - At other locations, i.e. toilet rooms, and as indicated on the architectural finish plans and
- elevations. 13. Install one layer of 5/8" glass mat tile backer board in lieu of gypsum board (where gypsum board occurs) of basic partition where there is no fire rating and over gypsum board face layer at fire rated partitions at the following locations.
 - Where ceramic tile finishes are indicated per the finish plans and/or interior elevations.
- At other locations as indicated by the architectural finish plans and elevations. 14. Provide fire blocking in concealed spaces of stud walls and partitions as follows: 1) vertically at the ceiling and floor levels and 2) horizontally at intervals not exceeding 10 feet.
- See detail 03/A1.2 for typical top of wall condition at all stud partitions. 15.
- See detail 02/A1.2 for typical bottom of wall condition at all stud partitions. 16.
- See detail 04/A1.2 for typical fire extinguisher cabinet installation details. 17.

GENERAL ANNOTATED PLAN NOTES:

- A. Field verify existing conditions.
- Where a wall has been removed, cut back gypsum board to adjoining wall and ceiling surfaces and patch as required for smooth and even finish.
- C. Patch and repair all existing gypsum board surfaces at locations of demolition work. Skim coat all existing walls to remain to provide smooth level finish - paint. See demolition plans and engineering sheets for demolition requirements.
- D. Patch and repair existing concrete floor slab as required at location of removed ceramic tile flooring system.
- Install leveling compound as required to level floor for new floor finishes. Patch and repair existing concrete floor slab as required at locations of floor slab saw cuts, demolished floor
- drains, plumbing lines, etc. See demolition plans and engineering sheets for demolition requirements. Provide 1/2" plywood or metal backing behind TV wall locations - re: partition types.
- Provide tactile exit signs meeting the requirements of ICC A117.1 at all exterior egress doors.

- re: reflected ceiling plan

- floor slab as required at location of removed flooring system in this as required to level floor for new floor finishes.
- floor slab as required at location of floor slab sawcut. floor slab as required at location of demolished floor drain.
- interior elevations.
- : millwork details and interior elevations.
- king behind TV wall locations re: partition types. support Owner provided upper cabinets
- frame in existing wall opening paint. Re: door schedule. Patch
- required. rnished and installed by Owner's Vendor.
- mb to match existing at location of removed storefront framing. uired for a complete storefront installation.
- partition with wood framing and batt insulation to match existing at nollow metal door system. Install 5/8" gypsum board at inside face at wall to provide smooth level finish - paint. Install plywood wall n to match existing @ exterior. Paint existing EIFS adjacent to
- h new EIFS. I covering on this wall - re: finish schedule for product data and nt layout. Maintain 1/2" reveal at walls and ceilings - re: detail 09/
- benings required for electrical devices in Soelberg panels. Openings trical device faceplate. board as required at location of demolished wall - paint.
- board as required at location of demolished wall finishes in this mooth level finish - paint.



09.21 Install sound batt insulation and 5/8" gypsum board over existing metal stud wall framing - re: finish schedule. Install 5/8" gypsum board to bottom of metal roof decking - paint. 09.22 Install sound batt insulation and 1/2" plywood wall sheathing over 5/8" gypsum board over existing metal stud wall framing - re: finish schedule. Install 5/8" gypsum board to bottom of metal roof decking - paint. Install plywood wall sheathing to 10'-0" above finish floor elevation.

09.18 Infill existing wood framed exterior partition with wood framing and batt insulation to match existing at

location of demolished storefront system. Install 5/8" gypsum board at inside face of wall to match

existing. Skim coat wall to provide smooth level finish - paint. Install plywood wall sheathing and

Paint existing EIFS adjacent to existing storefront opening to match new EIFS. Re: detail 06/A1.2.


exterior EIFS system to match existing @ exterior - re: exterior elevations. Coordinate opening dimensions with ATM supplier. Install stainless steel flashing around ATM wall opening where occurs.

- 10.01 Semi-recessed fire extinguisher cabinet with fire extinguisher re: detail 02/A1.2. Basis of design: JL Industries FE10 extinguisher with JL Industries 1015G17 with safety lock cabinet. 10.03 Provide tactile exit signs meeting the requirements of ICC A117.1 at exterior egress door.
- 10.06 48" tall stainless steel corner guard
- 11.01 Refrigerator (N.I.C.) provided by Owner's Equipment Contractor
- 11.02 Microwave (N.I.C.) provided by Owner's Equipment Contractor 11.03 Wall mounted LCD screen (N.I.C.) - by Owner. Contractor to coordinate exact location with Owner
- and Architect re: electrical and equipment plan. 11.06 Cash recycler machine (N.I.C.) - provided by Owner's Equipment Contractor - re: equipment plan.
- Contractor to coordinate installation with millwork. 11.08 ATM machine (N.I.C.) - provided by Owner's Equipment Contractor - re: equipment plan. Coordinate rough opening dimensions in exterior wall with Owner's Equipment Contractor. Re: detail 06/A1.2 for
- stainless steel flashing at opening. 11.09 Cash safe (N.I.C.) - provided by Owner's Equipment Contractor - re: equipment plan.
- 22.01 Electric water cooler re: plumbing. Provide stainless steel wall panel behind water coolers. NORTH 22.04 Mop sink - re: plumbing.
- 26.03 Electrical panel re: electrical
- **1ST LEVEL ANNOTATED PLAN**

1' = 1'-O'', 1/4'' = 1'-O''06.02.21 **PERMIT SET** Project Number: 2118

AFCU - ALBUQUERQUE BRANCH 3400 HIGHWAY 528 ALBUQUERQUE, NM








620 24TH STREET OGDEN, UT 84401 BP-ARCHITECTS.NET P **801.394.3033** F 801.394.9064

KEYED NOTES:

tt Pantone Architects. Drawings, written materials and design concepts shall not be used or reproduced in whole or part in any form or format without prior written consent.



Existing EIFS system - protect from damage
Existing light fixture to remain - protect from damage
Existing awning system to remain - protect from damage
Existing aluminum storefront system to remain - protect from damage
New EIFS system to match existing - paint to match adjacent existing EIFS system.
Install new hollow metal door and frame in existing wall opening - paint. Re: door schedule. Patch

and repair existing EIFS system as required.
 O9.05 Infill existing wood framed exterior partition with wood framing and batt insulation to match existing at location of demolished storefront/hollow metal door system. Install 5/8" gypsum board at inside face

09.18 Infill existing wood framed exterior partition with wood framing and batt insulation to match existing at location of demolished storefront system. Install 5/8" gypsum board at inside face of wall to match existing. Skim coat wall to provide smooth level finish - paint. Install plywood wall sheathing and

Paint existing EIFS adjacent to existing storefront opening to match new EIFS. Re: detail 06/A1.2. 10.05 Building mounted exterior sign by Owner. Provide electrical power as per electrical drawings.

11.08 ATM machine (N.I.C.) - provided by Owner's Equipment Contractor - re: equipment plan. Coordinate

rough opening dimensions in exterior wall with Owner's Equipment Contractor. Re: detail 06/A1.2 for

exterior EIFS system to match existing @ exterior - re: exterior elevations. Coordinate opening dimensions with ATM supplier. Install stainless steel flashing around ATM wall opening where occurs.

existing storefront opening to match new EIFS.

stainless steel flashing at opening.

of wall to match existing. Skim coat wall to provide smooth level finish - paint. Install plywood wall

sheathing and exterior EIFS system to match existing @ exterior. Paint existing EIFS adjacent to

EXTERIOR ELEVATIONS

1/4" = 1'-0", 1" = 40' 06.02.21 **PERMIT SET** Project Number: 2118

AFCU - ALBUQUERQUE BRANCH 3400 HIGHWAY 528 ALBUQUERQUE, NM

