

SURVEYOR'S INSPECTION REPORT CONT.

- 7) Specific physical evidence of boundary lines on all sides found all property corners excepting the most westerly corner basis of inspection report
- 8) Is the property improved? (if structure appears to encroach or appear to violate set back lines, show approximate distance) property is improved, see sketch
- 9) Indications of recent building construction, alterations or repairs: none apparent



10) Approximate distance of structures from at least two lines must be shown. see sketch

NOTE: Improvement locations are based on previous property surveys. No monuments were set. This tract is subject to all easements, restrictions and reservations of record which pertain. This report is not to be relied on for the establishment of features, buildings or other future improvements.

[Signature]
SURVEYOR N.M.F.S. NO. 7002

The above information is based on boundary information taken from a previous survey and may not reflect that which may be disclosed by a boundary survey.

SKETCH
(THIS IS NOT A BOUNDARY SURVEY)
(THIS SURVEY MAY NOT BE USED BY A PROPERTY OWNER FOR ANY PURPOSE)



This map/plat/LR is being furnished as an aid in locating the herein described Land in relation to adjoining streets, natural boundaries and other land, and is not a survey of the land depicted. Except to the extent a policy of title insurance is expressly modified by endorsement, if any, the Company does not insure dimensions, encroachments, distances, location of easements, acreage, or other matters shown thereon.