

× ×	General Information			
Project Name and Location	on notas la Ballows Fresh Pkny			
	San Mater a Ballown Fresh Play			
Site Contact Name & Agency	Fradbuy Stone ESC File No. BIBEO 21			
Date of Inspection	12-19-17 Start/End 9-20/9:30			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Describe Present Phase of Construction	Stabili Zd			
Type of Inspection: Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up			
	Weather Information			
Weather at time of this inspecti	Temperature: ~F° Rain · Sleet · Fog · Snowing · Windy			
Has there been a storm event si	nce the site was Permitted? · Yes · No			
Amount: • < \\dag{1}/4\'' 1/4\'' \to \\dag{7}	4" · > 34" · Snow"			
	Erosion & Sediment Control Inspection			
Entrance / Track-Out	///			
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	Stablized			
Erosion Controls				
Housekeeping/Pollutant Control	ols grand, pards, hydramich			
Debris/Pollutants/Sediment in Notes	AS4			
Is site being maintained in compliance	the with the Drainage Ordinance? Fee No Signature 12 19-11 Date			

From: Sent: Lloyd, James <James.Lloyd@nmgco.com> Tuesday, December 19, 2017 11:07 AM

To:

Cherne, Curtis

Subject:

FW: Metro 12 inch construction site inspection

Attachments:

IMG_0656.jpg; IMG_0658.jpg

Hello Curtis, We have completed construction near I 25 and Rio Bravo. We are going to be reseeding that area soon. Just letting you know of our progress.

Thanks,

James Lloyd

From: Lloyd, James

Sent: Tuesday, September 26, 2017 2:25 PM **To:** 'Cherne, Curtis' < <u>CCherne@cabq.gov</u>>

Subject: RE: Metro 12 inch construction site inspection

Hello Curtis,

The items requiring attention have been addressed. Track out has been swept except in the extreme middle of the road and sandbags were removed. The hot mix asphalt bags were put in place of the sandbags (not pictured) but they were there when I left this afternoon. Track out pad is being installed today 1 load of gravel.

Thanks,

James Lloyd
Sr. Environmental Scientist
James.Lloyd@nmgco.com
New Mexico Gas Company
7120 Wyoming Blvd, Suite 20
Mail Stop BC-22
Albuquerque, NM 87109
Desk: (505) 697-3438

Desk: (505) 697-3438 Cell: (505) 239-9771 Fax: (505) 697-4481



From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Monday, September 25, 2017 2:35 PM
To: Lloyd, James < James.Lloyd@nmgco.com >

Cc: 'Grant Morrison' < grant@inspectionsplusinc.com Subject: Metro 12 inch construction site inspection

From:

Sent:

Cherne, Curtis Tuesday, December 19, 2017 3:55 PM 'Tim Tolbert'

To:

Subject:

NM Mutual Home Office Construction Site Inspection

Tim, Good afternoon. Finally made it out there. Site looked great.

Thanks,

Curtis Cherne, PE, QCIS Principal Engineer **Stormwater Quality** COA 505-924-3420



	General Information	
Project Name	NM MUTUAL HOME OFFICE	
and Location	NM MUTUAL HOME OFFICE San make of Balling Freik Pku	
Site Contact Name & Agency	BRADBURY STAM M ESC File No. B18,000/	
Date of Inspection	11-15-17 Start/End 8.45/9:15	
Inspector Name, COA Dept.	Stanice "Totten" Elliot Stormwater Quality	
Describe Present Phase of Construction	LANDSCAPING GOING IN, BLDG 90% COMP.	
Type of Inspection: ✓ Regular □ During store	rm event Post-storm event (> 0.5 inch) 311 / Complaint Response Follow-Up	
	Weather Information	
Weather at time of this inspect		
	ince the site was Permitted? Ses No	
Amount: $\Box < \frac{1}{4}$ " to $\frac{3}{4}$ " to $\frac{3}{4}$	√4" □ > 3/4" □ Snow"	
	Erosion & Sediment Control Inspection	
Entrance / Track-Out EM	MANCES PAVED	
Sediment Controls / Silt Fence, NO SEDIMENT BMP ON WEST AND EAST Inlet Protection, Wattles, etc. & SOUTH EDGE		
Erosion Controls Housekeeping/Pollutant Controls WASHOOT IN HONT OF BLDG.		
South of get he The agrees to have	MS4 CCATION brd: 11-15-17, west edge and east edge to be by drown the land on the by drown the land of the by drown the land of the by drown the land of the lan	

From:

Tim Tolbert <ttolbert@bradburystamm.com>

Sent:

Thursday, July 06, 2017 3:00 PM

To:

Cherne, Curtis

Cc:

Tim Slatunas W Green Globe; Liz Wehrli


Subject:

5201Balloon Fiesta silt repair

Curtis,

From you site inspection yesterday, we filled where the silt fence had some washout beneath it. Let me know if you needed anything else.

Thank you,



Tim Tolbert | Superintendent Bradbury Stamm Construction...since 1923

7110 2nd Street NW | Albuquerque, NM 87107

Main: 505.765.1200 | Fax: 505.842.5419 | Mobile: 505.264.8318

ttolbert@bradburystamm.com | www.bradburystamm.com

ECS File: <u>B18E021</u>



N. I.				
	General Information			
Project Name and Location	San Makeo a Ballow Frida Pkuy			
Site Contact Name & Agency	Bradbury Stans Contact Phone #/ E-mail			
Date of Inspection	7-5-17 Start/End 1/:15			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	Budg whoo			
Type of Inspection:				
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up			
	Weather Information			
Weather at time of this inspect	ion? Temperature: ~F° Rain • Sleet • Fog • Snowing • Windy			
Has there been a storm event s Amount: • < 1/4" • 1/4" to 3	ince the site was Permitted? • Yes • No '4" • > 34" • Snow"			
	Erosion & Sediment Control Inspection			
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 	· ·			
• Erosion Controls / Mulch, Seed,				
Housekeeping/Pollutant Controls Ok				
• Debris/Pollutants/Sediment in MS4				
Notes 5 pola al 7m				
Is site being maintained in compliance with the Drainage Ordinance? Yes No Signature 7-5-17 Date				

ECS File: B181502



Mar					
	General Information	An .			
Project Name and Location	No mufaet Hem	Office			
Site Contact Name & Agency	In Tothat	Contact Phone #/ E-mail			
Date of Inspection	2-21-17	Start/End 12:35/ 12:50			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction	Construction Bldg				
Type of Inspection:					
Regular	rm event • Post-storm event (> 0.5 inch)	• 311 / Complaint Response Follow-Up			
	Weather Information				
Weather at time of this inspect	ion?	Temperature: ~_60 F°			
clear Cloudy	Rain • Sleet • Fog • Snowing	• Windy			
	ince the site was Permitted? · Yes · N				
Amount: • < 1/4" • 1/4" to 3					
	Erosion & Sediment Control In	respection			
Entrance / Track-Out	Entrace New Maintain - Efrait 28	frechout 15 Mines			
 Sediment Controls / Silt F Check Dams, Waddles 	9 / 9				
 Erosion Controls / Mulch 	, Seed,				
Housekeeping/Pollutant C	Controls mitigator certir p	ohlu			
 Debris/Pollutants/Sedime 	nt in MS4				
Notes Green	Olde is her ance/	of and Separi 15			
dring the	14				
Is site being maintained in complian	nce with the Drainage Ordinance ? Yes No	Signature Date			

From:

tim@superiorstormwater.com

Sent:

Tuesday, February 07, 2017 6:02 PM

To:

Cherne, Curtis

Subject:

RE: NM Mutual SWPPP inspection

Curtis,

I met with Tim Tolbert on site today and went over these issues. He said the he wold get them taken care of.

Tim Slatunas, CESSWI, CISEC Superior StormWater Services, LLC.

Office: 505-433-3693 Fax: 505-433-3697 Cell: 505-353-2558

tim@superiorstormwater.com www.superiorstormwater.com

----- Original Message -----

Subject: NM Mutual SWPPP inspection

From: "Cherne, Curtis" < CCherne@cabq.gov>

Date: Tue, February 07, 2017 8:44 am

To: "ttolbert@bradburystamm.com" <ttolbert@bradburystamm.com> Cc: "tim@superiorstormwater.com" <tim@superiorstormwater.com>

Tim,

Good morning.

I went out to the site yesterday for a follow-up inspection.

The track-out pad still needs maintenance (issue reported last time). I saw the broom onsite and there was no track-out on the street, which is why this is an "issue" e-mail rather than a violation letter.

My biggest concern is the Lake Country and Geothermal trucks dripping hydraulic fluid into the soil. I only took two picks, but there were more leaks. They should fix their trucks and/or provide an acceptable drip pan. Contaminated soil should be removed and disposed of properly.

Thanks,
Curtis Cherne, PE, QCIS
Principal Engineer
Stormwater Quality
COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: BIBE021



N SOLD						
	General Information					
Project Name	NM mertad Hom	n Offici				
and Location	San mater & Ballon Frike PKWY					
Site Contact Name & Agency	Bradbury Stenn					
Date of Inspection	2-6-17 Start/End 11:90					
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One					
Describe Present Phase of Construction	Constructors Bldg					
Type of Inspection:						
Regular	rm event • Post-storm event (> 0.5 inch) • 3	311 / Complaint Response · Follow-Up				
	Weather Information					
Weather at time of this inspection? Temperature: ~50 F°						
		Windy				
Has there been a storm event s Amount: • < 1/4" • 1/4" to 3	ince the site was Permitted? Yes No 'A" > 34" Snow"					
Erosion & Sediment Control Inspection						
■ Entrance / Track-Out	grack of ped news ma					
 Sediment Controls / Silt F Check Dams, Waddles 	s, etc. <u>U/C</u>					
Erosion Controls / Mulch, Seed, ND Lake country Irolly rise leaking oil into						
* Housekeeping/Pollutant Controls 9ev Humil						
• Debris/Pollutants/Sediment in MS4 _ ~ U						
Notes has b	roum un site					
Is site being maintained in compliance with the Drainage Ordinance? Yes No Signature Date						

From:

Cherne, Curtis

Sent:

Tuesday, February 07, 2017 8:45 AM

To: Cc: ttolbert@bradburystamm.com tim@superiorstormwater.com

Subject:

NM Mutual SWPPP inspection

Attachments:

hydraulic_fluid.jpg; hydraulic_fluid2.jpg; track-out_pad.jpg

Tim,

Good morning.

I went out to the site yesterday for a follow-up inspection.

The track-out pad still needs maintenance (issue reported last time). I saw the broom onsite and there was no track-out on the street, which is why this is an "issue" e-mail rather than a violation letter.

My biggest concern is the Lake Country and Geothermal trucks dripping hydraulic fluid into the soil. I only took two picks, but there were more leaks. They should fix their trucks and/or provide an acceptable drip pan. Contaminated soil should be removed and disposed of properly.

Thanks,
Curtis Cherne, PE, QCIS
Principal Engineer
Stormwater Quality
COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: <u>B/9E02/</u>



N F N						
		General Info		,	1	
Project Name	un mutual Home Office					
and Location			Su Ma	had.	B416	on Fush pul
Site Contact Name & Agency	Tin o	rollows shows show	Man	Contact Pho E-mail	one #/	brodbuy Stom. a
Date of Inspection	1-17-17 Start/End 9:3179:50					25/2:50
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One					
Describe Present Phase of Construction	5/ab pours					
Type of Inspection:						
Regular During stor	m event	est-storm event (>	• 0.5 inch) • 3	11 / Complain	t Resp	onse • Follow-Up
		Weather Inf	ormation			
Weather at time of this inspect		• Fog • Sn	owing • '	Windy	Tem	perature: ~ <u>\$6</u> F°
Has there been a storm event si						
Amount: • < 1/4" • 1/4" to 3	<u>4" </u>		Snow"			
	Eros	ion & Sediment (Control Inspec	tion		
■ Entrance / Track-Out	fractous	- out pad	entrare	1411	M	untur
 Sediment Controls / Silt F Check Dams, Waddles 	ence,	-out pas	rus m	an run		
Erosion Controls / Mulch,	, Seed,					
Housekeeping/Pollutant Controls						
Debris/Pollutants/Sedime	nt in MS4			•		
· Notes Sph al 77n of Brad buy Stenn - told his						
he will ru	V H Su	vey Street	t of	MIJ SU	45	Cam to day
Is site being maintained in compliar	nce with the Drain	age Ordinance ? • `	Yes No Sig	gnature	a C	hen 1-17-D Date

ECS File: <u>818 E021</u>



The state of the s				
	General Information			
Project Name and Location	San mater and Ballion Fresh Pkay			
Site Contact Name & Agency	Bradby Stann Contact Phone #/ Ctable of E-mail bradhun Stone w			
Date of Inspection	10-24-14 Start/End 7130 /2:45			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction Type of Inspection:	grading			
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up			
	Weather Information			
Has there been a storm event s	Rain · Sleet · Fog · Snowing · Windy			
	Erosion & Sediment Control Inspection			
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 				
 Erosion Controls / Mulch 				
 Housekeeping/Pollutant C 	Controls OV			
■ Debris/Pollutants/Sedime	ent in MS4			
• Notes				
Is site being maintained in complian	nce with the Drainage Ordinance?* (Yes)* No Signature 10-34-16 Date			