



August 26, 2020

CONSTRUCTION NOTES							
<ol style="list-style-type: none"> ① EXISTING SIDEWALK ② SIDEWALK CONSTRUCTED AS PART OF WORK ORDER ③ DEFERRED SIDEWALK 							

LEGEND	
■	EXISTING SIDEWALK
■	SIDEWALK PART OF WORK ORDER
■	DEFERRED SIDEWALK

HUITT-ZOLLARS
 Huitt-Zollars, Inc.
 Albuquerque, New Mexico 87110
 Phone (505) 883-8114 Fax (505) 883-8022

SCALE 1" = 100'

Call before you dig. Dig safely. Dig right.
811 OR 725-1500

NOVUS PROPERTIES, LLC
 FOUNTAIN HILLS PLAZA SUBDIVISION

SIDEWALK MISSING LINK

City Project No: **5844.87**
 Zone Map No: **C-12Z-C-13Z**
 Sheet **10** of **47**

ENGINEER'S SEAL		SURVEY INFORMATION		BENCH MARKS		AS BUILT INFORMATION	
		FIELD NOTES		FOUND MONUMENT "9-C12"		CONTRACTOR DATE	
		NO.	BY	DATE	STANDARD 3 1/4" ALUMINUM DISC		WORK STAKED BY DATE
					NEW MEXICO STATE PLANE COORDINATES (CENTRAL ZONE-N.A.D. 1983)		INSPECTOR'S ACCEPTANCE BY DATE
					N=1 521 648.218		FIELD VERIFICATION BY DATE
					E=1 512 571.253		DRAWINGS CORRECTED BY DATE
					ELEV=5127.378 (NAVD 1988)		MICRO-FILM INFORMATION
					GROUND TO GRID FACTOR=0.999677378		RECORDED BY DATE
					MAPPING ANGLE=0°14'47.46"		NO.

DESIGN REVISIONS			
NO.	DATE	REMARKS	BY

DESIGNED BY: GM	DATE: August 26, 2020	
DRAWN BY: LRT	DATE: August 26, 2020	
DWG NAME: 10_SW Missing Link.dwg	PROJ #: R307202.01	
CHECKED BY: SAE	DATE: August 26, 2020	