ECS File: DIVEOSYA



	General Information						
Project Name and Location	Santa Manci Apts 5E com Duicksa an	1 Sun Pedro					
Site Contact Name & Agency	Brian Patterson Titan Doneluput	Contact Phone #					
Date of Inspection	9-29-16 Start/End 7:20/2:40						
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality						
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov						
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One						
Describe Present Phase of Construction	Stapiliza						
Type of Inspection:							
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 31	11 / Complaint Response • Follow-Up					
	Weather Information						
Weather at time of this inspect • Clear • Cloudy • 1 Has there been a storm event s Amount: • < 1/4" • 1/4" • 3	Rain · Sleet · Fog · Snowing · Vince the site was Permitted? · Ves · No	Temperature: ~60_F° Windy					
	Erosion & Sediment Control Inspect	tion					
• Entrance / Track-Out	NIA						
 Sediment Controls / Silt F Check Dams, Waddles 	. ///-						
 Erosion Controls / Mulch 	• •						
 Housekeeping/Pollutant C 	Controls 01C						
 Debris/Pollutants/Sedime 	nt in MS4						
• Notes							
Is site being maintained in complian	ice with the Drainage Ordinance ? 71 es - No	Cut c Che 4-28-11, gnature Date					

From: Grant Morrison <grant@inspectionsplusinc.com>

Sent: Tuesday, October 06, 2015 2:20 PM

To: Cherne, Curtis

Subject: RE: Automatic reply: SWPPP violations Broadstone Promenade

Curtis

We swept Derickson ave at Broadstone but the landscapers are removing dirt for final grading and we will clean that up again when they are out of the way. Probably Thursday.

I just wanted you to know it is being taken care of but it is a daily issue right now.

Thanks

Grant Morrison

Inspections Plus, Inc 4382 Alexander Blvd NE Albuquerque, NM 87107 Cell 505-489-5077 Off 505-344-9410

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Monday, October 05, 2015 8:44 AM

To: Grant Morrison < grant@inspectionsplusinc.com >

Subject: Automatic reply: SWPPP violations Broadstone Promenade

I will return on Wednesday October 7th.

No virus found in this message. Checked by AVG - www.avg.com

Version: 2015.0.6140 / Virus Database: 4435/10763 - Release Date: 10/05/15

From: Grant Morrison <grant@inspectionsplusinc.com>

Sent: Monday, October 05, 2015 8:44 AM

To: Cherne, Curtis

Cc: 'Brian Patterson'; 'Gabriel Asbury'; kburger@allresco.com

Subject: RE: SWPPP violations Broadstone Promenade

Curtis

Part of this was cleaned up last week and we should have the remainder cleaned up by end of day today or first thing tomorrow morning.

Grant Morrison
Inspections Plus, Inc
4382 Alexander Blvd NE
Albuquerque, NM 87107
Cell 505-489-5077
Off 505-344-9410
-----Original Message-----

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Friday, October 02, 2015 2:15 PM

To: 'jaddison@allresco.com' < <u>jaddison@allresco.com</u>> Cc: <u>grant@inspectionsplusinc.com</u>; Brian Patterson

(bpatterson@Titan-Development.com) < bpatterson@Titan-Development.com>;

'kburger@allresco.com' < kburger@allresco.com> Subject: SWPPP violations Broadstone Promenade

John,

I gave you a call earlier.

Not all of my photos went through. This is enough to get the picture.

As you are aware, a follow-up inspection is to be conducted. It is a large site. Please be thorough.

Curtis

NPDES Tracking No: MR 2 AY23

ECS File: DIBEOSYA



M.E. Sanda							
	Genera	I Information					
Project Name and Location	Brondsden Prime San Pedro and	oricking	ESC PERM	IT#			
Site Contact Name & Agency	Bob Finch. Allance Residute	ed Company	Contact Pho	one#	486-431-077		
Date of Inspection	10-12-15		Start/End 7:40 /10:30				
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality						
Inspector Phone / E-mail	505-924-3420/ccherne@ca	abq.gov					
Inspector Qualifications	Stormwater USA						
Describe Present Phase of Construction	fine graded	, 6/tgs w	har 1	nstei	They landscapery		
Type of Inspection:							
Regular · Drive-By/R	andom • During storm o	event • Post-stor	m event •	311/0	Complaint Response		
	Weathe	r Information					
Weather at time of this inspect	ion? Rain · Sleet · Fog	· Snowing	High Winds		perature: ~ 76 F°		
Hasthan haan a storm avent s	nce the site was Permitted	? • Yes • No					
Has there been a storm event since the site was Permitted? · Yes · No Amount: · < 1/4" · 1/4" · > 3/4" Intensity: · Light · Med. · Hvy. · Snow"							
Erosion & Sediment Control Inspection							
Check any BMPs that ha	ve FAILED or REQUIRE	MAINTENANCE					
Entrance / Off Tracking	OŁ						
Sediment Controls / Silt F Check Dams, Waddles					Andrews and the Property		
Erosion Controls / Mulch	Seed,O						
• Wind Blown Erosion	VO	<i>t</i>					
 Housekeeping / Pollutant 	Controls Way	better, ho	1 m	Conc	rele washout		
· au me paint	dunping soto	e. Ahle drash					
Is site being maintained in complia	nce with Const. Gen. Permit ?"		gnature	hn	71/13-13 Date		

From:

Cherne, Curtis

Sent:

Monday, October 12, 2015 1:46 PM

To:

Brian Patterson (bpatterson@Titan-Development.com); jaddison@allresco.com;

'bfinch@allresco.com'; kburger@allresco.com

Cc:

grant@inspectionsplusinc.com

Subject:

SWPPP follow-up Boradstone Promenade

Good afternoon,

I got the chance to talk to Bob on site today and thank him for the efforts in this past week of cleaning up the site. The effort was enough to de-escalate the situation.

I let Bob know of a few more things he still needed to do.

Curtis Cherne, PE Stormwater Quality Engineer COA

From: Sent: John Addison jaddison@allresco.com Wednesday, September 23, 2015 9:58 AM

To:

Cherne, Curtis

Cc: Subject: Gabriel Asbury
RE: Broadstone Promenade SWPPP inspection

Curtis

Please include Gabe Asbury and myself on future inspection reports so that we may take care of any issues.

Thank you

John Addison Project Manager

Alliance Residential Company 2415 E Camelback Rd Ste 600 Phoenix, Az 85016 602-812-4538 Direct 602-377-3219 Cell 602-957-1003 Fax

jaddison@allresco.com www.ollresco.com

From: Brian Patterson [mailto:bpatterson@Titan-Development.com]

Sent: Wednesday, September 23, 2015 7:37 AM

To: John Addison

Subject: FW: Broadstone Promenade SWPPP inspection

From: Brian Patterson

Sent: Wednesday, September 23, 2015 8:36 AM

To: 'Gabriel Asbury' <gasbury@allresco.com'>; Josh Rogers <<u>irogers@titan-development.com</u>'> **Cc:** 'Asa Nilsson-Weber' <<u>asaw@iacivil.com</u>'>; Kurt Browning <<u>kbrowning@titan-development.com</u>>

Subject: FW: Broadstone Promenade SWPPP inspection

Gabe/John,

I received this email below from the City regarding their SWPPP inspection that took place on September 22nd and there are numerous items that need to be corrected. See items below as well as photos.

Brian

From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Tuesday, September 22, 2015 3:33 PM

To: Brian Patterson < boatterson@Titan-Development.com >; Asa Nilsson-Weber (asaw@iacivil.com)

<asaw@iacivil.com>; grant@inspectionsplusinc.com Subject: Broadstone Promenade SWPPP inspection

Hello,

CITY OF ALBUQUERQUE

October 2, 2015

John Addison Alliance Residential Builders 2415 Camelback Rd Ste 600 Phoenix, AZ 85016 jaddison@allresco.com

Re: SWPPP Violations-Numerous-See list below eNOI NMR12AY23

Dear Mr. Addison,

On September 23rd, 2015 you were notified of the following violations at Broadstone Promenade:

- 1. Lots of trash all over the site.
- 2. Sediment in Derickson St.
- 3. Sidewalk culvert on San Pedro was unprotected and there was sediment leaving the site.
- 4. Mortar mess in the middle of the site. (mitigated)
- 5. Sediment in drive aisle at the north entrance not protected from entering the street.
- 6. Refer to e-mail dated 9-23-15 for additional items.

PO Box 1293

We met and walked the site and discussed the above listed violations on 9-22-15.

Albuquerque

The site was visited on 10-1-15 and similar violations were observed. In addition, the site was not posted per paragraph 1.5 of the CGP and a large milky-covered puddle was observed east of the pool area as well as sediment in Derickson St. related to the landscaping work.

New Mexico 87103

The above listed violations (including list in 9-23-15 e-mail) are to be mitigated within seven days or your non-compliance will be reported to the New Mexico Environment Department, Surface Water Quality Bureau to aid in the determination if this issue is to be forwarded to the EPA.

www.cabq.gov

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

C: grant@inspectionsplusinc.com

kburger@allresco.com

bpatterson@titan-development.com

ECS File: D'OEOSYA



	General Information					
Project Name and Location	Broadstar Rrumode San Podro and Dricksur Juhn Addisir	ESC PERMIT	#			
Site Contact Name & Agency	John Addison. Allance Residential Buildes	Contact Phone # 602-377 - 32				
Date of Inspection	10-1-15	Start/End //:///90				
Inspector Name, COA Dept.	Curtis Cherne, St	ormwater Quali	ty			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Stormwater USA					
Describe Present Phase of Construction	Bedos Vertical, fine 5	redel				
Type of Inspection: Regular · Drive-By/Random · During storm event · Post-storm event · 311 / Complaint Response						
	Weather Information					
	Rain · Sleet · Fog · Snowing ·		Cemperature: ~ F° Other:			
Has there been a storm event s Amount: • < 1/4"	ince the site was Permitted? · Kes · No '4" · > 34" Intensity: · Light · Me	ed. • H vy.	• Snow"			
Erosion & Sediment Control Inspection						
Check any BMPs that h	ave FAILED or REQUIRE MAINTENANCE					
Entrance / Off Tracking	reed maintanne					
 Sediment Controls / Silt I Check Dams, Waddles 		alk culus	b aul 'erdni			
Erosion Controls / Mulch, Seed,						
• Wind Blown Erosion	NO 1		1 1			
Housekeeping / Pollutant	Controls Luts of drash,	convit	washert			
	has	2				
Is site being maintained in complia	ance with Const. Gen. Permit ? Yes	Int G	Date			

NPDES Tracking No: 1 P12 AD0 |

ECS File: 1) 1 E & SYA



Maria							
	General Information						
Project Name and Location	Broad stone Primode, Sure Pedro and Dericksu	ESC PERMIT #	_				
Site Contact Name & Agency	Broad Stone Primode Smit Prdro and Dericksu Brian Postfusun Titan Dovelynt	Contact Phone #	990-0163				
Date of Inspection	/6-1-13 Start/End Time						
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality						
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov						
Inspector Qualifications	Stormwater USA						
Describe Present Phase of Construction	Blass vertical, for grain	lut, Landscup.	worken for				
Type of Inspection: Regular · Drive-By/Random · During storm event · Post-storm event · 311 / Complaint Response							
	Weather Information						
Weather at time of this inspect	ion? Rain · Sleet · Fog · Snowing ·		perature: ~F°				
I .	ince the site was Permitted? · Yes · No 4" · > 34" Intensity: · Light · Me	ed. • Hvy.	• Snow"				
Erosion & Sediment Control Inspection							
	ave FAILED or REQUIRE MAINTENANCE						
• Entrance / Off Tracking enhance Meds manhall							
Sediment Controls / Silt Fence, ned watth at 5 duh culwit and Check Dams, Waddles, etc. at north endrum							
Erosion Controls / Mulch, Seed,							
■ Wind Blown Erosion _	oll	. 1					
Housekeeping/Pollutant Controls Wash of drash, controle wash-out sed my in sheet me in inter-							
Is site being maintained in complic	ince with Const. Gen. Permit ? "Yes "(No)	wo che	16-1-1				
is site being maritained in compila		ignature	Date				

From: Cherne, Curtis

Sent: Monday, June 01, 2015 2:35 PM

To: 'Brian Patterson'

Cc: grant@inspectionsplusinc.com

Subject: RE: Santa Monica Place-Erosion Sediment Control Plan

Attachments: derickson-inlet.jpg; san-pedro-recently-swept.jpg; sediment-ada-ramp.jpg; small-

sedimentation-pond.jpg

Brian.

Promenade just had a couple things. The City was sweeping San Pedro when I was there. There was more sediment on the street yesterday.

At the northwest corner, the little sedimentation pond is ...uh...little. It's a low spot, so I'm thinking you're losing some sediment in this spot. A waddle may help.

Good talking to you.

Thanks for staying on top of it.

Curtis Cherne, PE Stormwater Quality Engineer 924-3420

From: Brian Patterson [mailto:bpatterson@Titan-Development.com]

Sent: Monday, June 01, 2015 2:22 PM

To: grant@inspectionsplusinc.com; Asa Nilsson-Weber

Cc: Cherne, Curtis; Kurt Browning

Subject: Santa Monica Place-Erosion Sediment Control Plan

Grant/Asa,

I just got off the phone with Curtis Cherne and he was asking if we have a Sediment Control Plan for <u>Santa Monica Place</u> <u>Public Infrastructure Improvements</u>. I believe that we do because we have BMP's in place at the site. If we do, can you send Curtis a pdf copy so he can include it in the file?

Brian Patterson

Development Project Manager



(O) 505-998-0163 (M) 505-934-3344

bpatterson@titan-development.com | www.titan-development.com

From:

Pete Montalvo <pmontalvo@allresco.com>

Sent:

Monday, June 01, 2015 4:41 PM Brian Patterson; Gabriel Asbury

To: Cc:

Cherne, Curtis; grant@inspectionsplusinc.com; Kurt Browning; John Addison

Subject:

RE: Santa Monica Place-Erosion Sediment Control Plan

Grant

Can you get this done tomorrow? Touch base with Gabe or myself.

Thanks

Sent from my Verizon Wireless 4G LTE Tablet

----- Original message -----

From: Brian Patterson < bpatterson@Titan-Development.com >

Date:06/01/2015 4:05 PM (GMT-07:00)

To: Gabriel Asbury <gasbury@allresco.com>, Pete Montalvo pmontalvo@allresco.com>

Cc: "Curtis Cherne (CCherne@cabq.gov)" < CCherne@cabq.gov>, grant@inspectionsplusinc.com, Kurt

Browning < kbrowning@titan-development.com >

Subject: FW: Santa Monica Place-Erosion Sediment Control Plan

Gabe/Pete,

Please see email below from the City. Overall, the City is very happy with the site and your quick response to resolve any issues. They did note a very minor issue at the northwest corner where some runoff has occurred. Would a waddle on our end help? Thoughts?

Brian

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Monday, June 01, 2015 2:35 PM

To: Brian Patterson

Cc: grant@inspectionsplusinc.com

Subject: RE: Santa Monica Place-Erosion Sediment Control Plan

Brian,

Promenade just had a couple things. The City was sweeping San Pedro when I was there. There was more sediment on the street yesterday.

At the northwest corner, the little sedimentation pond is ...uh...little. It's a low spot, so I'm thinking you're losing some sediment in this spot. A waddle may help.

Good talking to you.

Thanks for staying on top of it.

Curtis Cherne, PE



	General Information	
Project Name and Location	Broadstone Promenate San Pedro and DerickSon	ESC PERMIT #
Site Contact Name & Agency	Brian Patterson Titan Darryment	Contact Phone # 998 - 6/63
Date of Inspection		Start/End 18:35 11:00
Inspector Name, COA Dept.	Curtis Cherne, S	tormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov	
Inspector Qualifications	Stormwater USA	
Describe Present Phase of Construction	buildes wall and builder	1
RegularFollow-Up	Random • During storm event • Post-sto	rm event • 311 / Complaint Response
	Weather Information	
Weather at time of this inspect	tion? Rain · Sleet · Fog · Snowing ·	Temperature: ~ 7.5 F
Has there been a storm event s Amount: < 1/4" (1/4") to	since the site was Permitted? · Yes · No 34" · > 34" Intensity: · Light · M	ed. • Hvy. • Snow"
	Erosion & Sediment Control Inspe	ection
Check any BMPs that h	ave FAILED or REQUIRE MAINTENANCI	3
 Entrance / Off Tracking 	500	
 Sediment Controls / Silt Check Dams, Waddle Erosion Controls / Mulch 	5, etc. Sidinal Leaving 50	Shill - Sodified on Son
 Wind Blown Erosion 	NO	
Housekeeping / Pollutani	Controls <u>Small</u> amount of	drash
· City struct	t sweeps went by on.	South Putro
Is site being maintained in compli	ance with Const. Gen. Permit ? Yes (N)	Gut-Ch G-2-U Signature Date

ECS File: DIE ESSAA



	General Information						
Project Name and Location	Brond Stone Santa Mancer Jan Robos Prickers Bron lattoan Lee Filey 5.6 Sup	ESC PERMIT #					
Site Contact Name & Agency	Brion lattoan Lee Frieg 5. b SUL	Contact Phone # 948-0167					
Date of Inspection	9-23-15 Start/End 9:45/10245						
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality						
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov						
Inspector Qualifications	Stormwater USA						
Describe Present Phase of Construction	Fire graded interior schut.	s built, blds burbed					
Type of Inspection:	1. During atoms and a Post at	orm event • 311 / Complaint Response					
• Regular • Drive-By/R	andom • During storm event • Post-sto	offit event 5117 Complaint Response					
Janes Sp	Weather Information						
Weather at time of this inspect		Temperature: ~ 7 f					
	Rain · Sleet · Fog · Snowing ·	•					
Has there been a storm event since the site was Permitted? · Yes · No Amount: · < 1/4" · 1/4" to 1/4" · > 3/4" Intensity: · Light · Med. · Hvy. · Snow"							
Erosion & Sediment Control Inspection							
Check any BMPs that ha	ave FAILED or REQUIRE MAINTENANCI	$\mathbf{\underline{\varepsilon}}$					
Entrance / Off Tracking							
* Sediment Controls / Silt Fence, Check Dams, Waddles, etc. walther regis a varous locatus, So Lind Cearing Eil							
Erosion Controls / Mulch, Seed,							
• Wind Blown Erosion							
· Housekeeping / Pollutant Controls Lots of drash, murlan wash out							
· ask ubout posting sign?							
Is site being maintained in complia	nnce with Const. Gen. Permit ?* Yes No	Curb Clar 9-23-11 Signature Date					

From:

Cherne, Curtis

Sent:

Tuesday, September 22, 2015 3:33 PM

To:

Brian Patterson (bpatterson@Titan-Development.com); Asa Nilsson-Weber

(asaw@iacivil.com); grant@inspectionsplusinc.com

Subject:

Broadstone Promenade SWPPP inspection

Attachments:

trash3.jpg; trash-pile.jpg; trash2.jpg; mortar-mess.jpg; concrete-washout.jpg

Hello.

I visited Broadstone Promenade for a SWPPP inspection today.

The issues were numerous, but I will begin with:

- 1. The large amount of trash on the site. If it isn't the trashiest I've ever seen it is a close runner-up.
- 2. Sediment in Derickson.
- 3. Sediment pile and trash in the cattle guard inlet. Should clean that while the traffic control is in place.
- 4. Sediment is leaving the site through the entrance on Derickson. A wattle should be place at the security fence inside.
- 5. The sidewalk culvert on Derickson near San Pedro was unprotected and there is a large unprotected dirt slope right next to it as well as extending far to the east.
- 6. Mortar mess in the middle of the site.
- 7. Concrete washout and trash in the material laydown area.
- 8. The rundown leading to San Pedro should have inlet protection/wattle.
- 9. There was sediment in the drive area and a dirt pile that was eroding towards the rundown. A smaller wattle (3"??) may work best here as it can trap sediment, yet allow high flows to go over it.

I did get the chance to discuss some of this with Lee and Gabe. Please remind them that mitigation time is 7 days and due to the condition of the site I have to go back.

The amount of pictures will require two e-mails.

Curtis

From:

Cherne, Curtis

Sent:

Tuesday, September 22, 2015 3:34 PM

To:

Brian Patterson (bpatterson@Titan-Development.com); Asa Nilsson-Weber

(asaw@iacivil.com); grant@inspectionsplusinc.com

Subject:


Attachments:

more pics promenade

sediment-needs-wattle.jpg; sediment-pile-in-inlet.jpg; concrete-washout-trash.jpg; sdwk-

culvert-wattle.jpg; sdwk-culvert-wattle2.jpg; sediment-derickson.jpg

Curtis



CONTROLS

PROJECT BONDARY

PROJECT BONDA TO BE DETERMINED

CONSTRUCTION TRA

STAGING AREA CONSTRUCTION TRAILER
STAGING AREA
CONCRETE WASHOUT
FORT-O-LET OUTFALL BTAKE DOWN IF USED. 100

ASLIGIUMI Brian

Lec Riley

Cabe ashu-1

NOTES

HAP IS NOT TO SCALE

RECEIVING MATERS

RIG Grande

RIG Grande

RIG Misso to Most

E NO

Santa Monica

ONUE: Del Rey investments LLC

OPERATOR: Sells Brothers Construction inc.

DATE: February 21, 2012

From:

Cherne, Curtis

Sent:

Tuesday, September 22, 2015 3:37 PM

To:


Brian Patterson (bpatterson@Titan-Development.com); Asa Nilsson-Weber (asaw@iacivil.com); grant@inspectionsplusinc.com posting sign-didn't see it

Subject:

Almost forgot.

I didn't see the posting sign as required per paragraph 1.5 of the CGP. If I missed it, please let me know where it is.

Curtis



You are here: Permits Landing Page 2012 CGP 2012 CGP Details

2012 Construction General Permit eNOI Detail

Quick Jump to Other **Permits**

Details for NMR12AD01

General Information

Project / Site Name: **Current Status:** Tracking Number: Permit Type:

Santa Monica selling as Broadstone Santa Monica

Active NMR12AD01

NOI



Is your project/site located in Indian Country Lands? Are you requesting coverage under this NOI as a 'federal operator' as defined in Appendix A?

No



Bob Finch Assistant Superintendent

7400 San Pedro NE Albuquerque, NM 87109

p 480.431.0771 e bfinch@allresco.com

Operator Information

Operator's Name: Street: City: State: Zip Code: Point of Contact Name:

Phone Number: Operator Email:

IRS Employer Identification Number (EIN):

Broadstone Santa Monica, LLC

6300 Riverside Plaza Lane, NW, Suite 220

Albuquerque New Mexico 87120 **Kurt Browning** 505-889-3061

kbrowning@titan-development.com

505-837-1061 371665428

Project / Facility Information

Project / Site Name:

Street: City: State: Zip Code:

Project / Facility on Indian Land?

Reservation Name:

Santa Monica selling as Broadstone Santa Monica

7311 Louisiana Blvd. NE

Albuquerque New Mexico 87109 No N/A

Additional Project Information

Feedback

Is your project an 'emergency-related project' as defined in Appendix

A?

Have stormwater discharges from your project/site been covered

previously under an NPDES permit?

Estimated Project Start Date: 10/05/2012 11/30/2013 Estimated Project End Date Have earth-disturbing activities commenced on your project/site?

County or Similar government subdivision:

Yes Bernalillo

Yes

Latitude and Longitude Information

Longitude: -106.5688 Longitude Unit: N/A 35.1627 Latitude: N/A Latitude Unit:

Microsoft Streets & Trips Latitude / Longitude Data Source:

Horizontal Reference Datum Unknown Estimated Area to be Disturbed (to the nearest quarter acre): 20

Chemical Treatment Information

Will you use polymers, flocculants, or other treatment chemicals at your construction site?

ESA

Under which criterion listed in Appendix D are you eligible for coverage under this permit?

Provide the basis for criterion selection selected: 1) Any federal listed species and/or designated habitat located in your Silvery Minnow, Southern Willow Flycatcher, Black Footed Ferret

2) The distance between your site and the listed species or designated 5.3 critical habitat (in miles):

C. Federally-listed threatened or endangered species or their designated critical habitat(s) are likely to occur in or near your site's "action area," and your site's discharges and dischargerelated activities are not likely to adversely affect listed threatened or endangered species or critical habitat. This determination may include consideration of any stormwater controls and/or management practices you will adopt to ensure that your discharges and discharge-related activities are not likely to adversely affect listed species and critical habitat. To make this certification, you must include the following in your NOI: 1) any federally listed species and/or designated habitat located in your "action area"; and 2) the distance between your site and the listed species or designated critical habitat (in miles). You must also include a copy of your site map with your NOI. U.S Fish and Wildlife Service or National Marine Fisheries Service

SWPPP Point of Contact

Will Carter Name:

Organization Name: Broadstone Santa Monica, LLC 505-889-3061 Phone: 505-837-1061 Fax:

kbrowning@titan-development.com Email:

Discharge Information

Does your project/site discharge stormwater into a Municipal Separate Yes

Storm Sewer System (MS4)?

Are there any surface waters within 50 feet of your project's earth

disturbances?

Feedback

If a TMDL has been approved or established, identify the title or reference of the TMDL document:

EPA Watershed Assessment, Tracking & Environmental Results

Impaired Surface Waters to Which you Discharge

Surface water(s) to which you discharge

Impaired Water Listed Water Pollutant(s)

Tier 2, 2.5 or 3

Source

TMDL Name and Pollutant

Rio Grande

Yes

PATHOGENS;

EPA website

Historic Preservation

Is your project/site located on a property of religious or cultural significance to an Indian tribe? Are you installing any stormwater controls as described in Appendix E that require? (Appendix E, Step 1): If yes, have prior surveys or evaluations conducted on the site have already determined historic properties do not exist, or that prior disturbances have precluded the existence of historic properties?

(Appendix E, Step 2):

N/A

If no, have you determined that your installation of subsurface earthdisturbing stormwater controls will have no effect on historic properties? (Appendix E, Step 3):

N/A

If no, did the SHPO, THPO, or other tribal representative (whichever applies) respond to you within the 15 calendar days to indicate whether the subsurface earth disturbances caused by the installation of stormwater controls affect historic properties? (Appendix E, Step 4) If yes, describe the nature of their response:

N/A

N/A

Certifier Information

Name: Title:

Email:

Certified Date:

Kurt Browning VP of Development

kbrowning@titan-development.com

09/21/2012

Preparer Information

Name: Phone: Fax:

Organization:

Email:

Rene A Hartman 505–344–9410 505–344–9864 Inspections Plus, Inc. rene@inspectionsplusinc.com

Corresponding Documents

File Name	File Size	File Section	Date Uploaded	Download
Santa Monica Rec Waters.pdf	240115	ESA Section	21-SEP-12	Download
Del Rey – Santa Monica SWPPP Map.pdf	1658920	ESA Section	21-SEP-12	Download

1 - 2

Back to Search Results



release 1.3

					^
			(Av.		



Development & Building Services Division

City of Albuquerque

Planning Department

velopment & Building Services Division

OWNER

Sediment Control (FECG) To

Erosion and Sediment Control (ESC) PERMIT APPLICATION

ESC plans and permits are required for any new development and redevelopment site with 1-acre or more of land disturbing area, including projects less than 1-acre that are part of a larger common plan of development.

	REV 02/2013)
Project Name: Broadstone Promenade	City ESC #:
Date of Application: July 10, 2017	Start Date:
Applicant Name: Del Rey Investments TSM II, LLC	
eNOI #:	
fi .	
Project Address: Derickson Ave and San Pedro Blvd NE	
Number of Project Acres: 9.2	Number of Disturbed Acres: 9.2
General Purpose of Land Disturbing Activity: Multi family house	
Operator (Person with day-to-day Control of activities occ	urring at the construction site): Company: Alliance Residential Builders
Address: 2415 Camelback Rd Pheonix, AZ	Company:
Call Fix	E-mail: kburger@allresco.com
	E-mail: Noting El (Ballies Co. Com)
Owner Information:	
Name: Will Carter	Company: Del Rey Investments TSM II, LLC
Address: 6300 Riverside Plaza Ln NE Ste 200 , Albuquerqu	Je, NM 87120
Office Phone: 505-998-0163 Cell Pho	ne: Pax:
al'III	E-mail: wcarter@titan-development.com
Owner Signature:	Date: 7-11-14
of any kind arising directly or indirectly out of commission by the Applic	he City, its officers, and employees harmless from any and all claims, damages or suits cant, or any employee, agent, assign, contractor or subcontractor of the Applicant, in Es General Permit and/or City Stormwater Permit.
To be completed by the City Staff:	
Permit Fee (based on size of Project):	Permit No:
	Signature:
Termination Date: Name:	Signature:
Responsible Party After Termination of This Permit:	
eNOI # for the reponsible Party:	Permit No: