July 7, 2017



Copy: Mike Hontas, mhontas@daskalosdi.com

Site: Andalucia



Dear Mr. Daskalos,

The following violations were observed at today's inspection:

- 1. Trash and sediment in gutter of Mirandela St.
- 2. Inlet protection for both inlets in Mirandela St require maintenance.
- 3. Trash not in a trash receptacle and trash receptacle not observed onsite.
- 4. No BMP on south side of site; west of entrance.

#### Photos are shown below:

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Sediment and trash in Mirandela St.



Sediment and trash in Mirandela St.

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Sediment and trash near site entrance.



Trash

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



More trash.



No sediment BMP and sediment spilling into street.

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Inlet protection requires maintenance.



### Required mitigation:

- 1. Remove trash and sediment from project side of Mirandela St. from Coors Blvd to inlet near Montano Blvd.
- 2. Perform maintenance on inlet protection for both inlets in Mirandela St.
- 3. Bring in a trash receptacle(s).
- 4. Remove trash from entire site.
- 4. Install a sediment BMP along Mirandela St. on the south side of the site west of the entrance per approved Erosion and Sediment Control Plan.

If the violations are not mitigated within 30 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you would like to schedule a follow-up inspection at a day and time of your convenience, prior to 30 days from the date of this letter please let me know.

PO Box 1293

Albuquerque

If you have any questions, you can contact me at 924-3420.

Sincerely,

Centr a Cheme

New Mexico 87103

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

www.cabq.gov