## CITY OF ALBUQUERQUE



June 9, 2016

David Soule, PE Rio Grande Engineering 1606 Central SE Suite 201 Albuquerque, NM 87106

RE: HLP Endodontics

10429 Lagrima Del Oro NE Requested for Permanent C. O. – Not Accepted Engineers Stamp Date 6/29/15 (F21D063) Certification dated: 6-2-16

Dear Mr. Soule,

Based on the certification provided in your submittal received 6/2/2016, the above referenced site cannot be accepted for release of Certificate of Occupancy by Hydrology until the following comments are addressed:

PO Box 1293

Albuquerque

- Both 1'-0" curb openings on the north end are missing.
- There is a transformer where the pond at the NE corner was approved. New drainage flows are not as-built on the drawing.
- Only a portion of the rock plated slope w/ retention trench is constructed on the west side. Per the superintendent on site, the portion not constructed is being changed to a retaining wall. This has not been as-built on the drawings.
- The SO-19 sidewalk culvert should be poured monolithic. Culvert should be 2'-0" however it only measures 1'-4".

New Mexico 87103

An inspection by our office will need to take place after these corrects are made.

www.cabq.gov

If you have any questions, you can contact me at 924-3986 or Totten Elliott at 924-3982.

Sincerety,

Abiel Carrillo, P.E.

Principal Engineer, Planning Department Development and Review Services

TE/AC

C: email, Cordova, Camille C.; Miranda, Rachel; Sandoval, Darlene M.; Blocker, Lois