

City of Albuquerque Stormwater Construction Site Inspection Report

ESC File No. G11E067F Project Name: Olive Garden on Coors NPDES Id. No. NIMR10060d LOCation: 3823 Coors Boulevard NW 5/5/2025 Owner Contractor Operator Olive Garden Holdings, LLC JK Builders Contact name & title Robert Ricketts Tommy Elmore e-mail rricketts@darden.com telmore@jkbuilder.com Contact Phone # 407-245-5183 615-970-0969	
NPDES Id. No. NMIR10060d Location: 3823 Coors Boulevard NW 5/5/2025 Owner Contractor Operator Olive Garden Holdings, LLC JK Builders Contact name & title Robert Ricketts Tommy Elmore e-mail rricketts@darden.com telmore@jkbuilder.com	
5/5/2025 Owner Contractor Operator Olive Garden Holdings, LLC JK Builders Contact name & title Robert Ricketts Tommy Elmore e-mail rricketts@darden.com telmore@jkbuilder.com	
Operator Olive Garden Holdings, LLC JK Builders Contact name & title Robert Ricketts Tommy Elmore e-mail rricketts@darden.com telmore@jkbuilder.com	
Contact name & title Robert Ricketts Tommy Elmore e-mail rricketts@darden.com telmore@jkbuilder.com	
e-mail rricketts@darden.com telmore@jkbuilder.com	
Contact Phone # 407-245-5183 615-970-0969	
COA Inspector James Hughes Time 10AM	
Construction Phase: vertical	
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up	
Weather at time of inspection? Cloudy Temperature: ~ 50	
Estimated date of last storm 0.25" or greater 5/4/2025	
ltem	
Deficiency/ Corrective Action	
1 Posting - CGP coverage was not posted so it is visible from the public road nearest to the active part	of the
construction site, using a font large enough to be readily viewed from a public right-of-way in violation	on of
CGP 1.5. Required Mitigation : You must post a sign or other notice of your permit coverage at a safe	
publicly accessible location in close proximity to the construction site. The notice must be located so it is	
visible from the public road that is nearest to the active part of the construction site, and it must use	a font
large enough to be readily viewed from a public right-of-way per CGP 1.5.	
large chough to be readily viewed norma public right of way per cor 1.5.	
2 SWPPP - The OWNER's Certification and inspection reports were missing. Required mitigation: The S	WPPP.
including the SWPPP Map, Self Inspection Reports, and Corrective Action Reports, must be kept up-to-date	
per CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3 and 7.3. If an on-site location is unavailable to	keep
the SWPPP when no personnel are present, notice of the plan's location must be posted near the ma	in
entrance of your construction site CGP 7.3.	
3	
4	
2.1 Discharge off site? (Y/N) no	
4 Self Inspection Reports OK Latest report Date: missing	
Notes: This inspection was conducted the day after a 0.30" rain but no discharge.	
The SWPPP is in the connex.	

City of Albuquerque Stormwater Inspector Signature and date: Contact information: James Hughes jhughes@cabq.gov

05/05/2025 James D. Hughes