CITY OF ALBUQUERQUE

Planning Department Brennon Williams, Director



Mayor Timothy M. Keller

May 11, 2022

Courtney Lynch Development Management Group, LLC 4209 Gallatin Pike Nashville, TN 37216

Re: Chase Bank - ATM
2529 San Mateo NE
Traffic Circulation Layout
Architect's Stamp 04-29-2022 (H17-D049)

Dear Ms. Lynch,

Based upon the information provided in your submittal received 05-09-2022, the above referenced plan cannot be approved for Building Permit until the following comments are addressed:

Menaul driveway (adjacent to proposed ATM):

PO Box 1293

- The driveway/pad width/dimension will need to be provided.
- A 15'R instead of 5'R should be provided for better turning movement of vehicles.

Albuquerque

 Provide length from edge of existing drivepad to pavement marking text 'Do Not Enter' to ensure adequate queue length is met.

2. Keyed Note 7:

NM 87103

- The 'Do Not Enter' sign will need to be on both sides of the exit lane.
- Sign Face detail for Stop sign (R1-1) and Do Not Enter sign (R5-1) needs to be added to details.

www.cabq.gov

3. Keyed Note 11:

- The pavement marking text 'Do Not Enter' detail needs to be added.
- Provide complete details for proposed pavement markings.

4. Keyed Note 19 (New Curb & Gutter):

- Ususally a 6" curb is used on internal site, please verify that your proposed detail doesn't impact/compromise the integraty of existing curbing.
- If need be please provide transition back to existing curbing.
- Provide a detail on how the proposed c&g connects onto the existing Menaul drivepad to avoid any safety conflict with sidewalk (pedestrian pathway across driveway/pad).
- 5. **Keyed Note 24:** A Stopping Sight Distance and/or Intersection Sight Distance will need to be provided at San Mateo drivepad from the intersection of San Mateo/'Menaul due to the proposed Landscaping.

CITY OF ALBUQUERQUE

Planning Department
Brennon Williams, Director



Mayor Timothy M. Keller

Sincerely

- 6. You will need to provide a One Way sign (include sign face detail) prior to the entrance of ATM drive thru lane. Location should be near the 18'-5"/6'-0" dimension line shown on sheet A-1.
- 7. A copy of receipt for Resubmittal fee's paid (\$75+tax) will need to be provided
- 8. Please provide a letter of response for all comments given.

If you have any questions, please contact me at (505) 924-3630.

Nilo Salgado-Fernandez, P.E. Senior Traffic Engineer, Planning Dept. Development Review Services

PO Box 1293

C: CO Clerk, File

Albuquerque

NM 87103

www.cabq.gov