

Cherne, Curtis

From: Rodriguez, Jason T.
Sent: Thursday, October 16, 2014 7:43 AM
To: Cherne, Curtis
Subject: RE: 9th street and Tijeras SW

Curtis I was off yesterday and there is a sidewalk culvert also on the project and the inlet is in the southwest corner, I could not get a picture of it.

Jason

From: Cherne, Curtis
Sent: Wednesday, October 15, 2014 12:32 PM
To: Rodriguez, Jason T.
Subject: RE: 9th street and Tijeras SW

Jason,

Your e-mail discusses an inlet penetration while your picture is of a sidewalk culvert???

Curtis

From: Rodriguez, Jason T.
Sent: Thursday, October 09, 2014 11:49 AM
To: Cherne, Curtis
Cc: Harmon Rita T.; hross@tlcplumbing.com
Subject: 9th street and Tijeras SW

Hi Curtis I was out at 816 Tijeras SW (J14-D114) met with Wayne form TLC and inspected the inlet penetration and side walk culvert they are a pass if you need any more let me know thanks.

Jason Rodriguez C.O.A. Storm Maintenance
Office 505-857-8607
Cell 505-235-8016
E-mail jtrodriguez@cabq.gov