

Work Location

An aerial photograph of a parking lot. A red circle highlights a small concrete curb island in the center of the lot. To the left of the island is a parking area with several cars. To the right is a large white building with a flat roof. The surrounding area is filled with trees, some with autumn-colored leaves. A red text box is overlaid on the left side of the image.

Remove existing ~20' concrete curb island, replace with 3" thick SP-C ACHM over compacted 6" subgrade.











