




Imagery ©2020 Maxar Technologies, NMRGIS, U.S. Geological Survey, USDA Farm Service Agency, Map data ©2020 200 ft

🕒 7400 Cienega Road Northwest Albuquerque, NM

🕒 Santa Fe Village Park Bogart Street Northwest, Albuque...

Remove and replace two damaged bollards.

Remove and replace all damaged/displaced sidewalk stones.

Adjust pull box to grade.


12/11/2020 10:52







12/11/2020 10:52



12/11/2020 10:52



12/11/2020 10:53