



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	A10E002A	Project Name:	Seville Subdivision		
NPDES Id. No.		Location:	Brookline Dr. NW		
6/28/2021	Owner			Contractor	
Operator	John R. DeBassige				
Contact name & title	John R. DeBassige				
e-mail	jrdebassige@yahoo.com				
Contact Phone #	505-710-3775				
COA Inspector	Doug Hughes	Start/End Time:	11am		
Construction Phase:	earthwork/grading				
Type of Inspection:		Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	cloudy		Temperature: ~	43	
Estimated date of last storm 0.25" or greater	1/1/2022				
Item Number	Deficiency/ Corrective Action				
1	None				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	N/a	Latest report Date:	12/29/2021	

Notes:	Inactive site, vertical not started yet.

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Doug hughes (505) 924-3420
jhughes@cabq.gov