



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	A10E010	Project Name:	SAMS Academy		
NPDES Id. No.	NMRT004DC	Location:	6441 Ventura Rd. NW		
4/20/2022	Owner		Contractor		
Operator	RM SAMS, LLC				
Contact name & title	Steve Nacamura				
e-mail	Steve@dmcnm.com				
Contact Phone #	228-1401				
COA Inspector	Doug Hughes			3pm	
Construction Phase:	plumbing				
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	Clear		Temperature: ~	88	
Estimated date of last storm 0.25" or greater	3/23/2022				

Item Number	Deficiency/ Corrective Action			
1	NPDES permit coverage wasn't posted. You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to the construction site per CGP 1.5.			
2	The SWPPP was not available onsite when requested. The SWPPP must be kept up-to-date and available onsite per CGP 7.1. If an on-site location is unavailable to keep the SWPPP when no personnel are present, notice of the plan's location must be posted near the main entrance of your construction site CGP 7.3.			
2.1	Discharge off site? (Y/N)	no		
4	Self Inspection Reports	requested	Latest report Date:	?

Notes:	
SF and CE installed, no sediment	

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Doug Hughes (505) 924-3420
jhughes@cabq.gov

4/21/2022
James D. Hughes