



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	McMahon Lots				
Location:	5750 Mc Mahon				
Site Contact Name & Agency	Don - Wilger	ESC File No.	A11E011I		
	don@wilger.com	NPDES Id. No.	NMR1002NB		
Inspection Date:	06/18/20	Start/End Time:	1150/1210hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:					
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	83*
Estimated date of last storm 0.25" or greater	6/1/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 6/20/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 06/18/20