

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Bright Shine Carwash (McMahon Carwash)						
Location:		McMahon & Unser						
Site Contact Name &		Larry - PJ Development		ESC File No.	A11E016A			
Agency		pat@pidev.net		NPDES Id. No.		NMR1001SK		
Inspection Date:		11/19/19 Start/End Time: 12		250/1310hrs				
	water Inspector							
Construction Phase:		site work vertical						
Type of Inspection: x		Regular Storm Event		Post Storm Event >0.25" 311/Complaint Follow Up				
Weath	er at time of i	nspection?	on? Cloudy			Temperature: ~ 64*		
Estimated	date of last s	torm 0.25" o	r greater		10/4/2019			
Item								
	Deficiency/ Corrective Action							
Number								
1	The concrete washout facility requires maintenance. Please clean.							
	additionally there is washout on the adjacent property. Mitigate all washout and cementous waste.							
2.1	Discharge off site?	(Y/N)	No					
4	-	tion Reports		Latest re	port Date:	11/7/20	019	
	•	•			•			

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155 or