## **Development & Commercial Stormwater Construction Site Inspection Report**

General Information				
Project Name	McMahon Carwash			
Owners/Operators Name	LBJ Enterprises / PJ Dev	elopment, Inc.		
Date of Inspection	12/04/19	Start Time	12:30pm	
Inspector's Name(s)	Cassandra Durkin			
Inspector's Title(s)	Environmental Compliance	e Manager		
Inspector's Contact Information	cassandra@inspectionspl	us.com		
Inspector's Qualifications	CPESC, CESSWI – see ins	spector qualification p	page in section 2 of the SWPPP.	
Type of Inspection:  ☐ Regular ☐ During storm ev	vent Post-storm eve	nt		
	Weather Info	ormation		
<ul> <li>5. Have the delegation letters</li> <li>6. Has a delegation of author the inspection reports? Pa</li> <li>7. Has the "Chemical On Sit</li> <li>8. Is there a spill kit on site?</li> <li>9. Have they done any traini</li> <li>10. Was the inspector able to</li> </ul>	stime of the discharge? Classite? No Where is it located on the certification page is been signed? Yes Where is it located on the certification page is been signed? Yes Where is it located? No Where is it located? In gor the supervisors or of train any one on this visit?	High Winds  ear Partly turbited?  ey located?  Yes What companies have so is signing the inspectation.  thers? No No Who did you special parts of the second	□ Partly Cloudy  d □ Very turbid  d □ Very turbid  panies have signed? LBJ Enterprises igned? PJ Development, Inc. etion reports? Yes Who is signing	
Are the SWPPP and inspections available on site?	No The SWPPP I	book and inspections	are located at Unknown.	
<ol> <li>Send inspections to Pat Joseph -</li> <li>3.</li> </ol>	Notes pat@pjdev.net	3		

	Final Stabilization/Termination Checklist.						
1.	Are all soil-disturbing activities complete?	No					
2.	Have all inactive areas of the site not covered by pavement or structure achieved a density of 70% coverage?	No					
3.	Date of Final Stabilization.						
	If construction ceases on the site for more t	han 14 days, the sit	e must be stabilized until construction resumes.				
Date	e Construction Stopped	Date Construction	n Resumed				
Mea the S	Site.						

Construction Phasing		
Activity	Current Status	Activity Started / Completed
Installed BMPs	Silt fence, Portable Toilet, Concrete washout	Started: 02/06/19
		Completed:
Site Clearing and Grading	In progress	Started: 02/06/19
		Completed:
Installing Utilities	Continue to be installed	Started:
		Completed:
Building Structure	Interior and exterior work in progress	Started: 03/12/19
		Completed:
Paving and Walks	Concrete paving and walks continue in progress	Started: 08/14/19
		Completed:
Final Grading/ Stabilize Site	Landscaping in progress	Started: 11/20/19
		Completed:
Other		Started:

### Site-specific BMPs

• The corrective actions initiated and date completed are in the Corrective Action Log.

	List of BMPs Installed	BMP Installed?	BMP Maintenance Required?	Notes
1	Silt Fence	Yes	Yes	See the corrective action log
2	Concrete Washout	No	Yes	Install a concrete washout
3	Portable Toilet	Yes	No	
4	Roll off	Yes	No	
5	Stabilized Construction Entrance	Yes	Yes	See the corrective action log
6				
7				
8				
9				
10				

1	Are the BMPs shown on	Yes	
	the map?		
2	Were there changes to	No	
	the SWPPP?		
3	Has the SWPPP been	No	
	updated?		
4	Were the changes to the		
	SWPPP implemented		
	within 7 days?		

	New BMPs needed	Notes
1		
2		
3		
4		
5		

### **Overall Site Issues**

 $\label{list of corrective actions will be supplied with this inspection.}$ 

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	Yes	No	
2	Are natural resource areas (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?	Yes	No	
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	No	Yes	Silt fence is not perfoming. It is damaged in areas and has debris and sediment built up beyond the recocomended height.
4	Are discharge points and receiving waters free of any sediment deposits?	Yes	No	
5	Are storm drain inlets properly protected?			No inlets
6	Is the construction exit preventing sediment from being tracked into the street?	Yes	Yes	See the corrective action log
7	Is trash/litter from work areas collected and placed in dumpsters?	Yes	No	
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	No	Yes	See the corrective action log Use linings for concrete washouts.

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	No	No	N/A
10	Are materials that are potential storm water contaminants stored inside or under cover?	Yes	No	
11	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	No	No	N/A
12	Has the Site map been updated to reflect current conditions?	Yes	No	The Inspectors map has been updated.
13	Is the NOI posted	Yes	No	NOI Posting Location: at the Southwest corner of the site. Facing to McMahon Blvd.
14	Were previous corrections made within 7 days of last inspection or before the next storm event?	No	Yes	See the corrective action log
15	(Other)			

Wa	lk through the facility and	look for signs of	pollution including paint, solvents, chemicals, solid waste, oil, and fuel.
1	Are there any signs of	No	
	hazardous materials		
	being exposed to storm		
	water runoff?		
2	Have there been any	No	
	reportable quantities		
	releases of hazardous		
	materials?		

#### **CERTIFICATION STATEMENT**

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name: Castandra Durkin	Title: CPESC, CESSWI
Signature:	<b>Date:</b> 12/04/19
•	
SWPPP Management Signature:	Date:
SWFFF Management Signature:	Date:

Project: McMahon Carwash

# **Corrective Action Log**

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
1	Post the NOI	02/14/19		02/25/19
2	Post a rain gauge	02/14/19		
3	Ensure there is a spill kit	02/14/19		
4	Install a rock pad entrance to minimize the trackout of sediment onto the streets.	02/14/19		03/12/19
5	Provide SWPPP book on site	02/14/19		02/25/19
6	The silt fence at the SE corner of the site needs to be reinstalled. It is laying on the ground where it should be installed.	02/25/19		03/26/19
7	Need to make sure the silt fence around the site is toed in (bottom of fence is buried 6")	2\2519		07/16/19
8	Need to read one training session per month from tab 7 and sign it and date it.	2/25/19		
9	Reinstall 5 panels of the security fence on the west side have fallen by strong winds.	03/12/19		03/26/19
10	Around the concrete batch plant the concrete powder needs to be removed from the ground and disposed of.	03/26/19		04/10/19
11	No new issues at the time of this inspection	04/10/19		04/10/19
12	Re install approx. 50' of silt fence at the west side of the site behind the batch plant.	05/07/19		07/16/19
13	No new issues at the time of this inspection. Address previous issues	05/21/19		05/21/19
14	Reatach the silt fence to the chain link fence where needed on the North side of the site	06/04/19		07/16/19
15	The trash bin needs to be emptied	06/04/19		07/02/19
16	Replace the concrete washout. Washout pits must have a liner. 07/16/19 It has been cleaned.	06/04/19		07/16/19
17	No new issues at the time of this inspection. Address previous issues	06/18/19		06/18/19
18	No new issues at the time of this inspection. Address previous issues	07/02/19		07/02/19
19	Repair and reinstall the silt fence along the site perimeter. 10/23/19 Part of the silt fence has been removed to pour concrete and landscaping activities.	07/16/19		10/23/19
20	Re-locate the rock pad entrance. It is not being used and they are jumping on one side of the curb.	07/31/19		

Ver. 070813

Date: 12/04/2019

Project: MaMa

## **McMahon Carwash**

# **Corrective Action Log**

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
21	Remove the blow away trash at the East side of the site . (Stucco guys trash )	07/31/19		08/14/19
22	No new issues at the time of this inspection. Address previous issues	08/14/19		08/14/19
23	The trash bin needs to be emptied	08/28/19		09/11/19
24	No new issues at the time of this inspection. Address previous issues	09/11/19		09/11/19
25	Cleanup the concrete washed out at the East side of the site	09/25/19		
26	Remove the blow away trash around the building.	09/25/19		11/07/19
27	No new issues at the time of this inspection. Address previous issues	10/09/19		10/09/19
28	No new issues at the time of this inspection. Address previous issues	10/23/19		10/23/19
29	No new issues at the time of this inspection. Address previous issues	11/07/19		11/07/19
30	No new issues at the time of this inspection.	11/20/19		11/20/19
31	Repair Silt Fence at perimeter of site	12/04/2019		

SWPPP Management Signature: Date:

Ver. 070813