

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.			Project Name:		Unser/McMahonLots1 & 3-7			
NPDES Id. No.	NMR1004PN LC		Location:	10745 Unser Blvd		Unser Blvd		
9/1	9/2024	Owner			Contractor			
Operator		Holly Partners LLC.						
Contact name & title		Yogesh Patel						
e-mail		yogi1020@gmail.com						
Contact Phone #		275-8223						
COA Inspector		Chancellor English			Start/End Time:	: 12:30pm		
Construction Phase: Activity on some lots, stockpiles								
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up								
Weath	er at time of i	nspection?	Clea	r	Temper	ature: ~	90	
Estimated date of last storm 0.25" or greater 8/31/2024								
Item								
Number	Deficiency/ Corrective Action							
1	Stabilization - The stockpiles have not been stabilized in violation of CGP Part 2.2.14. Required							
-	mitigation: Initiate the installation of stabilization measures immediately in areas of exposed soil							
	where construction activities have permanently ceased or will be temporarily inactive for 14 or more							
	calendar days and complete the installation of stabilization measures as soon as practicable, but r						le, but no	
	later than seven calendar days after stabilization has been initiated per CGP Part 2.2.14							
2								
3								
4								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	yes	Latest rep	oort Date:	9/10/20	024	
					!			

Notes: Lots 2, 3, 8, and 9 have been transferred to new owners. Tierra West prepared the SWPPP and Inspection Plus has been doing inspections. Yogesh Patel has signed a blank Delegation of Authority. The EPA does not allow Delegation of Authority to a third party. Inspections Plus plans to have the site stabilized by the end of the month.

> City of Albuquerque Stormwater Inspector Signature and date: Contact information: Chancellor English 505-924-3325 <u>cenglish@cabq.com</u> Chance

Chancellor English