

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	A11E017	_Omni Pr	Project Name: Omni L		Jniversal Trust Lots 8 & 9 Unser/McMahon		
NPDES Id. No.	NMR10	NMR1005E9 Location:			5762 McMahon Blvd NW		
3/13/2023		Owner			Contractor		
Operator		Omni Universal Trust			Caldon Seeding & reclamation		
Contact name & title		Michael G Rosenberg trustee			Len Horan		
e-mail		mgr@lobo.net			lenhoran@rocketmail.com		
Contact Phone #		970-259-7501			505-699-5913		
COA Inspector		Doug Hughes			Start/End Tim		
Construction Phase:		Lots 8 & 9 Graded with subc					
	nspection:	Regular	Storm Event	Post Storm	Event >0.25"		
Weather at time of i					Temperature: ~ 50		
Estimated date of last storm 0.25" or greater 12/4/2022						12/4/2022	
Item	Deficiency/ Corrective Action						
Number	Denciency/ conective Action						
1	Permit coverage wasn't posted. You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to the construction site. The notice must be located so it is visible from the public road that is nearest to the active part of the construction site, and it must use a font large enough to be readily viewed from a public right-of- way per CGP 1.5 SWPPP wasn't available on site at time of inspection, so it couldn't be checked to see if it is up-to-date						
2	Provide a scanned copy of the up-to-date SWPPP with all reports to the Storm Water Quality Section at 600 2nd St NW suite 400 - Jhughes@cabq.gov - Per CGP 4.8.2						
3	Stabilization was missing - You must continue permit coverage, self-inspections, SWPPP and BMP maintenance until the City determines that the Final Stabilization Criteria CGP2.2.14.c has been satisfied. Then you must remove the BMPs and send documentation of the Final Stabilization to the EPA with a Notice of Termination (NOT) per CGP 8.2 to end your coverage under the CGP. This step is independent of the Work Order. Please copy me with the documentation and the EPA's acceptance of the NOT at that time. In the meantime seed and Hydromulch are required per CGP 2.2.14.						
4	BMPs missing - Silt fence is full of sediment or has fallen down in most places along the north side. It is missing on the other three sides. Silt fence is required around the perimiter until the final stabilization criterisa is satisfied. There is sediment next to the curb on the east and west sides of the site. Sediment must be removed from the adjacent streets and sidewalk.						
2.1	Discharge off site?	(Y/N)	Yes				
4	Self Inspect	tion Reports	n/a	Latest re	port Date:		
·			., -				

 Notes:

 ESC Plan and NOI approved on 3/3/23. After the inspection I called Mr Rosenberg and asked about the sign and silt fence and he said he would call Len and get Caldon to take care of the violations later today. He also said he would get the City fee paid.

 City of Albuquerque Stormwater Inspector Signature and date:
 3/14/2023

 Contact information:
 Doug Hughes (505) 924-3420

jhughes@cabq.gov

James D. Hughes