

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	File No. A11E017C				Tidal Wave Care Wash			
NPDES Id. No.	NPDES Id. No.		Location:			10601 Unser Blvd		
3/13/2023		Owner			Contractor			
Operator		TWAS Properties LLC						
Contact name & title		CO Joshua Skarsgard						
e-mail		Josh@retailsouthwest.com						
Contact Phone #		262-2323						
COA Inspector		Doug Hughes			Start/End Time: 9AM			
Construction Phase:		Building on lot 4 & both new and old disturbance on other lots Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow U						
Type of Inspection:		Regular	Storm Event				Follow Up	
	er at time of i					50		
Estimated	ated date of last storm 0.25" or greater							
Item	Deficiency/ Corrective Action							
Number			Deficient	y/ correctiv	Action			
1	The new prion	erty owners NC)I and ESC Plan h	aven't been s	submited to t	he City for approva	al as required	
_	The new prioperty owners NOI and ESC Plan haven't been submitted to the City for approval as required by the EPA's CGP part 1.4.3. Table 1 "New Operator of a permitted site" and the City Ordinance.							
	by the Li A 3 C	Or part 1.4.5. 1	able 1 New Ope	rator or a pe	illitted site	and the city ordin	arice.	
2	Permit coverage wasn't posted. You must post a sign or other notice of your permit coverage at a safe,							
	publicly accessible location in close proximity to the construction site. The notice must be							
	visible from the public road that is nearest to the active part of the construction site, and it must						must use a	
	font large eno	ugh to be readi	ly viewed from a	public right-o	of- way per C	GP 1.5		
3	3 SWPPP wasn't available on site at time of inspection, so it couldn't be checked to see if it is up-to-date. Provide a scanned copy of the up-to-date SWPPP with all reports to the Storm Water Quality Section at						up-to-date	
							ty Section at	
	600 2nd St NW suite 400 - Jhughes@cabq.gov - Per CGP 4.8.2							
4						ections, SWPPP and	d BMP	
	4 Stabilization was missing - You must continue permit coverage, self-inspections, maintenance until the City determines that the Final Stabilization Criteria CGP2.							
		•						
	satisfied. Then you must remove the BMPs and send documentation of the Final Stabilization to the EPA with a Notice of Termination (NOT) per CGP 8.2 to end your coverage under the CGP. This step is independent of the Work Order. Please copy me with the documentation and the EPA's acceptance of							
							-	
							ceptance of	
	the NOT at tha	at time. In the m	neantime seed ar	nd Hydromulo	ch are require	ed per CGP 2.2.14.		
5	BMPs missing - Silt fence is full of sediment on the east side. It is missing on the west side. Silt fence is required around the perimiter until the final stabilization criterisa is satisfied.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	n/a	Latest rep	oort Date:	_		

Notes:	
Josh Skars	guard said yesterday that Jason Skarsguard in working with Inspections plus and TWAS, he said
he wasn't	sure what is causing the delay.

City of Albuquerque Stormwater Inspector Signature and date: 3/14/23

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

James D. Hughes