



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

| ESC File No.                                  | A12E008B2  | Project Name:  | Golf Course Rd and Westside Blvd |               |           |
|---|--|--|----------------------------------|---------------|-----------|
| NPDES Id. No.                                 | NMR100611  | Location:  | 10850 Golf Course Rd NW          |               |           |
| 3/3/2025                                      | Owner  | Contractor   |                                  |               |           |
| Operator                                      | Dennis & George LLC  | Desert Fox paving  |                                  |               |           |
| Contact name & title                          | Dennis Carpenter   | Francisco H  |                                  |               |           |
| e-mail  | <a href="mailto:denniscarpenter1@aol.com">denniscarpenter1@aol.com</a>   | <a href="mailto:FranciscoH@yahoo.com">FranciscoH@yahoo.com</a> |                                  |               |           |
| Contact Phone #                               | 505-269-1812   | 505-553-0207   |                                  |               |           |
| COA Inspector                                 | Chancellor English   | Start/End Time:  | 1pm                              |               |           |
| Construction Phase:                           | Paving complete  |  |                                  |               |           |
| Type of Inspection:                           | Regular  | Storm Event  | Post Storm Event >0.25"          | 311/Complaint | Follow Up |
| Weather at time of inspection?                | Windy  |  | Temperature: ~                   | 55            |           |
| Estimated date of last storm 0.25" or greater |  |  | 11/7/2024                        |               |           |
| Item Number                                   | Deficiency/ Corrective Action  |  |                                  |               |           |
| 1   | A portable toilet was found on its side in violation of CGP Part 2.3.3.f. Required mitigation: For sanitary waste, position portable toilets so they are secure and will not be tipped or knocked over and are located away from receiving waters, storm drain inlets, and constructed or natural site drainage features per CGP Part 2.3.3.f. |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
|   |  |  |                                  |               |           |
| 2.1   | Discharge off site? (Y/N)  | no   |                                  |               |           |
| 4   | Self Inspection Reports  | Yes  | Latest report Date:              | 9/4/2024      |           |

|   |  |
|---|--|
| Notes:                                      |  |
| SWPPP is in 5 gallon bucket at posting sign |  |
|   |  |
|   |  |
|   |  |
|   |  |

City of Albuquerque Stormwater Inspector Signature and date: 3/5/2025

Contact information: Chancellor English (505) 924-3325

[cenglish@cabq.gov](mailto:cenglish@cabq.gov)

*Chancellor English*