

## City of Albuquerque Stormwater Construction Site Inspection Report

General information							
Project Nai	me:	Paradise Vi	ew				
Location:		Paradise & Jerusalem					
Site Contact Name &		Various		ESC File No.	B10E001		
Agency		NPDES Id. No			various		
Inspection Date:		06/03/19		.030/1045hrs			
	water Inspecto		Timothy E. Sims				
Construction Phase:		STABILIZED					
Type of Inspection: x		Regular	Storm Event	Post Storm I	Event >0.25"	311/Complain	t Follow Up
Weath	er at time of i	nspection?	Cle	ear	Tempe	rature: ~	76*
Estimated	date of last s	torm 0.25" or greater 5/11/201					}
Item	Deficiency/ Corrective Action						
Number							
	CTADILIZED						
	STABILIZED						
2.1	Discharge off site?	(Y/N)	No	l at at at	ant Detail		
4	Self Inspect	ion Report	.S	Latest rep	oort Date:		
Notes:							

 $\hbox{City of Albuquerque Stormwater Inspector Signature and date:} \\$ 

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

06/03/19\_\_\_\_