



Submission of this Notice of Termination constitutes notice that the operator identified in Section III of this form is no longer authorized discharge pursuant to the NPDES Construction General Permit (CGP) from the site identified in Section IV of this form. All necessary information must be included on this form. Refer to the instructions at the end of this form.

Permit Information

NPDES ID: NMR1004B6

Reason for Termination: You have completed construction activities at your site, and you have met all other requirements in Part 8.2.1.

Use the space below to attach either ground or aerial photographs that show your site's compliance with the Part 2.2.14 stabilization requirements.

Name	Uploaded Date	Size
TimePhoto_20230731_135200 (1).jpg (attachment/1718008)	08/10/2023	1.05 MB
TimePhoto_20230731_135157.jpg (attachment/1718006)	08/10/2023	1.09 MB
TimePhoto_20230731_135157_5453.jpg (attachment/1718007)	08/10/2023	1.09 MB
TimePhoto_20230731_135136.jpg (attachment/1718005)	08/10/2023	1.84 MB
TimePhoto_20230731_135100.jpg (attachment/1718004)	08/10/2023	1.52 MB
TimePhoto_20230731_135054.jpg (attachment/1718003)	08/10/2023	1.26 MB
TimePhoto_20230731_135050.jpg (attachment/1718002)	08/10/2023	1.42 MB
TimePhoto_20230731_135048.jpg (attachment/1718001)	08/10/2023	1.71 MB
TimePhoto_20230731_135041.jpg (attachment/1718000)	08/10/2023	1.36 MB
TimePhoto_20230731_134354.jpg (attachment/1717999)	08/10/2023	1.50 MB
TimePhoto_20230731_134346.jpg (attachment/1717998)	08/10/2023	1.67 MB
TimePhoto_20230731_134344.jpg (attachment/1717997)	08/10/2023	1.72 MB
TimePhoto_20230731_134342.jpg (attachment/1717996)	08/10/2023	1.57 MB

Please include the date each photograph was taken, and a brief description of the area of the site captured by the photograph (e.g., photo shows application of seed and erosion control mats to remaining exposed surfaces on the northeast corner of site).

The photographs were taken on 7/31/2023 and show the lots pending sale have been stabilized with soil tackifier and seed. The project area is in a semi - arid environment and subject to the final stabilization exception for vegetative stabilization. The seed is protected by wood cellulose hydromulch.

Operator Information

Operator Name: Diamond Tail Realty, LLCAddress Line 1: 20 Fall Pippin LaneAddress Line 2: Suite 203City: AshevilleZIP/Postal Code: 28803State: NCCounty or Similar Division: BuncombePhone: 505-850-2427

Ext.:

Email: rgrowney@growney-inc.com

Operator Point of Contact

First Name Middle Initial Last Name: Ryan Growney

Project/Site Information

Project/Site Name: Ventana Square Paving & Utility Improvements

Project/Site Address

Address Line 1: Universe Blvd. & Paseo del Norte

Address Line 2:

City: Albuquerque

ZIP/Postal Code: 87114

State: NM

County or Similar Division: Bernalillo

Certification Information



I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. Signing an electronic document on behalf of another person is subject to criminal, civil, administrative, or other lawful action.

Certified By: Thomas R. Growney

Certifier Title: Principal

Certifier Email: rgrowney@growney-inc.com

Certified On: 08/10/2023 3:00 PM ET