

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	B11E0	10A	OA Project Name:		Viva Paradise Town Homes			
NPDES Id. No. NMR10		02ZX Location:		5512 Buglo Ave. NW				
		Owner			Contractor			
Operator		Buglo Properties, LLC.						
Contact name & title		John Lowe						
e-mail		jlowe14@comcast.net						
Contact Ph		505-688-6834						
COA Inspector		Thomas Evans			Start/End Time: 1:15 PM/1:30 PM			
	ction Phase:				onstruction			
	nspection:	Regular	Storm Event			311/Complaint	Follow Up	
	er at time of i				Temperature: ~ 83			
Estimated date of last storm 0.25" or greater 5/3/2021								
Item	Deficiency/ Corrective Action							
Number								
1	No posting of permit coverage. Post signage of NOI in a location most visible to the public.							
2	Washout on the ground. Direct wash water from concrete, paint, and stucco into a leak-proof container per CGP 2.3.4. Removed and dispose of hardened washout with other waste per CGP 2.3.2							
3	Holes in silt fence, silt fence down, and section of silt fence not installed. Install and repair silt fences to prevent sediment from entering the street.							
4	Sediment accumulated along silt fence that is greater than half the height of the fence. Remove accumulated sediment from the silt fence.							
5	Self-inspection reports not received. Send self-inspection report upon request. Reports should be kept on site in the SWPPP.							
6	Sediment in the street. Sweep and remove sediment from the street daily.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Reports	Requested	Latest re	port Date:	None on	file	
Notes: Areas of the site appear to not be stabilized.								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans 06/11/2021