

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. B11E		Project Name:		Apartments on Buglo			
NPDES Id. No. NMR10		003YA Location:		5530 Buglo Ave. NW			
	4/2021	Owner			Contractor		
Operator		Sharif Rabadi Trustee of Star Trust					
Contact name & title		Sharit Rabadi			Mohamad Tahat		
e-mail		startrustofnm@yahoo.com			mntahat10@g	mail.com	
Contact Phone #		505-440-6443					
COA Inspector		Doug Hughes			Start/End Time: 10:00 AM-10:20 AM		
Construction Phase: Type of Inspection:					ary stabilization		
			Storm Event			311/Complaint	Follow Up
	<u>er at time of i</u>		clea	r	Tempera	ture: ~	40
Estimated	date of last s	torm 0.25" o	r greater		10/1/2021		
Item	Deficiency/ Corrective Action						
Number			Dencienc	Ly/ Correctiv	VE ACTION		
1	None observe	 d.					
_							
2	The SWPPP was not available onsite and its location was not posted other than the phone number of the						
	operator. Provide the latest self-inspection report.						
3							
3							
4							
4							
5							
			_				
			1	1			
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	tion Reports	requested	Latest re	port Date:	6/11/2	021
Notes: NOI is posted. Site inactive, SWPPP not available onsite.							
The sediment in the residents yards along Saragossa was removed.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: James Hughes (505 924-3420)

jhughes@cabq.gov