



INSPECTION REPORT

GENERAL INFORMATION

DATE OF INSPECTION: 8/4/2020

COMPANY NAME: Gamma Development, LLC

PROJECT NAME: Ascension Subdivision

LOCATION: 8820 Horizon Blvd., Albuquerque, New Mexico, 87113

TRACKING NO: NMR1002JR

COMPLIANCE EVALUATION: Satisfactory

TYPE OF INSPECTION: 14Day

START TIME: 11:36 AM

END TIME: 11:53 AM

INSPECTOR'S NAME: Ray Welton

INSPECTOR'S TITLE: NPDES Inspector

INSPECTOR'S QUALIFICATIONS: StormwaterONE

INSPECTOR'S CONTACT: 505-400-7500

PHASE OF CONSTRUCTION: ☐ Clear and Grub ☒ Excavation ☒ Building (vertical)
☐ Rough Grading ☒ Infrastructure ☐ Final Grading
☐ Final Stabilization

WEATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

WEATHER AT TIME OF THIS INSPECTION: Clear

TEMPERATURE: 88

HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

ARE ANY DISCHARGES OCCURRING NOW? ☐ Yes ☒ No

ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT? ☐ Yes ☒ No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	PHOTO
1	NPDES Permit Notification	None	None	Gondola Way/Horizon Blvd. Entrance	1	EA	Yes
2	Silt Fence	None	None	East Perimeter	100	LF	Yes
3	Inlet Protection	None	None	Onsite	1	EA	Yes
4	Concrete Washout	None	None	Onsite	1	EA	Yes
5	Construction Entrance	None	None	Entrance	1	EA	Yes

GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location
2	Are steep slope areas not actively being worked properly stabilized?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Silt Fence and curb stabilized and protected areas.
3	Are disturbed areas not actively being worked properly stabilized?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Silt Fence and curb stabilized and protected areas.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Silt Fence and curb stabilized and protected areas.
5	Are discharge points and receiving waters free of any sediment deposits?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Washout facilities (concrete) available, clearly marked and maintained
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
10	Are offsite flows entering the construction site?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	No offsite flows entering the construction site
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	No evidence that pollutants are leaving the site
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
13	Are non-stormwater discharges properly controlled?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Project being operated in compliance with the SWPPP and with permit conditions at this time
15	Are changes to the SWPPP necessary at this time?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	No changes to the SWPPP necessary at this time
16	Are dust control measures being properly implemented?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Water truck onsite to ensure dust control measures are being properly implemented
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Book not viewed onsite

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:

Ray Welton

DATE:

August 05, 2020

SIGNATURE AND AFFILIATION:



CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:

,

DATE:

SIGNATURE: