



INSPECTION REPORT

GENERAL INFORMATION

DATE OF INSPECTION: 3/16/2021

COMPANY NAME: Gamma Development, LLC

PROJECT NAME: Ascension Subdivision

LOCATION: 8820 Horizon Blvd., Albuquerque, New Mexico, 87113

TRACKING NO: NMR1002JR

COMPLIANCE EVALUATION: Satisfactory

TYPE OF INSPECTION: 14Day

START TIME: 12:25 PM

END TIME: 12:34 PM

INSPECTOR'S NAME: Ray Welton

INSPECTOR'S TITLE: NPDES Inspector

INSPECTOR'S QUALIFICATIONS: StormwaterONE

INSPECTOR'S CONTACT: 505-400-7500

PHASE OF CONSTRUCTION: ☐ Clear and Grub ☒ Excavation ☐ Building (vertical)
☐ Rough Grading ☒ Infrastructure ☐ Final Grading
☒ Final Stabilization

WEATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

WEATHER AT TIME OF THIS INSPECTION: Clear

TEMPERATURE: 59

HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

ARE ANY DISCHARGES OCCURRING NOW? ☐ Yes ☒ No

ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT? ☐ Yes ☒ No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	PHOTO
1	NPDES Permit Notification	None	None	Gondola Way/Horizon Blvd. Entrance	1	EA	Yes
2	Silt Fence	None	None	Mid Slte	50	LF	Yes
3	Inlet Protection	None	None	Dawn Patrol Trail NE	2	EA	Yes
4	Inlet Protection	None	None	Gondola Way/Horizon Blvd. Entrance	1	EA	Yes
5	Stockpiles or Spoil Piles	None	None	Entrance	1	EA	Yes

GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location.
2	Are steep slope areas not actively being worked properly stabilized?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	Curb, block wall, inlet protection and silt fence stabilized and protected perimeter.
3	Are disturbed areas not actively being worked properly stabilized?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	Curb, block wall, inlet protection and silt fence stabilized and protected perimeter.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	Curb, block wall, inlet protection and silt fence stabilized and protected perimeter.
5	Are discharge points and receiving waters free of any sediment deposits?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	☐ Yes ☐ No ☒ N/A	☐ Yes ☒ No	Washout not viewed onsite.
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
9	Are materials that are potential stormwater contaminants stored inside or in containers?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
10	Are offsite flows entering the construction site?	☐ Yes ☒ No ☐ N/A	☐ Yes ☒ No	No offsite flows entering the construction site.
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	☐ Yes ☒ No ☐ N/A	☐ Yes ☒ No	No evidence that pollutants are leaving the site.
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
13	Are non-stormwater discharges properly controlled?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	Project being operated in compliance with the SWPPP and with permit conditions at this time.
15	Are changes to the SWPPP necessary at this time?	☐ Yes ☒ No ☐ N/A	☐ Yes ☒ No	No changes to the SWPPP necessary at this time.
16	Are dust control measures being properly implemented?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	Book not viewed onsite.

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:

Ray Welton

DATE:

March 17, 2021

SIGNATURE AND AFFILIATION:



CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:

,

DATE:

SIGNATURE: