



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Estates @ Glendale				
Location:	8800 Glendale				
Site Contact Name & Agency	Randy Scmile - Ashton's Homes	ESC File No.	B19E027		
	cschmileco@yahoo.com	NPDES Id. No.	NMR100AX		
Inspection Date:	02/27/20	Start/End Time:	0945/0955hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	home construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	35
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 10/31/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 02/27/20