**City of Albuquerque Stormwater Construction Site Inspection Report**

## General Information

| | | | |
|---|---|---|---|
| Project Name: | Estates @ Glendale | | |
| Location: | 8800 Glendale | | |
| Site Contact Name & Agency | Randy Scmile - Ashton's Homes | ESC File No. | B19E027 |
| | cschmileco@yahoo.com | NPDES Id. No. | NMR100AX |
| Inspection Date: | 05/12/20 | Start/End Time: | 1140/1150hrs |
| CoA Stormwater Inspector: | Timothy E. Sims | | |
| Construction Phase: | STABILIZED | | |

| Type of Inspection: | X | Regular | | Storm Event | | Post Storm Event >0.25" | | 311/Complaint | | Follow Up |
|---|---|---|---|---|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| Weather at time of inspection? | Clear | Temperature: ~ | 72* |
| Estimated date of last storm 0.25" or greater | | 4/13/2020 | |

| Item Number | Deficiency/ Corrective Action | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| 2.1 | Discharge off site? (Y/N) | No | | |
| 4 | Self Inspection Reports | | Latest report Date: | |

STABILIZED

| | |
|---|---|
| Notes: | |
| | |
| | |
| | |
| | |
| | |

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2020.05.14 07:34:47 -06'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 05/12/20