



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Estates @ Glendale		
Location:	8800 Glendale		
Site Contact Name & Agency	Randy Scmile - Ashton's Homes	ESC File No.	B19E027
		NPDES Id. No.	NMR100AX
Inspection Date:	05/31/19	Start/End Time:	0900/0930hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:			
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input checked="" type="checkbox"/> 311/Complaint <input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	63*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	no issues noted.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 5/24/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 05/31/19