



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Estates @ Glendale				
Location:	8800 Glendale				
Site Contact Name & Agency	Randy Scmile - Ashton's Homes	ESC File No.	B19E027		
		NPDES Id. No.	NMR100AX		
Inspection Date:	07/11/19	Start/End Time:	0930/1000hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	home construction				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	79*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action			
	no issues noted.			
	****Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	5/24/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/11/19