

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Desert Ridge Pointe					
Location:		Wyoming & Glendale					
Site Contact Name & Agency		Jon McGill- Scott Patrick ESC File No. B19E028					
		jmcgill@scot	tpatrickhomes.com	NPDES Id. No.		NMR10024N	
Inspection Date:		08/28/19	Start/End Time: 09	000/0915hrs			
CoA Stormwater Inspector: Timothy E. Sims							
	ction Phase:			Home co	nstruction		
Type of Ir	spection: x	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
Weath	er at time of i	nspection?	Clea	ar	Tempe	rature: ~	73*
Estimated	mated date of last storm 0.25" or greater 7/7/2019						
Item							
Number	Deficiency/ Corrective Action						
Number							
	no issues noted						
	***Please provide latest SWPPP self-inspection report						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	ion Poporte		Latest ren	ort Date:	7/8/20	10
4	Sell ilispect	ion Reports	requesteu	Latest Tep	ort Date.	7/8/20	19
Nicho							
Notes:							
				<u> </u>			

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$ 

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

08/28/19\_\_\_\_