

City of Albuquerque Stormwater Construction Site Inspection Report

	General Information				
Project Name & Location	DESERT RIDGE POINTE Northeast Corner of Wyoming Blvd and Glendale Ave Albuquerque, NM 87122				
Site Contact Name & Agency	Jon McGill, General Manager ABQ Development LLC & Scott Patrick Homes (505) 828-9900 jmcgill@scottpatrickhomes.com				
Date of Inspection	5/13/19	Start/End 10:00 AM			
Inspector Name	Jon McGill, General Manager				
Describe Present Phase of Construction	Subdivision development work complete				
Type of Inspection:					
☐ Regular ☐ During stor	m event Post-storm event (> 0.25 inch)	311 / Complaint Response			
	Weather Information				
Weather at time of this inspecti		Temperature: ~60F° Windy			
Has there been a storm event si Amount: $\Box < \frac{1}{4}$ " $\Box = \frac{1}{4}$ " to $\frac{3}{4}$ "	nce the last inspection? Let \square So				
	Erosion & Sediment Control Inspec	ction			
Entrance / Track-Out	Private Streets are Paved; No Issues				
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	Swales are installed at the front of each 1st flush ponds are installed at the back				
Erosion Controls Housekeeping/Pollutant Contro	Retaining walls have been installed wh				
Debris/Pollutants/Sediment in M Notes	MS4 None				
Is site being maintained in compliance	e with the Drainage Ordinance ?MYcs □No				

	Control of the Contro		Maintenance	a l
	BMP / Activity	Implemented?	Required?	Corrective Action Needed and Notes
1	Are all slopes and disturbed areas not actively being worked, properly stabilized?	v∕Yes □No	□Yes WNo	
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	□Yes □No	□Yes □No	Not Applicable at this site
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	Iv∕Yes ∃No	UYes 12Mo	
4	Are discharge points and receiving waters free of any sediment deposits?	ØYes □No	□Yes 环o	
5	Are storm drain inlets properly protected?	⊠Yes □No	□Yes ⊠No	
0	Is the construction exit preventing sediment from being tracked off-site, to the street?	√Yes □No	□Yes ŒNo	
7	Is trash/litter from work areas collected and placed in covered dumpsters?	ű∕Yes □No	□Yes MNo	
3	Are washout facilities (e.g., paint, stucco, conc.) available, clearly marked, and maintained?	¥Yes □No	□Yes □No	
)	Are vehicle & equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No	No longer applicable at this site (not needed for homebuilding operations)
0	Are materials that are potential stormwater contaminants stored inside or under cover?	v∕Yes □No	□Yes WNo	
1	Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled?	√Yes ⊔No	□Yes ≝No	
2	Is site being maintained in compliance with Const. Gen. Permit?	ĽYes □No	□Yes MNo	
			Non-	Compliance
	ibe any incidents of non- one	-compliance not o	documented ab	ove:
1 1	One			
'RI	NT (Name and Title): J	fon McGill, Gen	eral Manager	
	// /_	CHINA	7	Date: 5-13-19