

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. B20E					8400 & 8420 Glendale Ave NE		
NPDES Id. No.			cation:			Glendale Ave NE	
	9/2020	Property Owne			Contractor		
Operator		Las Ventanas NM, Inc					
Contact name & title		Scott Ashcraft					
e-mail		tscott@lasventanasnm.com					
Contact Phone #		505-362-6824			•		
COA Inspector		Doug Hughes			Start/End Time:	8:30-9:30am	
Construction Phase:		Earthwork					
Type of In	spection:	Regular   Storm Event   Post Storm Event >0.25"   311/Complaint   Follow Up					
Weather at time of inspection? Clear Temperature: ~ 69							
Estimated date of last storm 0.25" or greater							
Item Number	Deficiency/ Corrective Action						
	TI						
1	These two lots have been graded and about 3700 cy fill has been stockpiled. This requires an Approved Grading and Drainage Plan and a Grading permit from Hydrology.						
2	The disturbed area is more than 1 acre so NPDES permit coverage is required and both the NOI are the ESC Plan must be approved by the City. BMPs are required.						
3	Fill has been placed in the floodplain without a Floodplain Development Permit and must be						
	removed and the disturbed area stabelized immediately.						
	Items 1, 2, & 3 have not changed since the precvious inspection o9/24/20 and remained unchanged						
	still on 10/13/20.						
2.1	Discharge off site?	(Y/N)	Yes				
4		ion Reports	103	Latest rer	ort Date:	n/a	
4	Sell Hispect	lon Reports		Latest Tep	ort bate.	Π/ α	
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov