

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	B20E067 Project Name:				8500 Glendale			
NPDES Id. No.	Location:			8500 Glendale				
	5/2020	Property Owne	er		Contractor			
Operator		John Jones			Mark Homes			
Contact name & title		John Jones rtmf91@gmail.com						
e-mail Contact Phone #		505-480-4537						
					Start/End Times 0 0.20am			
COA Inspector		Doug Hughes			Start/End Time: 9 - 9:30am			
Construction Phase:					ertical			
Type of Inspection:			Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weather at time of inspection? Clear Temperature: ~ 76								
Estimated date of last storm 0.25" or greater								
Item	Deficional/Corrective Action							
Number	Deficiency/ Corrective Action							
	Required NPDES permit coverage is missing							
1								
2	BMPs missing							
3	Loose soil in f	loodplain need:	s removed or co	mpacted				
4	Selfinspection reports required							
·	i interpretation of the control of t							
2.1	Discharge off site?	(Y/N)	yes					
4	Self Inspect	tion Reports		Latest rep	oort Date:	n/a		
				•	•			
Notes:								
-								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

9/29/20

James D. Hughes