

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	B20E06/ Project Name			8500 Glendale				
NPDES Id. No.		Location:			8500 Glendale			
	5/2020	Property Own	ner		Contractor			
Operator		John Jones			Mark Homes			
Contact name & title e-mail		John Jones						
Contact Phone #		rtmf91@gmail.com 505-480-4537						
					Start/Ford Times			
COA Inspector		Doug Hughes			Start/End Time:			
Construction Phase:		_	T T		rtical	T	1	
Type of Inspection:		Regular	Storm Event			311/Complaint	Follow Up	
Weather at time of inspection? Clear Temperature: ~ 76								
Estimated date of last storm 0.25" or greater								
Item	Deficiency/Corrective Action							
Number	Deficiency/ Corrective Action							
	Required NPDES permit coverage is missing							
1								
2	BMPs missing							
3	Loose soil in f	loodplain nee	ds removed or c	ompacted				
4	Selfinspection reports required							
-	•							
2.1	Discharge off site?	(Y/N)	yes					
4	Self Inspect	tion Reports		Latest rep	oort Date:	n/a		
Notes:								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov