

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	B20E067	Project Name:	8500 Glendale		
NPDES Id. No.		Location:	8500 Glendale		
10/10/2020	Property Owner		Contractor		
Operator	John Jones		Mark Homes		
Contact name & title	John Jones				
e-mail	rtmf91@gmail.com				
Contact Phone #	505-480-4537				
COA Inspector	Doug Hughes		Start/End Time:	8 - 9am	
Construction Phase:	Vertical				
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	Clear		Temperature: ~	76	
Estimated date of last storm 0.25" or greater					
Item Number	Deficiency/ Corrective Action				
1	Required NPDES permit coverage is missing				
2	BMPs missing				
3	Selfinspection reports required				
4					
2.1	Discharge off site? (Y/N)	No			
4	Self Inspection Reports		Latest report Date:	n/a	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Doug Hughes (505) 924-3420
jhughes@cabq.gov